

SERVICE INFORMATION

NO. SI D4-149

NO. SI 40NG-009

NOTE: SI's are used only:
1) To distribute information from DAI to our customers.
2) To distribute applicable information/documents from our suppliers to our customers with additional information.
Typically there is no revision service for SI's. Each new information or change of that will be sent along with a new SI.

I. TECHNICAL DETAILS

1.1 Airplanes affected:

All DA 40 D and DA 40 NG airplanes equipped with GARMIN G1000 System

1.2 Subject:

GARMIN Service Advisory No. 1129 Revision A
ATA-Code: 34-00

1.3 Reason:

GARMIN has become aware of a condition that may cause momentary interruption of GRS 77 AHRS and/or GDC 74A Air Data operation. For each installed component, there is a limited possibility for a one to two-second interruption to occur once every 90 operating hours.

1.4 Information:

For detailed technical information refer to GARMIN Service Advisory No. 1129 Revision A which is applicable without any further additions or restrictions.

II. OTHERS

GARMIN Service Advisory No. 1129 Revision A is attached to this Service Information.

In case of doubt contact Diamond Aircraft Industries GmbH.



SERVICE ADVISORY

NO.: 1129 Revision A

TO: Owners/Operators of G1000, G1000H, G950, G900X, G500, G500H, G600, Cirrus Perspective™, and Embraer Prodigy® integrated flight deck systems

DATE: May 19, 2011

SUBJECT: Momentary loss of GRS 77/77H and GDC 74A/74B/74H functions

AFFECTED PRODUCTS

All GRS 77/77H Attitude Heading and Reference System (AHRS) and/or GDC 74A/74B/74H Air Data Computer units as installed with Garmin Integrated Flight Decks (G1000, G1000H, G950, G900X, G500, G500H, G600, Cirrus Perspective™, and Embraer Prodigy®) with the following software versions are affected:

GRS 77 (fixed wing)	3.01 or earlier
GRS 77H (rotary wing)	3.51 or earlier
GDC 74A/74B/74H	3.07 or earlier

This condition has existed in these products since they were initially fielded in 2004.

DESCRIPTION

Garmin has become aware of a condition that may cause momentary interruption of GRS 77/77H AHRS and/or GDC 74A/74B/74H Air Data operation. For each installed component, there is a limited possibility for a one to two-second interruption to occur once every 90 operating hours.

Depending on the installation and/or system configuration, the momentary interruption of these systems may: (a) result in the display of a red 'X' for up to two seconds in the affected data field(s) on the PFD; and/or (b) result in an annunciated disengagement or reversionary mode-change of the autopilot. Affected primary data fields include: Attitude, Heading, Slip/Skid, Airspeed, Altitude, and Vertical speed. This issue will not affect attitude and air data information at the same time.

The attitude and heading red 'X' may persist for up to 45 seconds to accommodate a reset of the GRS 77/77H AHRS.

PILOT ACTION

Refer to the applicable flight manual or flight manual supplement for information regarding immediate actions in the event of any system failure.

RESOLUTION

This issue will be corrected in a future system software release.

© Copyright 2011
Garmin Ltd. or its subsidiaries
All Rights Reserved

Perspective™ is a trademark of Cirrus Design Corporation. Prodigy™ is a trademark of Embraer S.A. Except as expressly provided herein, no part of this document may be reproduced, copied, transmitted, disseminated, downloaded or stored in any storage medium, for any purpose without the express prior written consent of Garmin. Garmin hereby grants permission to download a single copy of this document and of any revision to this document onto a hard drive or other electronic storage medium to be viewed and to print one copy of this document or of any revision hereto, provided that such electronic or printed copy of this document or revision must contain the complete text of this copyright notice and provided further that any unauthorized commercial distribution of this document or any revision hereto is strictly prohibited.