

DAI MSB 40-074 DAI MSB D4-094 DAI MSB F4-028 Page 1 of 3 10-May-2013

MANDATORY SERVICE BULLETIN MSB 40-074 MSB D4-094 MSB F4-028

I TECHNICAL DETAILS

I.1 Category

Mandatory.

I.2 Airplanes affected

Type: DA 40, DA 40 D, DA 40 F

Serial numbers: 40.006 through 40.009

40.011 through 40.1071 40.1073 through 40.1077

D4.001 through D4.382

40.DS001 through 40.DS030 40.FC001 through 40.FC029

NOTE Airplanes converted to DA 40 NG via OSB D4-080 are not affected.

I.3 Date of effectivity

10-May-2013

I.4 <u>Time of Compliance</u>

Within the next 2000 hrs since new or since the last Major Structural Inspection from the date of effectivity, but not later than 31-Dec-2022.

I.5 Subject

Reinforcement of aft main spar.

ATA-Code: 57-00

I.6 Reason

By further testing and investigation it was discovered that the fatigue strength of the aft main spar in the cabin area does not ensure unlimited lifetime. This Service Bulletin prescribes the reinforcement of the aft main spar to correct this condition. As an additional benefit the reinforcement is the basis for the Major Structural Inspection interval increase to 6000 hrs since new and every 4000 hrs thereafter.

I.7 Concurrent Documents

None.



DAI MSB 40-074 DAI MSB D4-094 DAI MSB F4-028 Page 2 of 3 10-May-2013

I.8 Approval

The technical information or instructions contained in this document relate to the Design Change Advisories No. MÄM 40-398 and MÄM 40-475, which have been approved under the authority of EASA Design Organization Approval ref. EASA.21J.052.

The technical content of this document has been approved under the authority of DOA ref. EASA.21J.052.

I.9 Accomplishments / Instructions

Comply with WI-MSB 40-074 / WI-MSB D4-094 / WI-MSB F4-028, latest effective issue.

I.10 Mass (Weight) and CG

Not affected.

II PLANNING INFORMATION

II.1 Material and Availability

See WI-MSB 40-074 / WI-MSB D4-094 / WI-MSB F4-028, latest effective issue.

Materials including drawings are available from Diamond Aircraft Industries.

II.2 Special Tools

None.

II.3 <u>Labour Effort</u>

Approx. 4 hours.

II.4 Credit

None.

II.5 Reference Documents

DA 40 Series Airplane Maintenance Manual, Doc. No. 6.02.01, latest effective issue.

III <u>REMARKS</u>

- 1. All work must be done by a certified aircraft service station or a certified aircraft maintenance mechanic.
- 2. All work, in particular that which is not especially described in this Service Bulletin, must be done in accordance with the referenced Maintenance Manual.
- 3. Completion of all work must be recorded in the log book.
- In case of doubt contact Diamond Aircraft Industries GmbH.



DAI MSB 40-074 DAI MSB D4-094 DAI MSB F4-028 Page 3 of 3 10-May-2013

EXECUTION REPORT TO SERVICE BULLETIN MSB 40-074 MSB D4-094 MSB F4-028

| AIRPLANE DATA | | | |
|--------------------------------|----------|-----------------------|---|
| Airplane Serial Number | | | - |
| Airplane Registration | | | _ |
| Airplane Operator | | | _ |
| Hours of operation of airplane | | | _ |
| No. of landings | | | - |
| Hours of operation-engine | | | - |
| Typical operation of airplane | private, | club, training, other | |
| | | | |
| | | | |
| | | | |
| | | | |
| Date, Name, Sign | | | |

Please fax the completed form to Fax No. +43-2622-26700-1369 or e-mail to airworthiness@diamond-air.at



WI-MSB 40-074 WI-MSB D4-094 WI-MSB F4-028 Revision 0 Page 1 of 3 10-May-2013

WORK INSTRUCTION
WI-MSB 40-074
WI-MSB D4-094
WI-MSB F4-028

I GENERAL INFORMATION

I.1 Subject

Reinforcement of aft main spar.

I.2 Reference Documents

DA 40 Series Airplane Maintenance Manual, Doc. No. 6.02.01, latest effective issue.

I.3 Remarks

- a) All work must be done by a certified aircraft service station or a certified aircraft maintenance mechanic.
- b) All work, in particular if not described in this work instruction, must be done in accordance with the referenced maintenance manual.
- c) For conversion factors between SI units and US/Imperial units refer to AMM Chapter 02.
- d) In case of doubt, contact Diamond Aircraft Industries GmbH.

II DRAWINGS, SPECIAL TOOLS & MATERIALS

II.1 **Drawings**

D41-5313-03-00_2 Page 3.

II.2 Special Tools

None.



WI-MSB 40-074 WI-MSB D4-094 WI-MSB F4-028 Revision 0 Page 2 of 3 10-May-2013

II.3 Material

| Quantity | Part Number | Description |
|----------|-------------|----------------------------------|
| 2 m | KDU 1034 | SGL UD Carbon Fiber Tape |
| a/r | LR 285 | EPIKOTE™ Resin MGS® LR285 |
| a/r | LH 286 | EPIKURE™ Curing Agent MGS® LH286 |

Material including drawing is available from Diamond Aircraft Industries.

III INSTRUCTIONS

| 1 | Remove rear seat bench i.a.w. AMM Section 25-10. |
|---|---|
| 2 | Remove carpets in rear floor panel. |
| 3 | Prepare bonding area i.a.w. AMM Section 51-20. |
| | CAUTION Do not damage the laminate. |
| 4 | Prepare LH and RH reinforcement patch i.a.w. drawing D41-5313-03-00_2: Place impregnated reinforcement patches (items 101 to 104) on a PE or PP carrier foil. |
| 5 | Put LH and RH reinforcement patch in place on aft main spar i.a.w. drawing D41-5313-03-00_2. |




16

Diamond Aircraft Industries GmbH N. A. Otto-Straße 5 A-2700 Wiener Neustadt Austria

WI-MSB 40-074 WI-MSB D4-094 WI-MSB F4-028 Revision 0 Page 3 of 3 10-May-2013

Where the reinforcement patches overlap parts other than the aft main spar, trim the reinforcement patch (max cut off 60 mm).



7 Cover the patches with peel ply. 8 Cure and post cure i.a.w. AMM Section 51-20. 9 Remove peel ply. 10 Install carpets in rear floor panel. 11 Install rear seat bench i.a.w. AMM Section 25-10. 12 Clean working areas, check for foreign objects. 13 Check all altered, replaced and repaired parts for improper function. 14 Test all systems in working area for function. 15 Record MÄM 40-398 as installed.

Make all necessary entries in the airplane logs.

