

# Diamond Aircraft Industries G.m.b.H. N.A. Otto-Straße 5 A-2700 Wiener Neustadt

DAI SI 40-020 DAI SI D4-029 Page 1 of 2 17-May-2005

# SERVICE INFORMATION NO. SI 40-020 SERVICE INFORMATION NO. SI D4-029

NOTE: SI's are used only:

- 1) To distribute information from DAI to our customers.
- 2) To distribute applicable information / documents from our suppliers to our customers with additional information.

Typically there is no revision service for Si's. Each new information or change of that will be send along with a new SI.

## I. TECHNICAL DETAILS

## 1.1 Airplanes affected:

DA 40 all airplanes equipped with Garmin 500 Series Units as listed in Garmin Software

Service Bulletin

DA 40 D all airplanes equipped with Garmin 500 Series Units as listed in Garmin Software

Service Bulletin

#### 1.2 Subject:

Software Upgrade for Garmin 500 Series Units

ATA-Code:

34-50

#### 1.3 Reason:

Garmin has issued the Mandatory Software Service Bulletin No. 0514 with the purpose of upgrading the 500 Series Unit Software to Version 5.04.

#### 1.4 Approval:

The technical information contained in this document has been approved under the authority of EASA Design Organization Approval No. EASA.21J.052.



# Diamond Aircraft Industries G.m.b.H. N.A. Otto-Straße 5 A-2700 Wiener Neustadt

DAI SI 40-020 DAI SI D4-029 Page 2 of 2 17-May-2005

# 1.5 Information:

For detailed information see attached Garmin Software Service Bulletin No. 0514.

This SSB is applicable with no restrictions beyond those stated in the Garmin Software Service Bulletin.

# II. OTHERS

none



# \*\* MANDATORY \*\* SOFTWARE SERVICE BULLETIN

NO.: 0514

TO:

All Garmin Aviation Service Centers

DATE:

15 March 2005

SUBJECT:

New Software Version 5.04 (Main) for 500 Series Units

#### **PURPOSE**

This Software Service Bulletin incorporates unit Main Software Version 5.04 for 500 Series units.

Main Software Version 5.04 includes the following:

- Corrects now rescinded/cancelled Main Software Version 5.03 to properly provide DME/ARC navigation procedures.
- 2. Corrects RAIM input for TAWS availability.
- 3. Provides GDL 69 Data Link interface.

The following models are affected:

GPS 500, Unit P/N 011-00562-00, 011-00562-10

GPS 500 w/TAWS, Unit P/N 011-00863-00, 011-00863-01, 011-00863-10,

011-00863-11

GNS 530, Unit P/N 011-00550-00, 011-00550-10, 011-00550-30

GNS 530 w/TAWS, Unit P/N 011-00940-00, 011-00940-01, 011-00940-10,

011-00940-11, 011-00940-31

GNS 530A, Unit P/N 011-00835-00, 011-00835-10

GNS 530A w/TAWS, Unit P/N 011-00864-00, 011-00864-01, 011-00864-10,

011-00864-11

#### **DESCRIPTION**

This modification consists of uploading 500 Series Main Software Version 5.04.

#### **APPROVAL**

TSO-C129a TSO-C37d, JTSO-2C37e TSO-C38d, JTSO-2C38e TSO-C40c, JTSO-2C40c TSO-C36e, JTSO-C36e TSO-C34e, JTSO-C34e TSO-C151b

The Engineering data contained in Main Software Version 5.04 of the GPS 500, GPS 500 w/TAWS, GNS 530/A, and GNS 530/A w/TAWS are FAA approved. This change is a minor software change.

#### **AFMS AND PILOT'S GUIDE CONSIDERATIONS**

There are no AFMS changes.

#### **PRODUCT AFFECTED**

All GPS 500, GPS 500 w/TAWS, GNS 530/A, and GNS 530/A w/TAWS units with main software version 5.03 or previous are affected. The unit's current software version for the Main Processor may be viewed on the Software Version Page under the AUX Menu.

#### **COMPLIANCE**

**MANDATORY** for TAWS units with Main Software Version 5.02 or 5.03 and non-TAWS units with Main Software Version 5.03 only.

NOTE: Units without Main Software Version 5.03 may be upgraded to enable GDL 69 interface as a non-reimbursable option.

#### REFERENCES

500 Series Installation Manual, P/N 190-00181-02, Rev. M or later

#### **MANPOWER**

One-hour (1.0) labor including testing

#### WARRANTY INFORMATION

This modification is warranty reimbursable for parts and labor for TAWS units with Main Software Version 5.02 or 5.03 and non-TAWS units with Main Software Version 5.03 only.

NOTE: Units without Main Software Version 5.03 may be upgraded to enable GDL 69 interface as a non-reimbursable option.

Software Service Bulletin 0514 March 15, 2005

#### MODIFICATION INSTRUCTIONS

The procedures described below are for the software field upgrade only.

- 1. Check the unit's current software version for the Main Processor. This information can be viewed on the Software Version Page under the AUX Menu.
- 2. Write down the display contrast level value on the Display Page, located on AUX page 4, before clearing the memory. This number will be required later in the process.
- 3. Apply power and turn the unit on. Allow the Self Test to complete and press the ENT key to acknowledge as required.
- 4. Insert the software upgrade data card into the left datacard slot on the front of the unit. (Note: It may take several seconds before recognizing the data card).
- 5. Confirm the software upload by pressing the <ENT> key on the User Card Upload Confirmation Window.
- 6. The software upload status is displayed during the upload (upload time is approximately 30 seconds).
- 7. When complete, the unit will reset and a color display test will appear.
- 8. Turn the unit off and wait for the unit to power off.
- 9. Remove the software upgrade data card and replace the Jeppesen datacard.
- 10. Turn the unit on and verify the new software version on the Startup / Self-Test Page or Software Version Page.
- 11. Turn the unit off and wait for the unit to power off.
- 12. Press and hold the <CLR> key down while turning the unit on. (This will clear all memory including waypoints, user setup and satellite almanac information.)
- 13. Turn the unit off.
- 14. Turn the unit on and enter the display contrast level value (written down in Step 2) on the Display Page located on AUX page 4.
- 15. Connect an outside antenna to the unit and allow it to collect almanac data. This process should take 15-20 minutes.

#### **TESTING PROCEDURE**

The unit's built-in Self-Test and successful completion of the Post Installation Check Out Procedure in the aircraft, as outlined in the unit's Installation Manual, is adequate to ensure proper functioning.

# **MATERIAL INFORMATION**

All parts required to modify one (1) GPS 500, GPS 500 w/TAWS, GNS 530/A, or GNS 530/A w/TAWS per this Service Bulletin:

QTY	Part Number	Description
1	010-00224-10	Software Upload Datacard, Main ver. 5.04
		*NOTE * This datacard carries a charge of \$50.00, which will be refunded upon return of the datacard to Garmin.

A connector kit is available to construct the test harness if required:

QTY	Part Number	Description
1	011-00351-04	Upload connector kit  Consists of:
		78 Pin connector and pins