

**Operation in Brazil** 

## SUPPLEMENT N023 TO THE AIRPLANE FLIGHT MANUAL DA 42 NG

## **OPERATION IN BRAZIL**

Doc. No.	: 7.01.15-E
Date of Issue of the Supplement	: 10-Mar-2010
Design Change Advisory	: NÄM 42-023

This Supplement is approved by EASA on behalf of ANAC.

Signature	:	Aller Age
Stamp	:	General Ko
Date of approval	:	2 3. MRZ, 2010

This airplane must be operated in compliance with the information and limitations contained herein.

Prior to operation the pilot must take notice of all information contained in this supplement to the Airplane Flight Manual.

DIAMOND AIRCRAFT INDUSTRIES GMBH N.A. OTTO-STR. 5 A-2700 WIENER NEUSTADT AUSTRIA



Intentionally left blank.

_				
•	Page 9-N023-2	28-May-2020	Rev. 1	Doc. # 7.01.15-E

Г



Operation in Brazil

)

## 0.1 RECORD OF REVISIONS

Rev. No.	Reason	Chap- ter	Page(s)	Date of Revision	Approval Note	Date of Approval	Date Inserted	Signature
1	NÄM 42- 023/a	all	all	28-May- 2020	This revision is approved by EASA on behalf of third of the second second the second s	topel 2020		

	Doc. # 7.01.15-E	Rev. 1	28-May-2020	Page 9-N023-3
S.				



## 0.2 LIST OF EFFECTIVE PAGES

	Chapter	Page	Date
	0	9-N023-1 9-N023-2 9-N023-3 9-N023-4 9-N023-5 9-N023-6	28-Mar-2020 28-Mar-2020 28-Mar-2020 28-Mar-2020 28-Mar-2020 28-May-2020
I	1	9-N023-7	28-May-2020
     	2	9-N023-8 9-N023-9 9-N023-10 9-N023-11 9-N023-12	28-May-2020 28-May-2020 28-May-2020 28-May-2020 28-May-2020
I	3	9-N023-13	28-May-2020
I	4A	9-N023-14	28-May-2020
I	4B	9-N023-15	28-May-2020
I	5	9-N023-16	28-May-2020
I	6	9-N023-17	28-May-2020
 	7	9-N023-18 9-N023-19	28-May-2020 28-May-2020
I	8	9-N023-20	28-May-2020

I	Page 9-N023-4	28-May-2020	Rev. 1	Doc. # 7.01.15-E
---	---------------	-------------	--------	------------------



## 0.3 TABLE OF CONTENTS

Page

	1. GENERAL
	2. OPERATING LIMITATIONS 9-N023-8
I	3. EMERGENCY PROCEDURES 9-N023-13
I	4A. NORMAL OPERATING PROCEDURES
I	4B. ABNORMAL OPERATING PROCEDURES
I	5. PERFORMANCE
I	6. MASS AND BALANCE
I	7. DESCRIPTION OF THE AIRPLANE AND ITS SYSTEMS 9-N023-18
I	8. AIRPLANE HANDLING, CARE AND MAINTENANCE

I	Doc. # 7.01.15-E	Rev. 1	28-May-2020	Page 9-N023-5
---	------------------	--------	-------------	---------------



Intentionally left blank.

I	Page 9-N023-6	28-May-2020	Rev. 1	Doc. # 7.01.15-E	



## 1. GENERAL

No change.

I	Doc. # 7.01.15-E	Rev. 1	28-May-2020	Page 9-N023-7
---	------------------	--------	-------------	---------------

T



#### 2. OPERATING LIMITATIONS

#### 2.15 LIMITATION PLACARDS

(a) Next to Each of the Two Fuel Filler Necks:




(b) In Addition Next to Each of the Two Auxiliary Fuel Filler Necks (If Installed):




I	Page 9-N023-8	28-May-2020	Rev. 1	Doc. # 7.01.15-E
---	---------------	-------------	--------	------------------



Next to the Baggage Compartment:



Extended Baggage Compartment (If Installed):




ı	Doc. # 7.01.15-E	Rev. 1	28-May-2020	Page 9-N023-9
---	------------------	--------	-------------	---------------

**Operation in Brazil** 



DA 42 NG AFM Supplement N023

#### Short Baggage Extension (if OÄM 42-207 is installed)



I	Page 9-N023-10	28-May-2020	Rev. 1	Doc. # 7.01.15-E
---	----------------	-------------	--------	------------------



In the Nose Baggage Compartment:

CAPACIDADE MÁXIMA DESTE COMPARTIMENTO (lado esquerdo mais lado direito): 30 kg VEJA O CAPÍTULO 6 DO MANUAL DE VÔO

Beside the Door Locking Device Installed in the Passenger's Door:

# SAÍDA DE EMERGÊNCIA A fechadura deve estar destrancada durante o vôo.



#### I 2.16 OTHER LIMITATIONS

#### I 2.16.11 G1000 GPS NAVIGATION SYSTEM LIMITATIONS

1	Note
I .	Currently, SBAS (Satellite-Based Augmentation System) is
I .	not available in Brazil. While SBAS is not functional,
I .	operations that require it, such as GNSS vertical navigation
I .	modes, are not available and should not be performed in
I	Brazilian airspace.

I Page 9-N023-12 28-May-2020 Rev. 1 Doc. # 7.01.15-E	I	Page 9-N023-12	28-May-2020	Rev. 1	Doc. # 7.01.15-E
--	---	----------------	-------------	--------	------------------



#### 3. EMERGENCY PROCEDURES

I Doc. # 7.01.15-E Rev. 1 28-May-2020 Page 9-N023-13
--



## 4A. NORMAL OPERATING PROCEDURES

	Page 9-N023-14	28-May-2020	Rev. 1	Doc. # 7.01.15-E
•	Fage 9-11023-14	28-101ay-2020	Rev. I	DUC. # 7.01.13-E



#### 4B. ABNORMAL OPERATING PROCEDURES

I Doc. # 7.01.15-E Rev. 1 28-May-2020 Page 9-N023-1	I	Doc. # 7.01.15-E	Rev. 1	28-May-2020	Page 9-N023-15
---	---	------------------	--------	-------------	----------------



#### 5. PERFORMANCE

I	Page 9-N023-16	28-May-2020	Rev. 1	Doc. # 7.01.15-E



#### 6. MASS AND BALANCE

I Doc. # 7.01.15-E Rev. 1 28-May-2020 Page 9-N023-1
---



#### 7. DESCRIPTION OF THE AIRPLANE AND ITS SYSTEMS

#### 7.8 CANOPY, REAR DOOR AND CABIN INTERIOR

#### Front canopy

The front canopy is closed by pulling down on the canopy frame, following which it is locked by means of a handle on the left hand side of the frame. On locking, steel bolts lock into mating holes in polyethylene blocks.

"Cooling Gap" position: A second setting allows the bolts to lock in, leaving a gap under the front canopy.


The canopy can be blocked by a locking device on the left side near the canopy opening lever by turning the key clockwise. The closed and blocked canopy can be opened from inside by pulling the lever inside the opening handle.

#### WARNING

The airplane may be operated with the front canopy in the "cooling gap" position on the ground only. Before take-off the front canopy must be completely closed and locked.

Do not block the canopy with the locking key before flight in order to assure emergency evacuation from outside.

A window on the left hand side of the canopy can be opened for additional ventilation or as an emergency window.



	Page 9-N023-18	28-May-2020 Rev	. 1 Doc. # 7.01.15-E
•	1 age 5 11020 10	20 May 2020 - 100	




#### Rear door

The rear door is closed in the same way, by pulling down on the frame and locking it with the handle. A gas pressure damper prevents the door from dropping; in strong winds the assembly must be securely held. The rear door is protected against unintentional opening by an additional lever.

The door can be blocked by a locking device on the left side near the door opening lever by turning the key clockwise. The closed and blocked door can be opened from inside by pulling the lever inside the opening handle.

#### WARNING

Do not block the door with the locking key before flight in order to assure emergency access from outside.



I	Doc. # 7.01.15-E	Rev. 1	28-May-2020	Page 9-N023-19
---	------------------	--------	-------------	----------------



#### 8. AIRPLANE HANDLING, CARE AND MAINTENANCE

ı	Page 9-N023-20	28-May-2020	Rev. 1	Doc. # 7.01.15-E
	-			