

Supplement O04 TO THE AIRPLANE FLIGHT MANUAL DA 42 NG

Operation without Unfeathering Accumulator

Doc. No.	: 7.01.15-E
Date of Issue	: 15-Nov-2012
Design Change Advisories	: OÄM 42-224

This Supplement to the Airplane Flight Manual has been approved by EASA with EASA Approval No. 10043478.

DIAMOND AIRCRAFT INDUSTRIES GMBH N.A. OTTO-STR. 5 A-2700 WIENER NEUSTADT AUSTRIA Operation without Unfeathering Accumulator



DA 42 NG AFM Supplement O04

Intentionally left blank.

Page 9-004-2	Rev. 0	15-Nov-2012	Doc. # 7.01.15-E



0.1 RECORD OF REVISIONS

Reason	Chap- ter	Page(s)	Date of Revision	Approval Note	Date of Approval	Date Inserted	Signature
	Reason	Onup			Reason Chap- ter Page(s) Date of Revision Approval Image: Approval of term Image: Approval of term Image: Approval of term Image: Approval of term Image: Approval of term Image: Approval of term Image: Approval of term Image: Approval of term Image: Approval of term Image: Approval of term Image: Approval of term Image: Approval of term Image: Approval of term Image: Approval of term Image: Approval of term Image: Approval of term Image: Approval of term Image: Approval of term Image: Approval of term Image: Approval of term Image: Approval of term Image: Approval of term Image: Approval of term Image: Approval of term Image: Approval of term Image: Approval of term Image: Approval of term Image: Approval of term Image: Approval of term Image: Approval of term Image: Approval of term Image: Approval of term Image: Approval of term Image: Approval of term Image: Approval of term Image: Approval of term Image: Approval of term Image: Approval of term Image: Approval of term Image: Approval of term Image: Approval of term Image: Approval of term Image: Approval of term Ima		

Doc. # 7.01.15-E	Rev. 0	15-Nov-2012	Page 9-004-3
------------------	--------	-------------	--------------



0.2 LIST OF EFFECTIVE PAGES

Chapter	Page	Date
0	9-004-1 9-004-2 9-004-3 9-004-4 9-004-5	15-Nov-2012 15-Nov-2012 15-Nov-2012 15-Nov-2012 15-Nov-2012
1	9-004-6	15-Nov-2012
2	EASA approved 9-004-7	15-Nov-2012
3	9-004-8	15-Nov-2012
4A	9-004-9	15-Nov-2012
4B, 5, 6	9-O04-10	15-Nov-2012
7	9-O04-11	15-Nov-2012
8	9-O04-12	15-Nov-2012

Page 9-004-4 Rev. 0 15	v-2012 Doc. # 7.01.15-E
------------------------	-------------------------



0.3 TABLE OF CONTENTS

Page

1.	GENERAL
2.	LIMITATIONS
3.	EMERGENCY PROCEDURES
4A.	NORMAL OPERATING PROCEDURES
4B.	ABNORMAL OPERATING PROCEDURES
5.	PERFORMANCE
6.	MASS AND BALANCE
7.	SYSTEM DESCRIPTION 9-004-11
8.	AIRPLANE HANDLING, CARE AND MAINTENANCE

Doc. # 7.01.15-E Rev. 0 15-Nov-2012 Page 9-004
--



1. GENERAL

This Supplement supplies the information necessary for operation of a DA 42 NG without propeller unfeathering accumulators.

The information contained in this Supplement is to be used in conjunction with the complete AFM. The limitations and information contained herein either supplement or, in the case of conflict, override those in the Airplane Flight Manual or its previous Temporary Revisions.

This Supplement is a permanent part of this AFM and must remain in this AFM at all times if OÄM 42-224 is implemented.

Page 9-004-6 Rev. 0 15-Nov-2012 Doc. #	7.01.15-E
--	-----------



2. LIMITATIONS

2.4 POWER-PLANT LIMITATIONS

Items x and y are amended to read:

- x) Restart airspeed (starter assisted) : max.100 KIAS or airspeed for a
 - stationary propeller, whichever is lower
- y) Intentional in-flight engine shutdown is prohibited.

2.15 LIMITATION PLACARDS

The following is added:

In the forward view of the pilot, if OÄM 42-224 is carried out:

INTENTIONAL IN-FLIGHT ENGINE SHUT-DOWN IS PROHIBITED

Doc. # 7.01.15-E	Rev. 0	15-Nov-2012	EASA approved	Page 9-004-7
------------------	--------	-------------	------------------	--------------



3. EMERGENCY PROCEDURES

The following headline is amended to read:

3.7.4 RESTARTING THE ENGINE IN FLIGHT

Restarting the Engine with the Starter

Items 5 and 6 of the checklist are amended to read:

- 5. ENGINE MASTER of affected engine ON
- 6. STARTER of affected engine engage, 5 seconds maximum

The NOTE is added and item 7 is amended to read:

NOTE

Unfeathering of the propeller is done in the restart sequence by building up system oil pressure when cranking the starter.

7. Circuit breakers check / reset if necessary.

The Paragraph is added:

If engine does not start: wait 30 seconds and proceed with item 6. If engine does not start after 3 attempts proceed according to AFM Section 3.7.6 - ENGINE FAILURES IN FLIGHT.

Restarting the Engine by Windmilling

The NOTE is added and replaces the content of the Paragraph: NOTE

A windmilling restart is not possible without the unfeathering accumulator (if OÄM 42-224 is carried out).

Page 9-004-8	Rev. 0	15-Nov-2012	Doc. # 7.01.15-E



4A. NORMAL OPERATING PROCEDURES

4A.6 CHECKLISTS FOR NORMAL OPERATING PROCEDURES

4A.6.21 DEMONSTRATION OF ENGINE SHUTDOWN/RESTART

The NOTE is added and replaces the content of the Section:

NOTE

If OÄM 42-224 is carried out, demonstration of an intentional engine shut-down in flight is prohibited.

Doc. # 7.01.15-E Rev. 0 15-Nov-2012 Page 9-O04-9
--



4B. ABNORMAL OPERATING PROCEDURES

No change.

5. PERFORMANCE

No change.

6. MASS AND BALANCE

No change.

Page 9-004-10	Rev. 0	15-Nov-2012	Doc. # 7.01.15-E



7. SYSTEM DESCRIPTION

7.9 POWER PLANT

7.9.2 PROPELLER

Propeller Control

Feathering:

The Paragraph is amended to read:

To feather the propeller the engine must be shut down with the appropriate ENGINE MASTER switch. This will open the electric governor valve. All oil will flow back from the propeller hub, allowing the blades to move into the feathered pitch position.

Feathering is only possible at propeller speeds above 1300 RPM.

CAUTION

If the engine is shut down below an RPM of 1300 the propeller pitch remains below the start lock position. In this case the speed must be increased to increase the propeller RPM.

Unfeathering:

The Paragraph is amended to read:

To unfeather the propeller, the associated ENGINE MASTER switch must be set to ON. The electric governor valve will be closed. Cranking the engine will build up pressure in the propeller hub moving the propeller blades towards a low pitch position.

Doc. # 7.01.15-E	Rev. 0	15-Nov-2012	Page 9-004-11
------------------	--------	-------------	---------------



8. AIRPLANE HANDLING, CARE AND MAINTENANCE

No change.

Г

Page 9-004-12	Rev. 0	15-Nov-2012	Doc. # 7.01.15-E
---------------	--------	-------------	------------------