

SERVICE INFORMATION No. SI 42NG-006

NOTE: SI's are used only:

- 1) To distribute information from DAI to our customers.
 - 2) To distribute applicable information/documents from our suppliers to our customers with additional information.
- Typically there is no revision service for SI's. Each new information or change of that will be sent along with a new SI.

I. TECHNICAL DETAILS

1.1 Airplanes affected:

All DA 42 NG and DA 42 M-NG

1.2 Subject:

GARMIN – Service Advisory No. 0929 Revision A
ATA-Code: 34-00

1.3 Reason:

GARMIN has identified that using the “Delete All” menu option to delete all flight plans or all user waypoints may cause Red-X failure indications to appear momentarily in any data field(s), including primary flight data fields, on the PFD/MFD. The auto pilot may disconnect during this condition.

1.4 Information:

For detailed technical information refer to the GARMIN Service Advisory No. 0929 Revision A, which is applicable without any further additions or restrictions.

II. OTHERS

The GARMIN Service Advisory No. 0929 Revision A is attached to this SI.

In case of doubt contact Diamond Aircraft Industries GmbH.



SERVICE ADVISORY

NO.: 0929 Revision A

TO: Owner/Operators of Garmin Integrated Flight Deck Systems

DATE: 02 July 2009

SUBJECT: Momentary failure indications (Red-X) can occur when deleting stored data

AFFECTED PRODUCTS

All Garmin G900X, G950, G1000, Cirrus Perspective®, and Embraer Prodigy™ systems with GDU Software version 9.14 and all prior versions, are affected.

DESCRIPTION

Using the 'Delete All' menu option to delete all flight plans or all user waypoints may cause Red-X failure indications (Figure 1) to appear momentarily in any data field(s), including primary flight data fields, on the PFD(s)/MFD. The auto pilot may disconnect during this condition.



Figure 1. Red-X example

PILOT ACTION

Do not use the 'Delete All' menu option to delete flight plans or user waypoints during flight. This issue does not occur when deleting individual flight plans or user waypoints.

RESOLUTION

Garmin plans to address this issue in a future software release.

© Copyright 2009
Garmin Ltd. or its subsidiaries
All Rights Reserved

Except as expressly provided herein, no part of this document may be reproduced, copied, transmitted, disseminated, downloaded or stored in any storage medium, for any purpose without the express prior written consent of Garmin. Garmin hereby grants permission to download a single copy of this document and of any revision to this document onto a hard drive or other electronic storage medium to be viewed and to print one copy of this document or of any revision hereto, provided that such electronic or printed copy of this document or revision must contain the complete text of this copyright notice and provided further that any unauthorized commercial distribution of this document or any revision hereto is strictly prohibited.