

## MANDATORY SERVICE BULLETIN NO. MSB-42-038/2 SUPERSEDES RSB-42-038 & MSB-42-038/1

## I TECHNICAL DETAILS

I.1 Category

Mandatory

## I.2 Airplanes affected

Type: DA 42

Serial Numbers: 42.004 up to and incl. 42.231, if TAE 125-01 Engine is installed and RSB-42-038 not carried out. 42.AC001 up to and incl. 42.AC059, if TAE 125-01 Engine is installed and RSB-42-038 not carried out.

## I.3 <u>Time of Compliance</u>

23-Mar-2008

## I.4 <u>Subject</u>

Installation of a modified water tube bracket.

ATA-Code: 76

## I.5 <u>Reason</u>

To improve the reliability of the water tube bracket, a redesigned bracket is available at Diamond Aircraft Ind. It is required to replace the bracket by the new design.

## I.6 <u>Concurrent Documents</u>

None



#### I.7 Approval

The technical information or instructions contained in this document relate to the Design Change Advisory No. MÄM 42-231, which has been approved under the authority of DOA No. EASA.21J.052.

The technical content of this document has been approved under the authority of DOA No. EASA.21J.052.

#### I.8 Accomplishment / Instructions

WI-MSB-42-038, latest effective issue must be complied with.

## I.9 Mass (Weight) and CG

Negligible

## II PLANNING INFORMATION

#### II.1 Material & Availability

The Work Instruction WI-MSB-42-038 and appropriate necessary materials are available through DAI.

#### II.2 Special Tools

None

#### II.3 Credit

2 hours + material as specified in II.1 Credit can only be granted on sending a warranty application incl. work report at latest until 14-Apr-2008

#### II.4 Labor effort:

Approx. 2 hours

#### II.5 <u>Reference Documents</u>

DA 42 Airplane Maintenance Manual Doc. No. 7.02.01, latest effective issue WI-MSB-42-038, latest effective issue.



## III <u>REMARKS</u>

- 1. All measures must be carried out by a certified aircraft station or a certified aircraft mechanic.
- 2. Accomplishment of the measures must be confirmed in the log book.
- 3. In case of any doubt, contact Diamond Aircraft Industries.



I

## EXECUTION REPORT for MSB 42-038/2

## AIRPLANE DATA

Airplane Serial Number:			
Airplane Registration:			
Airplane Operator:			
Hours of operation of airplane:			
No. of landings:			
Hours of operation-engine LH:			
RH:			
Typical operation of airplane: private, club, training, other			

Date, Name, Sign

Please fax the completed form to Fax No. \*\*43-2622-26700-369 or e-mail to airworthiness@diamond-air.at



Revision 1 Page 1 of 5 23-Mar-2007

# WORK INSTRUCTION WI-MSB-42-038/1 "REDESIGN WATER TUBE BRACKET "

## SUPERSEDES WI-RSB-42-038

## I GENERAL INFORMATION

## I.1 Subject:

Installation of a modified water tube bracket.

## I.2 <u>Reference Documents:</u>

Diamond Aircraft DA42 Airplane Maintenance Manual, Doc. No. 7.02.01, latest effective issue.

## I.3 <u>Remarks:</u>

- a) The work must be carried out by a certified aircraft service station or a certified aircraft maintenance mechanic. In case of doubt, contact Diamond Aircraft.
- b) All works, particularly those that are not especially described in this work instruction, have to be carried out in accordance with the referenced maintenance manual.

## II DRAWINGS, SPECIAL TOOLS & MATERIALS

## II.1 Drawings:

None

## II.2 Special Tools:

None



Revision 1 Page 2 of 5 23-Mar-2007

## II.3 Material


Qty	Description	Part Number
2	Mounting Plate Assembly	D60-7526-99-00
4	Screw M5x14	LN9037-05014
4	Washer	DIN125-A5.3-A2
4	Pipe Clamp	MS21919WDG19

## III INSTRUCTIONS

1	Remove upper cowling LH (refer to AMM Section 71-10).
---	---




Revision 1 Page 3 of 5 23-Mar-2007





WI-MSB-42-038/1

Revision 1 Page 4 of 5 23-Mar-2007





Revision 1 Page 5 of 5 23-Mar-2007

6	Install screw on engine block, torque screw with 14 Nm and secure screw with Loctite 262. Install oil line.
8	Clean working area and check for foreign objects.
9	Perform functional check of all systems in working area.
10	Install the engine cowlings (refer to AMM, Section 71-00)
11	Perform items 1 to 10 for RH side.
12	Perform engine ground test (refer to AMM, Chapter 05-20-00)
13	Make appropriate entries into aircraft log.