DAI OSB 42-135/1 DAI OSB 42NG-076/1 Page 1 of 4 18-Oct-2019

OPTIONAL SERVICE BULLETIN OSB 42-135/1 OSB 42NG-076/1

supersedes OSB 42-135 and OSB 42NG-076

I <u>TECHNICAL DETAILS</u>

I.1 Category

Optional.

I.2 Airplanes affected

Type: DA 42, DA 42 M, DA 42 NG, DA 42 M-NG

Serial numbers: 42.004 through 42.427

42.AC001 through 42.AC151 42.M001 through 42.M026 42.N001 through 42.N067 42.N100 through 42.N250 42.N300 through 42.N323 42.NC001 through 42.NC008

42.MN001 through 42.MN042 42.MN050 through 42.MN055 42.NW001 through 42.NW029

42.MNW001 through 42.MNW004

I.3 Date of effectivity

05-Jul-2018

I.4 <u>Time of Compliance</u>

At owner's discretion.

I.5 Subject

Installation of the New Map Lights and Map Light Sealing.

ATA-Code: 33-13

DAI OSB 42-135/1 DAI OSB 42NG-076/1 Page 2 of 4 18-Oct-2019

I.6 Reason

Diamond Aircraft has developed a redesigned Map Light with improved sealing. This Service Bulletin describes the retrofit installation on airplanes already in service.

I.7 Concurrent Documents

None.

I.8 Approval

The technical information or instructions contained in this document relate to the Design Change Advisories No. MÄM 42-1024/f and MÄM 42-1094/a, which have been approved under the authority of EASA Design Organization Approval ref. EASA.21J.052.

The technical content of this document has been approved under the authority of DOA ref. EASA.21J.052.

I.9 Accomplishments / Instructions

Comply with WI-OSB 42-135 / WI-OSB 42NG-076 latest effective issue.

I.10 Mass (Weight) and CG

Approximately 333 g weight increase.

II PLANNING INFORMATION

II.1 Material and Availability

See WI-OSB 42-135, WI-OSB 42NG-076 latest effective issue.

II.2 Special Tools

None.

II.3 <u>Labour Effort</u>

Approx. 1.5 hours.

II.4 Credit

None.

II.5 Reference Documents

DA 42 Series Airplane Maintenance Manual, Doc. No. 7.02.01, latest effective issue. DA 42 NG Airplane Maintenance Manual, Doc. No. 7.02.15, latest effective issue.

DAI OSB 42-135/1 DAI OSB 42NG-076/1 Page 3 of 4 18-Oct-2019

III REMARKS

- 1. All work must be done by a certified aircraft service station or a certified aircraft maintenance mechanic.
- 2. All work, particular that which is not especially described in this Service Bulletin, must be done in accordance with the referenced Maintenance Manual.
- 3. Completion of all work must be recorded in the log book.
- 4. In case of doubt contact Diamond Aircraft Industries GmbH.



DAI OSB 42-135/1 DAI OSB 42NG-076/1 Page 4 of 4 18-Oct-2019

EXECUTION REPORT TO SERVICE BULLETIN OSB 42-135/1 OSB 42NG-076/1

AIRPLANE INFORMATION		
Airplane Serial Number		-
Airplane Registration		-
Airplane Operator		-
Hours of operation of airplane		-
No. of landings		-
Hours of operation-engine	LH	
	RH	
Typical operation of airplane	private, club, training, other _	
Date, Name, Sign		
-ato, Harrio, Olgii		

Please e-mail the completed form $\underline{execution reports@diamondair craft.com}$

WI-OSB 42-135 WI-OSB 42NG-076 Revision 0 Page 1 of 7 16-Jul-2018

WORK INSTRUCTION WI-OSB 42-135 WI-OSB 42NG-076

I GENERAL INFORMATION

I.1 Subject

Installation of the new Map Light Assy or new Map Light Sealing.

I.2 Reference Documents

DA 42 Airplane Maintenance Manual, Doc. No. 7.02.01, latest effective issue DA 42 NG Airplane Maintenance Manual, Doc. No. 7.02.15, latest effective issue.

I.3 Remarks

- a) All work must be done by a certified aircraft service station or a certified aircraft maintenance mechanic.
- b) All work, in particular if not described in this work instruction, must be done in accordance with the referenced maintenance manual.
- c) For conversion factors between SI units and US/Imperial units refer to AMM Chapter 02.
- d) In case of doubt, contact Diamond Aircraft Industries GmbH.

II DRAWINGS, SPECIAL TOOLS & MATERIALS

II.1 Drawings

None.

II.2 Special Tools

None.

WI-OSB 42-135 WI-OSB 42NG-076 Revision 0 Page 2 of 7 16-Jul-2018

II.3 Material

Set 1 if MÄM 42-1024 is not installed without OÄM 42-193 Air conditioning System

Quantity	Part Number	Description	
3	D60-3313-11-00_01	Map Light Assy (MÄM 42-1024)	
3	D60-3313-10-02_01	Map Light Seal (MÄM 42-1094)	
1	D60-3313-10-01_01	Emergency Lever Seal (MÄM 42-1094)	
1	D60-5200-71-00	Emergency Exit-Lever	
1	1966-090	Lead Seal 8mm	
0,5m	390-555	Copper Wire	

Set 2 if MÄM 42-1024 is **not** installed with OÄM 42-193 Air conditioning System

Quantity	Part Number	Description	
1	D60-3313-11-00_01	Map Light Assy (MÄM 42-1024)	
1	D60-3313-10-02_01	Map Light Seal (MÄM 42-1094)	
1	D60-3313-10-01_01	Emergency Lever Seal (MÄM 42-1094)	
1	D60-5200-71-00X01	Emergency Exit-Lever(RACC)	
1	1966-090	Lead Seal 8mm	
0,5m	390-555	Copper Wire	

Set 3 if MÄM 42-1024 is installed with OÄM 42-193 Air conditioning System

Quantity	Part Number	Description	
1	D60-3313-10-02_01	Map Light Seal (MÄM 42-1094)	
1	D60-3313-10-01_01	Emergency Lever Seal (MÄM 42-1094)	
1	1966-090	Lead Seal 8mm	
0,5m	390-555	Copper Wire	

Set 4 if MÄM 42-1024 is installed without OÄM 42-193 Air conditioning System

Quantity	Part Number	Description
3	D60-3313-10-02_01	Map Light Seal (MÄM 42-1094)
1	D60-3313-10-01_01	Emergency Lever Seal (MÄM 42-1094)
1	1966-090	Lead Seal 8mm
0,5m	390-555	Copper Wire

Material is available from Diamond Aircraft Industries.

WI-OSB 42-135 WI-OSB 42NG-076 Revision 0 Page 3 of 7 16-Jul-2018

III INSTRUCTIONS



Remove the protective foil from the seal before installation on the new Map Light. Install the Map Light Seal on the Map Light.



If MÄM 42-1024 was not installed, replace the Emergency Exit Lever.
Hold the pax door in closed position but not locked. Remove the Emergency Exit Lever.
Note: It is possible that the pax door hinge has shims installed.



WI-OSB 42-135 WI-OSB 42NG-076 Revision 0 Page 5 of 7 16-Jul-2018

- 6 Install the emergency lever seal on the emergency lever.
 - Clean the emergency lever on sealing surface.
 - Make sure to get no grease or silicone on the bonding surfaces





WI-OSB 42-135 WI-OSB 42NG-076 Revision 0 Page 6 of 7 16-Jul-2018

Install the copper wire with lead seal on the emergency door lever.

Seal the wire holes in the fuselage from the inside with silicone or equivalent sealant.

Seal the cable grommet with silicone or equivalent sealant.



8 Position the mounting tabs inwards for installation.







WI-OSB 42-135 WI-OSB 42NG-076 Revision 0 Page 7 of 7 16-Jul-2018

- 9 Connect the electrical cables to the light assembly at the in-line connector.
- Position the Map light in to the fuselage and push up. Tighten the three bolts. Make sure not to lose any of the mounting tab in the fuselage frame.



- 11 Perform steps 2 to 4 and 8 to 10 for the other map lights if installed.
- 12 Reset the TAXI/MAP/ACL circuit breaker.
- 13 Clean working areas, check for foreign objects.
- 14 Check all altered, replaced, repaired parts for proper function.
- 15 Test all systems in working area for function.
- 16 Determine new empty weight and Center of Gravity.
- 17 Make all necessary entries in the airplane logs.