

SERVICE INFORMATION NO. SI-42-126

NOTE: SI's are used only:

- 1) To distribute information from DAI to our customers.
 - 2) To distribute applicable information/documents from our suppliers to our customers with additional information.
- Typically there is no revision service for SI's. Each new information or change of that will be sent along with a new SI.

I. TECHNICAL DETAILS

1.1 Airplanes affected:

All DA 42 aircraft equipped with Thielert TAE 125-01 engine.

1.2 Subject:

FAA Airworthiness Directive No. 2009-24-10
ATA-Code: 72-00

1.3 Reason:

In-flight engine shutdown incidents were reported on aircraft equipped with TAE 125-01 engines. This was found to be mainly the result of operation over a long time period with broken piston cooling nozzles which caused thermal overload of the piston. FAA issued the Airworthiness Directive No. 2009-24-10 to prevent engine in-flight shutdown, possibly resulting in reduced control of aircraft.

1.4 Information:

For detailed technical information refer to FAA AD No. 2009-24-10, which is applicable without any further additions or restrictions.

II. OTHERS

The FAA AD No. 2009-24-10 is attached to this SI.

In case of doubt contact Thielert Aircraft Engines GmbH.

Airworthiness Directive 2009-24-10 Summary

Subject:	To prevent engine in-flight shutdown		
Manufacturer:	Thielert Aircraft Engines GmbH	Category:	Engine
Effective Date:	01/04/2010	Recurring:	Yes
Supersedes:	N/A	Superseded By:	N/A

For complete information on this AD, please see:

[AD 2009-24-10 FAA Copy](#)

[AD 2009-24-10 Preamble](#)

[AD 2009-24-10 CFR Copy](#)

Model Applicability:

Thielert Aircraft Engines GmbH (TAE) model TAE 125-01 reciprocating engines

Applicable Manufacturers Service Information:

Thielert Service Bulletin No. TM TAE 125-0017, Revision 2, dated February 22, 2008

Summary:

We are adopting a new airworthiness directive (AD) for the products listed above. This AD results from mandatory continuing airworthiness information (MCAI) issued by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as: In-flight engine shutdown incidents were reported on aircraft equipped with TAE-125-01 engines. This was found to be mainly the result of operation over a long time period with broken piston cooling oil nozzles which caused thermal overload of the piston. We are issuing this AD to prevent engine in-flight shutdown, possibly resulting in reduced control of the aircraft.

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2009-0753; Directorate Identifier 2009-NE-31-AD; Amendment 39-16102; AD 2009-24-10]

RIN 2120-AA64

Airworthiness Directives; Thielert Aircraft Engines GmbH (TAE) Model TAE 125-01 Reciprocating Engines

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for the products listed above. This AD results from mandatory continuing airworthiness information (MCAI) issued by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as:

In-flight engine shutdown incidents were reported on aircraft equipped with TAE-125-01 engines. This was found to be mainly the result of operation over a long time period with broken piston cooling oil nozzles which caused thermal overload of the piston.

We are issuing this AD to prevent engine in-flight shutdown, possibly resulting in reduced control of the aircraft.

DATES: This AD becomes effective January 4, 2010. The Director of the Federal Register approved the incorporation by reference of certain publications listed in this AD as of January 4, 2010.

ADDRESSES: The Docket Operations office is located at Docket Management Facility, U.S. Department of Transportation, 1200 New Jersey Avenue, SE., West Building Ground Floor, Room W12-140, Washington, DC 20590-0001.

FOR FURTHER INFORMATION CONTACT: Jason Yang, Aerospace Engineer, Engine Certification Office, FAA, Engine and Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803; e-mail: jason.yang@faa.gov; telephone (781) 238-7747; fax (781) 238-7199.

SUPPLEMENTARY INFORMATION:

Discussion

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to include an AD that would apply to the specified products. That NPRM was published in the **Federal Register** on September 17, 2009 (74 FR 47760). That NPRM proposed to correct an unsafe condition for the specified products. The MCAI states that:

In-flight engine shutdown incidents were reported on aircraft equipped with TAE-125-01 engines. This was found to be mainly the result of operation over a long time period with broken piston cooling oil nozzles which caused thermal overload of the piston.

Comments

We gave the public the opportunity to participate in developing this AD. We considered the comments received.

Request for Changes to Paragraph (e)(4)

One commenter, Thielert Engine Owners Group, requests that we delete the requirement to remove the engine, and modify the proposed AD paragraph (e)(4) to state that if any evidence of a failed cooling nozzle is found, repair or replace the cooling nozzle before further flight.

We partially agree. We do not agree that a broken cooling nozzle is repairable. We agree that the engine does not need to be replaced, and that a broken cooling nozzle must be replaced before further flight. We changed paragraph (e)(4) in the AD from "If any evidence of a failed cooling nozzle is found, remove the engine from service before further flight" to "If any evidence of a failed cooling nozzle is found, replace the failed cooling nozzle before further flight."

Request for Reference to the Thielert Repair Manual

Two commenters, Thielert Engine Owners Group and Alpine Aviation, request that we modify proposed AD paragraph (e)(4) to state that if any evidence of a failed cooling nozzle is found, replace the cooling nozzle in accordance with Thielert Repair Manual, Document No. RM-02-01, latest revision.

We partially agree. We agree that failed cooling nozzles must be replaced. We do not agree that the Thielert Repair Manual must be referenced in the AD. Part 43 of the Federal Aviation Regulations (14 CFR part 43) already requires that corrective actions specified in ADs be performed using the appropriate manuals and or service bulletins that were previously FAA-approved. We changed the AD to require replacing failed cooling nozzles.

Request To Leave in the Ferry Flight Permit Option Paragraph

Alpine Aviation requests that we leave the "standard" paragraph in the AD regarding the option to ferry the aircraft to a location to where the AD can be accomplished.

We do not agree. In July 2002, we published a new Part 39 that contains a general authority regarding special flight permits and airworthiness directives; see Docket No. FAA-2004-8460, Amendment 39-9474 (69 FR 47998, July 22, 2002). Thus, when we now issue ADs, we will not include a specific paragraph on special flight permits unless we want to limit the use of that general authority granted in section 39.23. We did not change the AD.

Conclusion

We reviewed the available data, including the comments received, and determined that air safety and the public interest require adopting the AD with the changes described previously. We determined that these changes will not increase the economic burden on any operator or increase the scope of the AD.

Costs of Compliance

Based on the service information, we estimate that this AD will affect about 250 engines of U.S. registry. We also estimate that it will take about 2 work-hours per engine to comply with this AD. The average labor rate is \$80 per work-hour. Required parts will cost about \$30 per engine. Based on these figures, we estimate the cost of the AD on U.S. operators to be \$47,500.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this AD:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this AD and placed it in the AD docket.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Operations office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone (800) 647-5527) is provided in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

■ Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new AD:

2009–24–10 Thielert Aircraft Engines

GmbH: Amendment 39–16102. Docket No. FAA–2009–0753; Directorate Identifier 2009–NE–31–AD.

Effective Date

(a) This airworthiness directive (AD) becomes effective January 4, 2010.

Affected Airworthiness Directives (ADs)

(b) None.

Applicability

(c) This AD applies to Thielert Aircraft Engines GmbH (TAE) model TAE 125–01 reciprocating engines, excluding engines that have been modified to TAE Design Modification No. 2007–001. These engines are installed in, but not limited to, Diamond Aircraft Industries Model DA42, Piper PA–28–61 (Supplemental Type Certificate (STC) No. SA03303AT), Cessna 172F, 172G, 172H, 172I, 172K, 172L, 172M, 172N, 172P, 172R, 172S, F172F, F172G, F172H, F172K, F172L, F172M, F172N, and F172P (STC No. SA01303WI) airplanes.

Reason

(d) This AD results from mandatory continuing airworthiness information (MCAI) issued by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as:

In-flight engine shutdown incidents were reported on aircraft equipped with TAE–125–01 engines. This was found to be mainly the result of operation over a long time period with broken piston cooling oil nozzles which caused thermal overload of the piston.

We are issuing this AD to prevent engine in-flight shutdown, possibly resulting in reduced control of the aircraft.

Actions and Compliance

(e) Unless already done, do the following actions:

(1) Within the next 110 flight hours, or during the next scheduled maintenance, whichever occurs first after the effective date of this AD, inspect the engine and engine oil for any evidence or pieces of broken piston cooling nozzles.

(2) Use the inspection instructions in Thielert Service Bulletin No. TM TAE 125–0017, Revision 2, dated February 22, 2008, to perform the inspection.

(3) Thereafter, repetitively inspect the engine and engine oil for any evidence or pieces of broken piston cooling nozzles, within every additional 100 flight hours.

(4) If any evidence of a failed cooling nozzle is found, replace the failed cooling nozzle before further flight.

Alternative Methods of Compliance (AMOCs)

(f) The Manager, Engine Certification Office, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19.

Related Information

(g) Refer to European Aviation Safety Agency AD 2008–0016 R1, dated February 22, 2008, and Thielert Aircraft Engines GmbH, Platanenstrasse 14 D–09350, Lichtenstein, Germany, telephone: +49–37204–696–0; fax: +49–37204–696–55; e-mail: info@centurion-engines.com, for related information.

(h) Contact Jason Yang, Aerospace Engineer, Engine Certification Office, FAA, Engine and Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803; e-mail: jason.yang@faa.gov; telephone (781) 238–7747; fax (781) 238–7199, for more information about this AD.

Material Incorporated by Reference

(i) You must use Thielert Service Bulletin No. TM TAE 125–0017, Revision 2, dated February 22, 2008 to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact Thielert Aircraft Engines GmbH, Platanenstrasse 14 D–09350, Lichtenstein, Germany, telephone: +49–37204–696–0; fax: +49–37204–696–55; e-mail: info@centurion-engines.com.

(3) You may review copies at the FAA, New England Region, 12 New England Executive Park, Burlington, MA; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call (202) 741–6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Burlington, Massachusetts, on November 18, 2009.

Peter A. White,

Assistant Manager, Engine and Propeller Directorate, Aircraft Certification Service.

[FR Doc. E9–28166 Filed 11–25–09; 8:45 am]

BILLING CODE 4910–13–P