

SERVICE INFORMATION

NO. SI 42-223

NO. SI 42NG-089

NOTE: SI's are used only:
1) To distribute information from DAI to our customers.
2) To distribute applicable information/documents from our suppliers to our customers with additional information.
Typically there is no revision service for SI's. Each new information or change of that will be sent along with a new SI.

I. TECHNICAL DETAILS

1.1 Airplanes affected:

All DA 42 series airplanes equipped Avidyne TAS 600 (OÄM 42-094 installed)

1.2 Subject:

FAA Special Airworthiness Information Bulletin NE-17-26.
ATA-Code: 34-00

1.3 Reason:

FAA issued Special Airworthiness Information Bulletin NE-17-26 informing about an airworthiness concern regarding the display of intruder aircraft vertical trend indications.

1.4 Information:

For detailed technical information refer to FAA SAIB NE-17-26 which is applicable without any further additions or restrictions.

II. OTHERS

FAA Special Airworthiness Information Bulletin NE-17-26 is attached to this Service Information.

In case of doubt contact Avidyne Corporation.



SUBJ: NAVIGATION - Traffic Advisory System - Misleading Intruder
Aircraft Vertical Trend

SAIB: NE-17-26
Date: September 25, 2017

This is information only. Recommendations aren't mandatory.

Introduction

This Special Airworthiness Information Bulletin alerts you, owners and operators of aircraft equipped with an **Avidyne TAS600A, TAS600, and 9900BX Traffic Advisory System (TAS)** of an airworthiness concern regarding the display of intruder aircraft vertical trend indications. At this time, this airworthiness concern is not an unsafe condition that would warrant airworthiness directive (AD) action under Title 14 of the Code of Federal Aviation Regulations (14 CFR) part 39.

Background

Avidyne has identified a defect in TAS units that may prevent the TAS from updating intruder aircraft vertical trend when rapidly changing ownship altitude updates are received. This problem is particularly pronounced when the TAS receives ownship altitude updates from an ARINC-429 altitude source providing 1 ft. resolution. However, there is the potential that the problem may be observed regardless of the source of ownship altitude updates. This issue does not affect traffic alerting because aircraft vertical trend is not used in the alerting algorithm. This issue also does not affect intruder range, altitude, and bearing indications.

Avidyne has released Service Information Letter 606-00161-005, regarding this issue. Avidyne has also released Service Bulletin (SB) 601-00185-009, which updates the software in the TAS600A processor to provide a solution to this behavior. Avidyne does not plan to release a software update to address this issue in TAS600 or 9900BX TAS series systems.

Recommendations

- The FAA recommends that owners and operators of TAS600 or 9900BX series TASs remain aware that those TASs have a defect and that they cannot rely on the display of intruder aircraft vertical trend indications.
- The FAA recommends that owners and operators of TAS600A series TASs remain aware that those TASs have a defect and that they cannot rely on the intruder display of vertical trend indications until the TAS600A series TAS has complied with Avidyne SB 601-00185-009.

For Further Information Contact

Nick Rediess, Aerospace Engineer, FAA, Boston ACO Branch, 1200 District Avenue, Burlington, MA 01803; phone: 781-238-7159; email: nicholas.rediess@faa.gov.

For Related Service Information Contact

Avidyne Corporation, 710 North Drive, Melbourne, FL 32934; phone: 888-723-7592, (Toll Free US) or, 781-402-7592 (International Direct Dial); fax: 781-402-7599; Internet: <http://www.avidyne.com/support/index.asp>.