

# MANDATORY SERVICE BULLETIN

## MSB 50-012

### **I TECHNICAL DETAILS**

#### **I.1 Category**

Mandatory

#### **I.1 Airplanes affected**

Type: DA 50 C  
Serial numbers: 50.C.A.A.007 through 50.C.A.A.068  
50.C.A.A.070 through 50.C.A.A.073  
50.C.Q.A.001 through 50.C.Q.A.002

#### **I.2 Date of effectivity**

01-Jul-2025

#### **I.3 Time of Compliance**

Within 200 flight hours, but not later than 31-Jul-2026.

#### **I.4 Subject**

Replacement of the Main Landing Gear Retaining Rings.  
ATA-Code: 32-00

#### **I.5 Reason**

It was discovered that the main landing gear braces of some aircraft had retaining rings with insufficient level of corrosion resistance being installed. This may cause the retaining rings to corrode, sustain damage, or fail (crack). If not corrected, this may lead to failure of the landing gear. This Service Bulletin describes the replacement of those retaining rings.

#### **I.6 Concurrent Documents**

None.

### **I.7 Approval**

The technical information or instruction contained in this document relate to the Design Change Advisory No. MÄM 50-391/a, which has been approved under the authority of the DOA ref. EASA.21J.052.

The technical content of this document has been approved under the authority of the DOA ref. EASA.21J.052.

### **I.8 Accomplishments / Instructions**

See WI-MSB 50-012 latest effective issue.

## **II Mass (Weight) and CG**

Mass and Center of Gravity are not affected.

## **II PLANNING INFORMATION**

### **II.1 Material and Availability**

See WI-MSB 50-012, latest effective issue.

### **II.2 Special Tools**

None.

### **II.3 Labour Effort**

Approx. 0.5 hours.

### **II.4 Credit**

Material according to WI-MSB 50-012, latest effective issue.

### **II.5 Reference Documents**

DA 50 C Airplane Maintenance Manual, Doc. No. 9.02.01, latest effective issue.

### **III REMARKS**

1. All work must be done by a certified aircraft service station or a certified aircraft maintenance mechanic.
2. All work, particular that which is not especially described in this Service Bulletin, must be done in accordance with the referenced Maintenance Manual.
3. Completion of all work must be recorded in the log book.
4. If material is subject to be credited through Diamond Aircraft Industries, the Service Bulletin must be done by an authorized Diamond Service Center within the time of compliance and the Warranty Application incl. Work Report must be sent not later than 30 days after completion of work.
5. In case of doubt contact Diamond Aircraft Industries GmbH.

## EXECUTION REPORT TO SERVICE BULLETIN MSB 50-012

### AIRPLANE INFORMATION

Airplane Serial Number \_\_\_\_\_

Airplane Registration \_\_\_\_\_

Airplane Operator \_\_\_\_\_

Hours of operation of airplane \_\_\_\_\_

Number of landings \_\_\_\_\_

Hours of operation – engine \_\_\_\_\_

Typical operation of airplane private, club, training, other \_\_\_\_\_

\_\_\_\_\_  
Date, Name, SignPlease send the completed form to [executionreports@diamondaircraft.com](mailto:executionreports@diamondaircraft.com)

# WORK INSTRUCTION

## WI-MSB 50-012

### **I     GENERAL INFORMATION**

#### **I.1   Subject**

Replacement of the Main Landing Gear Retaining Rings.

#### **I.2   Reference Documents**

DA 50 C Airplane Maintenance Manual, Doc. No. 9.02.01, latest effective issue.

#### **I.3   Remarks**

- a) All work must be done by a certified aircraft service station or a certified aircraft maintenance mechanic.
- b) All work, in particular if not described in this work instruction, must be done in accordance with the referenced maintenance manual.
- c) For conversion factors between SI units and US/Imperial units refer to AMM, Chapter 02.
- d) In case of doubt, contact Diamond Aircraft Industries GmbH.

### **II    DRAWINGS, SPECIAL TOOLS & MATERIALS**

#### **II.1   Drawings**

None.

#### **II.2   Special Tools**


None.

### II.3 Material

Quantity	Part Number	Description
4	DIN471-10-MZP	Retaining Ring, Mechanical Zinc Plated, DIN471-10x1,0-MZP (MLG Brace Assy LH and RH)
6	DIN471-20-MZP	Retaining Ring, Mechanical Zinc Plated, DIN471-20x1,2-MZP (MLG Brace Assy LH and RH)
2	DIN472-30X1.2-MZP	Retaining Ring, Mechanical Zinc Plated (MLG Drag Brace Assy LH and RH)

Material is available from Diamond Aircraft Industries.


## III INSTRUCTIONS

1	Pull and tag the GEAR circuit breaker to prevent inadvertent landing gear operation.
2	<p>Locate the retaining rings on the backside of the MLG. See Detail Views A and B shown in below figure showing the LH MLG:</p>  <p style="text-align: center;">Figure 1: MLG Backside Retaining Rings</p>


3	<p>Replace the Retaining Rings in Detail View A with:</p> <ul style="list-style-type: none"><li>• DIN471-20-MZP</li><li>• DIN471-10-MZP</li></ul> <p>Replace the Retaining Ring in Detail View B with:</p> <ul style="list-style-type: none"><li>• DIN472-30X1.2-MZP</li></ul> <p>Replace only one Retaining Ring at a time!</p> <p style="text-align: center;"><b>CAUTION</b></p> <p style="text-align: center;">Do not remove or move shafts while replacing retaining rings</p> <p>Clean the grooves of the bearing shafts. Inspect the folding stay and bearing shafts for general condition before installing the new retaining rings.</p> <p style="text-align: center;"><b>NOTE</b></p> <p style="text-align: center;">Any repair / replacement / further inspection of the folding stay, and/or the bearing shaft needs, must be completed before you proceed with the next steps.</p> <p style="text-align: center;"><b>NOTE</b></p> <p style="text-align: center;">Do not overstretch the retaining rings during installation. Open the rings only enough to fit over the shaft when installing.</p> <p>Install the new retaining rings. Make sure the retaining rings properly engage into the grooves of the bearing shafts.</p>
---	--

4

Locate the retaining rings on the frontside of the MLG. See Detail Views C and D shown in below figure showing the LH MLG:



**DETAIL VIEW C**



**DETAIL VIEW D**




Figure 2: MLG Frontside Retaining Rings



5	<p>Replace the Retaining Ring in Detail View C with:</p> <ul style="list-style-type: none"> <li>• DIN471-20-MZP</li> </ul> <p>Replace the Retaining Rings in Detail View D with:</p> <ul style="list-style-type: none"> <li>• DIN471-20-MZP</li> <li>• DIN471-10-MZP</li> </ul> <p>Replace one Retaining Ring at a time!</p> <p style="text-align: center;"><b>CAUTION</b></p> <p style="text-align: center;">Do not remove or move shafts while replacing retaining rings.</p> <p>Clean the grooves of the bearing shafts. Inspect the folding stay and bearing shafts for general condition before installing the new retaining rings.</p> <p style="text-align: center;"><b>NOTE</b></p> <p style="text-align: center;">Any repair / replacement / further inspection of the folding stay, and/or the bearing shaft needs, must be completed before you proceed with the next steps.</p> <p style="text-align: center;"><b>NOTE</b></p> <p style="text-align: center;">Do not overstretch the retaining rings during installation. Open the rings only enough to fit over the shaft when installing.</p> <p>Install the new retaining rings. Make sure the retaining rings properly engage into the grooves of the bearing shafts.</p>
6	Repeat steps 2 through 5 on the RH MLG.
7	Clean working areas, check for foreign objects.
8	Check all altered, replaced, repaired parts for proper function.
9	Apply anti-corrosion coating. Refer to AMM Section 12-30-00.
10	Set the GEAR circuit breaker.
11	Test all systems in working area for function.
12	Do all necessary entries in the airplane logs.