

SERVICE INFORMATION

NO. SI 50-003

NOTE: SI's are used only:

1) To distribute information from DAI to our customers.

2) To distribute applicable information/documents from our suppliers to our customers with additional information.

Typically there is no revision service for SI's. Each new information or change of that will be sent along with a new SI.

I. TECHNICAL DETAILS

1.1 Airplanes affected:

All DA 50 C airplanes

1.2 Subject:

Continental Aerospace Technologies GmbH Service Bulletin No. SB CG 300-1001 P1

ATA-Code: 72-00

1.3 Reason:

Continental Aerospace Technologies GmbH has issued Priority 1 Safety Service Bulletin No. SB CG 300-1001 P1 mandating an oil analysis of Centurion 3.0 (CD-300) engines. The measures are limited to an engine serial numbers listed in the SB CG 300-1001 P1.

1.4 Information:

For detailed technical information refer to Continental Aerospace Technologies GmbH Service Bulletin No. SB CG 300-1001 P1 which is applicable without any further additions or restrictions.

II. OTHERS

Continental Aerospace Technologies GmbH Service Bulletin No. SB CG 300-1001 P1 is attached to this Service Information.

In case of doubt contact Continental Aerospace Technologies GmbH.

SERVICE BULLETIN

PRIORITY 1 – SAFETY

Service Bulletin No. / Date: SB CG 300-1001 P1, Initial Issue / September 29, 2023



Subject: Additional Engine Oil Analysis and Engine Oil Filter Shipment

Type affected: Centurion 3.0 (CD-300)

Models affected: The following engine S/N are affected:

06-01-00027	06-01-00043	06-01-00055	06-01-00069	06-01-00080	06-01-00096
06-01-00032	06-01-00044	06-01-00057	06-01-00070	06-01-00081	06-01-00097
06-01-00034	06-01-00045	06-01-00058	06-01-00071	06-01-00082	06-01-00098
06-01-00035	06-01-00046	06-01-00060	06-01-00072	06-01-00083	06-01-00099
06-01-00036	06-01-00047	06-01-00061	06-01-00073	06-01-00084	
06-01-00037	06-01-00048	06-01-00062	06-01-00074	06-01-00088	
06-01-00038	06-01-00049	06-01-00063	06-01-00075	06-01-00089	
06-01-00039	06-01-00050	06-01-00064	06-01-00076	06-01-00092	
06-01-00040	06-01-00051	06-01-00065	06-01-00077	06-01-00093	
06-01-00041	06-01-00052	06-01-00066	06-01-00078	06-01-00094	
06-01-00042	06-01-00054	06-01-00067	06-01-00079	06-01-00095	

Classification: Category P1 – Safety

<p>Checked</p> <p>T. Kreißl, CVE </p>	<p>Approved</p> <p> D. Hartung, Office of Airworthiness</p>
---	--



Continental Aerospace
Technologies GmbH
Platanenstrasse 14
09356 Sankt Egidien, Germany

Tel: +49 37204 696 0
Fax: +49 37204 696 2912
www.continentaldiesel.com
support@continentaldiesel.com

SB CG 300-1001 P1

Time of Compliance: Measures have to be accomplished according to actual runtime of the engine and the amount of conducted engine oil analysis.

- a) Engine runtime is below 100 h and no engine oil exchange was carried out (no engine oil sample is available):
Compliance time is 3h, flights are limited to VFR conditions.
- b) Engine runtime is below 100 h and an engine oil exchange was carried out (an engine oil sample is available).
Compliance time is 50 h or next scheduled maintenance, whatever occurs first.
- c) Engine runtime is above 100 h and an engine oil exchange was carried out (engine oil samples are available).
Compliance time is 100h or next scheduled maintenance, whatever occurs first.
If engine oil samples are not available → proceed to a)

Reason: An incident of a power loss was reported. The investigation revealed that the loss of power was caused by a failed main bearing what resulted in an engine failure. The root cause was not fully determined. Continental Aerospace Technologies GmbH has decided to monitor the engine oil closely to identify any abnormalities at an early stage.

Correction: Carry out an engine oil analysis in accordance with OM-06-01, Chapter 6 (Annex 18), submit the results and send the oil filter to Continental Aerospace Technologies GmbH for further analysis.

Additional analysis of all previous conducted Engine oil samples as required by OM-06-01, Chapter 6 (Annex 5) and carry out an Engine oil analysis in accordance with OM-06-01, Chapter 6 (Annex 18), submit the results to Continental Aerospace Technologies GmbH.

Introduction of additional maintenance tasks:

Additional 3-6h (since new) maintenance action:

Carry out an engine oil analysis in accordance with OM-06-01, Chapter 6 (Annex 18), submit the results and send the oil filter to Continental Aerospace Technologies GmbH for further analysis.

Additional 50h (since new) maintenance action:

Carry out an engine oil analysis in accordance with OM-06-01, Chapter 6 (Annex 18), submit the results and send the oil filter to Continental Aerospace Technologies GmbH for further analysis.

Additional maintenance action every 100h:

Carry out an engine oil analysis in accordance with OM-06-01, Chapter 6 (Annex 18), submit the results to Continental Aerospace Technologies GmbH.



Continental Aerospace
Technologies GmbH
Platanenstrasse 14
09356 Sankt Egidien, Germany

Tel: +49 37204 696 0
Fax: +49 37204 696 2912
www.continentaldiesel.com
support@continentaldiesel.com

SB CG 300-1001 P1

Remarks: Labor Effort: 0.5 hours

Parts:

Item	Part Number	Description	Quantity
1	06-9900-19103R1	Bottle 100ml (for the additional 3-6h and 50h maintenance task)	1
	NV-0000-02358 01	Oil analysis set	
2	06-7251-K000201	Oil filter set	1
2.1	06-7251-K001301	Oil filter cartridge	1
2.2	06-7251-K001101	O-ring, stick oil filter	1
2.3	06-7251-K001201	O-ring, cover oil filter	1
3	NM-0000-0192601	Sealing ring	1

Approval: The technical content of this document is approved under the authority of the
DOA ref. EASA.21J.010.

Replaces Service Bulletin No. / Date: -

Page 3 / 3