

DAI OSB 62-006 Page 1 of 3 17-Jun-2016

# OPTIONAL SERVICE BULLETIN OSB 62-006

# I <u>TECHNICAL DETAILS</u>

#### I.1 Category

Optional.

#### I.2 Airplanes affected

 Type:
 DA 62

 Serial numbers:
 62.007, 62.009 through 62.015, 62.017, 62.019 through 62.021

#### I.3 Date of effectivity

17-Jun-2016

#### I.4 Time of Compliance

At owner's discretion

#### I.5 <u>Subject</u>

Retrofit Installation of Sun Visors.

ATA-Code: 25-10

#### I.6 <u>Reason</u>

To reduce fatigue of the pilot's eyes due to sunlight the installation of sun visors for the pilot and copilot is now possible. This service Bulletin describes the retrofit installation for airplanes already in service.

#### I.7 Concurrent Documents

None.

#### I.8 Approval

The technical information or instructions contained in this document relate to the Design Change Advisory No. OÄM 62-022, which has been approved under the authority of EASA Design Organization Approval ref. EASA.21J.052.

The technical content of this document has been approved under the authority of DOA ref. EASA.21J.052.

#### I.9 Accomplishments / Instructions

See WI-OSB 62-006, latest effective issue.

#### I.10 Mass (Weight) and CG

Mass (Weight) and CG affected.



### II PLANNING INFORMATION

#### II.1 Material and Availability

See WI-OSB 62-006, latest effective issue.

#### II.2 Special Tools

See WI-OSB 62-006, latest effective issue.

#### II.3 Labour Effort

Approx. 8 hours.

#### II.4 <u>Credit</u>

None.

#### II.5 Reference Documents

DA 62 Airplane Maintenance Manual, Doc. No. 7.02.25, latest effective issue.

### III <u>REMARKS</u>

- 1. All work must be done by a certified aircraft service station or a certified aircraft maintenance mechanic.
- 2. All work, particular that which is not especially described in this Service Bulletin, must be done in accordance with the referenced Maintenance Manual.
- 3. Completion of all work must be recorded in the log book.
- 4. In case of doubt contact Diamond Aircraft Industries GmbH.



DAI OSB 62-006 Page 3 of 3 17-Jun-2016

### EXECUTION REPORT TO SERVICE BULLETIN OSB 62-006

AIRPLANE INFORMATION				
Airplane Serial Number				-
Airplane Registration				-
Airplane Operator				-
Hours of operation of airplan	е			-
No. of landings				-
Hours of operation-engine	LH			-
	RH			-
Typical operation of airplane		private,	club, training, other	

Date, Name, Sign

Please fax the completed form to Fax No. +43-2622-26700-1369 or e-mail to airworthiness@diamond-air.at



# WORK INSTRUCTION WI-OSB 62-006

# I GENERAL INFORMATION

#### I.1 Subject

Sun Visor Retrofit.

#### I.2 <u>Reference Documents</u>

DA 62 Airplane Maintenance Manual, Doc. No. 7.02.25, latest effective issue.

#### I.3 <u>Remarks</u>

- a) All work must be done by a certified aircraft service station or a certified aircraft maintenance mechanic.
- b) All work, in particular if not described in this work instruction, must be done in accordance with the referenced maintenance manual.
- c) For conversion factors between SI units and US/Imperial units refer to AMM Chapter 02.
- d) In case of doubt, contact Diamond Aircraft Industries GmbH.

### II DRAWINGS, SPECIAL TOOLS & MATERIALS

#### II.1 Drawings

D67-2510-60-00\_02 D67-2510-61-02\_01

#### II.2 Special Tools

Template D67-2510-60-00\_02BV1




#### II.3 Material

Quantity	Part Number	Description
2	D67-9025-30-00	Lens Assembly, DA 62
6	DIN965 AM4x16-B-A2	Screw, Recessed Countersunk Flat Head
2	DS CI4-1-030	Carbon Insert
2	DS CI3-3-050-050	Carbon Insert
6	D67-9053-11-01	Threaded Insert
1	D67-2510-61-02_1	Sun Visor Attachment Bracket
2	BN90304-M5R	Nut Rivet
2	ISO 14583-M5x16 Torx	Button Head Srew
2	007 2050 599 01	Rosette ring M5
2	102 188	Static mixer
1	101970	Plexus MA-300m 50ml

Material is available from Diamond Aircraft Industries.

# III INSTRUCTIONS







	<image/> <caption></caption>
4	Install Template D67-2510-60-00_02BV1 (Fig. 3 item 8) on the compass attachment bracket (Fig. 2 item 6).
	<image/> <caption></caption>
5	Drill the 4 mm holes i.a.w. the template into the ceiling frame.
6	Remove the template.
7	<ul> <li>Prepare 2 insert DS Cl3-3-050-050.</li> <li>Drill the 3 holes according to the template.</li> <li>Drill out the holes to 5.8 mm.</li> <li>Bond the threaded insert D67-9053-11-01 with Plexus MA-300 into the DSC13-3-050-050 insert.</li> </ul>





8	Prepare the bonding surface on the ceiling frame and on the inserts.
	Sand and clean the bonding area.
9	Bond the LH and RH insert in to the ceiling frame with plexus MA-300 and fix it with 3
	bolts to the ceiling frame.
10	Cure for at least 30 minutes. Install the sun visor attachment bracket (Fig. 1 Nr. 4) to the central headliner unit.
10	<ul> <li>Pre-fit the attachment bracket according to drawing D67-2510-61-02_01, position</li> </ul>
	acc. to flag note 2.
	<ul> <li>Mark the position on the cushion and use a soldering iron to make the holes into</li> </ul>
	the cushion.
	Drill two 4 mm holes into the central headliner unit.
11	Prepare the bonding surface on the ceiling frame and on carbon inserts DS CI4-1-030 for
10	bonding.
12	Bond carbon inserts DS CI4-1-030 concentrically to the two holes in the central headliner unit from the rear side with Plexus MA-300.
	Cure for at least 30 minutes.
13	Drill two 7 mm holes through the central headliner unit and the carbon inserts. Install BN
	90304-M5R rivet nut.
14	Install the sun visor attachment bracket on the central headliner unit according to drawing
	D67-2510-61-02_01.
15	Pre-fit the central headliner unit to the Ceiling frame.
16	Install template D67-2510-60-00_02BV1 on the compass attachment. Mark the position
	on the cushion and use a soldering iron to make the hole in to the cushion.
	Drill the holes according to the template. Remove the template from the compass attachment.
17	Install ceiling frame cover 1.
18	Install the central headliner unit on to the ceiling frame.
19	Install the sun visor i.a.w. drawing D67-2510-60-00_02.
20	Check and adjust the friction of the sun visor hinges by torqueing the bolts.
21	Install the magnetic compass i.a.w. AMM section 34-20.
22	Test and adjust the magnetic compass i.a.w. AMM section 34-20
23	Determine the new empty weight and CG and record it in AFM section 6.
	Note: The Sun Visor weighs 0,85kg [1.9lb] with a lever arm of 1.88m [74 in].
	Calculate the empty weight and CG i.a.w. AFM section 6 and AMM Section 08-10.
24	Alternatively weight the airplane i.a.w. AMM Section 08-10.
24	Clean working areas, check for foreign objects.
25	Check all altered, replaced, repaired parts for proper function.
26	Test all systems in working area for function.
27	Make all necessary entries in the airplane logs.



	2	1	_
	REVISION		
	DESCRIPTION	DATE	
VI 62-022, FI	IRST RELEASE	21-MAR-2016	F
			E
			D
	TO CAD FILE POINTS SEE D67-5315-03-00_0	3	C
TH MOLYC	COTE FB 180		
	005 USING MATERIAL		
			2
	La contrata de contrata	ROSEN: 1962000	
ZE	SPECIFICATION	REMARK	В
ndustri	es N. A. Otto-Str A-2700 Wiene		
JECT	DA 62		1
.E			1
	/ISOR ALLATION		
			5
G.ORIG.	DWG. NO.	REV	
DAIA	D67-2510-60-		A
DE 710		SH 01 OF 02	
	2	1 Confidential	8







2	1	ן ך
SECTION C2	- C2	
N.T.S.	15	F
SOR IMENT BRACKET	A La	
	REF. D67-2513-17-00_02	
		E
		D
LE H		
	E.	
~	15	
		C
2 MOUNT LEATHER BRAC AND PARALLEL TO BAG		
3 DRILL HOLES DURING IN		
		Ц
	M. Yolck	В
/	11 APR /	
/		
COLOR: BLACK		
SUPPLIER : FA.SKIFFY	EALOT	$\left  \right $
	FA.KVT	
SPECIFICATION	REMARK	
B.ORIG. DWG. NO.	REV	A
	0-61-02_01	
E 710197 SCALE N	ITS SH 02 OF 02 1 Confidential	
<u>ک</u>		