

TECHNISCHE INFORMATION NR. SI 36-119

HINWES: Technische Informationen werden **nur** verwendet um:
1) Informationen von DAI an unsere Kunden weiterzugeben.
2) Informationen / Dokumente von unseren Zulieferern mit zusätzlichen Informationen an unsere Kunden weiterzugeben.
Typischerweise unterstehen Technische Informationen keinem Revisionsdienst. Neue Informationen oder Änderungen dieser werden durch eine neue Technische Information weitergegeben.

SERVICE INFORMATION NO. SI 36-119

NOTE: SIs are used **only**.
1) To distribute information from DAI to our customers.
2) To distribute applicable information / documents from our suppliers to our customers with additional information.
Typically there is no revision service for SIs. Each new information or change of that will be sent along with a new SI.

I. TECHNISCHE ANGABEN

1.1 Betroffene Flugzeuge:

Alle HK 36 TTS, TTC und TTC-ECO Flugzeuge

1.2 Gegenstand

ATA Code: 72-00

FAA Lufttüchtigkeitsanweisung 2019-21-12

1.3 Anlass

Die FAA hat die Lufttüchtigkeitsanweisung Nr. 2019-21-12 veröffentlicht, welche den Austausch der Auslassventile an Rotax 914 Motoren vorschreibt.

I. TECHNICAL DETAILS

1.1 Airplanes affected:

All HK 36 TTS, TTC and TTC-ECO aircraft

1.2 Subject

ATA Code: 72-00

FAA Airworthiness Directive 2019-21-12

1.3 Reason

FAA has issued Airworthiness Directive 2019-21-12 mandating the exchange of the exhaust valves on ROTAX 914 engines.

1.4 Information

Weitere technische Informationen sind in der FAA Lufttüchtigkeitsanweisung 2019-21-12 enthalten welche ohne weitere Ergänzungen und Einschränkungen anwendbar ist.

II. SONSTIGES

Bei etwaigen Fragen kontaktieren Sie bitte BRP-Powertrain GmbH & Co. KG.

Die FAA Lufttüchtigkeitsanweisung 2019-21-12 liegt dieser Technischen Information bei.

1.4 Information

For detailed technical information refer to FAA Airworthiness Directive 2019-21-12 which is applicable without any further additions or restrictions.

II. OTHER INFORMATION

In case of doubt contact BRP-Powertrain GmbH & Co. KG

FAA Airworthiness Directive 2019-21-12 is attached to this Service Information.

[Federal Register Volume 84, Number 213 (Monday, November 4, 2019)]

[Rules and Regulations]

[Pages 59292-59294]

From the Federal Register Online via the Government Publishing Office [www.gpo.gov]

[FR Doc No: 2019-24029]

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2019-0747; Product Identifier 2019-NE-26-AD; Amendment 39-19778; AD 2019-21-12]

RIN 2120-AA64

Airworthiness Directives; BRP-Rotax GmbH & Co KG Engines

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule; request for comments.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for certain BRP-Rotax GmbH & Co KG (Rotax) 914 F2, 914 F3, and 914 F4 model engines. This AD requires removal of a certain exhaust valve and its replacement with a part eligible for installation. This AD was prompted by a report of a broken exhaust valve installed on a Rotax 914 model engine. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective November 19, 2019.

The FAA must receive comments on this AD by December 19, 2019.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

Federal eRulemaking Portal: Go to <https://www.regulations.gov>. Follow the instructions for submitting comments.

Fax: 202-493-2251.

Mail: U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

Hand Delivery: U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this final rule, contact BRP-Rotax GmbH & Co KG, Rotaxstrasse 1, A-4623 Günskirchen, Austria; phone: +43 7246 601 0; fax: +43 7246 601 9130; email: airworthiness@brp.com; internet: www.flyrotax.com. You may view this service information at the FAA, Engine and Propeller Standards Branch, 1200 District Avenue, Burlington, MA 01803. For information on the availability of this material at the FAA, call 781-238-7759. It is also available

on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0747.

Examining the AD Docket

You may examine the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0747; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the mandatory continuing airworthiness information (MCAI), the regulatory evaluation, any comments received, and other information. The street address for Docket Operations is listed above. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Wego Wang, Aerospace Engineer, ECO Branch, FAA, 1200 District Avenue, Burlington, MA 01803; phone: 781-238-7134; fax: 781-238-7199; email: wego.wang@faa.gov.

SUPPLEMENTARY INFORMATION: Discussion

The European Union Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Community, has issued EASA AD No. 2018-0265R1, dated January 9, 2019 (and corrected January 10, 2019) (referred to after this as “the MCAI”), to address an unsafe condition for the specified products. The MCAI states:

A broken exhaust valve has been reported on a non-certified Rotax 914 UL2-01 engine. Subsequent investigation identified deviation in the manufacturing process of the affected exhaust valve.

This condition, if not corrected, could lead to in-flight shut down, possibly resulting in a forced landing with consequent damage to the aeroplane and injury to occupants.

Due to similarity of design, this condition may affect also Rotax 915 iSc3 A, 915 iSc3 B engines and Rotax 914 F2, 914 F3 and 914 F4 engines.

To address this potential unsafe condition, BRP-Rotax issued the ASB, later revised, providing applicable instructions, and EASA issued AD 2018-0265-E requiring replacement of affected exhaust valves, and prohibiting installation thereof on an engine.

Since that [EASA] AD was issued, it has been determined that only exhaust valve P/N 854113 of certain lot numbers are affected, and BRP-Rotax revised the ASB accordingly (now at revision 2).

You may obtain further information by examining the MCAI in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0747.

Related Service Information

The FAA reviewed BRP-Rotax Alert Service Bulletin (ASB) ASB-915 i A-003R2/ASB-915 i B-003R2/ASB-914-054R2 (single document), dated December 21, 2018. The ASB describes procedures for replacing the exhaust valve.

FAA's Determination

This product has been approved by EASA, and is approved for operation in the United States. Pursuant to the FAA's bilateral agreement with the European Union, EASA has notified the FAA of the unsafe condition described in the MCAI and service information referenced above. The FAA is issuing this AD because it evaluated all the relevant information provided by EASA and determined

the unsafe condition described previously is likely to exist or develop in other products of the same type design.

AD Requirements

This AD requires, within 10 flight hours or 3 months after the effective date of this AD, whichever occurs first, removal from service of certain exhaust valves and replacement with a part eligible for installation.

FAA's Justification and Determination of the Effective Date

An unsafe condition exists that requires the immediate adoption of this AD. The FAA has found that the risk to the flying public justifies waiving notice and comment prior to adoption of this rule because no domestic operators use this product. It is unlikely that the FAA will receive any adverse comments or useful information about this AD from U.S. operators. Therefore, the FAA finds good cause that notice and opportunity for prior public comment are unnecessary. In addition, for this same reason, the FAA finds that good cause exists for making this amendment effective in less than 30 days.

Comments Invited

This AD is a final rule that involves requirements affecting flight safety and was not preceded by notice and an opportunity for public comment. However, the FAA invites you to send any written data, views, or arguments about this final rule. Send your comments to an address listed under the ADDRESSES section. Include the docket number FAA-2019-0747 and Product Identifier 2019-NE-26-AD at the beginning of your comments. The FAA specifically invites comments on the overall regulatory, economic, environmental, and energy aspects of this final rule. The FAA will consider all comments received by the closing date and may amend this final rule because of those comments.

The FAA will post all comments received, without change, to <https://www.regulations.gov>, including any personal information you provide. The FAA will also post a report summarizing each substantive verbal contact received about this final rule.

Regulatory Flexibility Act

The requirements of the Regulatory Flexibility Act (RFA) do not apply when an agency finds good cause pursuant to 5 U.S.C. 553 to adopt a rule without prior notice and comment. Because the FAA has determined that it has good cause to adopt this rule without notice and comment, RFA analysis is not required.

Costs of Compliance

The FAA estimates that this AD affects 0 engines installed on airplanes of U.S. registry.

In the event an affected engine becomes installed on a U.S.-registered product, the FAA estimates the following costs to comply with this AD:

Estimated Costs

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Replace exhaust valve	6 work-hours × \$85 per hour = \$510	\$1,500	\$2,010	\$0

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

This AD is issued in accordance with authority delegated by the Executive Director, Aircraft Certification Service, as authorized by FAA Order 8000.51C. In accordance with that order, issuance of ADs is normally a function of the Compliance and Airworthiness Division, but during this transition period, the Executive Director has delegated the authority to issue ADs applicable to engines, propellers, and associated appliances to the Manager, Engine and Propeller Standards Branch, Policy and Innovation Division.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866, and
- (2) Will not affect intrastate aviation in Alaska.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 December 1, 2019 [Amended]

2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):



2019-21-12 BRP-Rotax GmbH & Co KG (Type Certificate previously held by BRP-Powertrain GmbH & Co KG; Bombardier-Rotax GmbH): Amendment 39-19778; Docket No. FAA-2019-0747; Product Identifier 2019-NE-26-AD.

(a) Effective Date

This AD is effective November 19, 2019.

(b) Affected ADs

None.

(c) Applicability

This AD applies to BRP-Rotax GmbH & Co KG (Type certificate previously held by BRP-Powertrain GmbH & Co KG, Bombardier-Rotax GmbH) (Rotax) Model 914 F2, 914 F3, and 914 F4 engines, with an exhaust valve part number (P/N) 854113 that has a production lot number 0317 or 0517.

(d) Subject

Joint Aircraft System Component (JASC) Code 8530, Reciprocating Engine Cylinder Section.

(e) Unsafe Condition

This AD was prompted by a report of a broken exhaust valve installed on a Rotax 914 model engine. The FAA is issuing this AD to prevent failure of the exhaust valve. The unsafe condition, if not addressed, could result in loss of engine thrust control and reduced control of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

Within 10 flight hours or 3 months after the effective date of this AD, whichever occurs first, remove from service each exhaust valve P/N 854113 that has a production lot number 0317 or 0517, and replace with a part eligible for installation.

Note 1 to paragraph (g): For guidance on replacing the exhaust valve, refer to the Accomplishment Instructions, paragraphs 3.1 through 3.6, of Rotax Alert Service Bulletin ASB-915 i A-003R2/ASB-915 i B-003R2/ASB-914-054R2 (single document), dated December 21, 2018.

(h) Installation Prohibition

After the effective date of this AD, do not install an exhaust valve P/N 854113 that has a production lot number 0317 or 0517 on any engine.

(i) Alternative Methods of Compliance (AMOCs)

(1) The Manager, ECO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (j)(1) of this AD. You may email your request to: ANE-AD-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(j) Related Information

(1) For more information about this AD, contact Wego Wang, Aerospace Engineer, ECO Branch, FAA, 1200 District Avenue, Burlington, MA 01803; phone: 781-238-7134; fax: 781-238-7199; email: wego.wang@faa.gov.

(2) Refer to European Union Aviation Safety Agency (EASA) AD No. 2018-0265R1, dated January 9, 2019 (and corrected January 10, 2019), for more information. You may examine the EASA AD in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating it in Docket No. FAA-2019-0747.

(k) Material Incorporated by Reference

None.

Issued in Burlington, Massachusetts, on October 29, 2019.
Robert J. Ganley,
Manager, Engine and Propeller Standards Branch,
Aircraft Certification Service.