

**Diamond Aircraft Publications**

Doc. No.	Description	Revision 89 Updates	Status
DA20-24-05 (O)	Replacement of the Aircraft Battery		Rev 0 - Aug-25-25

**Diamond Aircraft Publications**

Doc. No.	Description	Full Listing	Status
----------	-------------	--------------	--------

**Aircraft Manuals**

DA200	List of Applicable Publications (This document)		Rev 88 - Aug-02-23
DA201-A1	Aircraft Maintenance Manual (AMM)		Rev 16 - Jun-06-21
DA202	Airplane Flight Manual (English Day/Night VFR)		Rev 18 - Jan-18-12
DA202-VLA	Airplane Flight Manual (English - VLA Certification)		Rev 8 - Jan-18-12
DA202-100	Airplane Flight Manual (Katana 100 English Day/Night VFR)		Rev 6 - Jan-18-12
DA202-100-VLA	Airplane Flight Manual (Katana 100 English VLA Certification)		Rev 5 - Jan-18-12
DA202 TR# 12-01	Temporary Revision to Rev 18 of the DA202 Flight Manual - Maximum Cylinder Head Temperature		Rev 0 - Nov-09-12
DA202 TR# 12-02	Temporary Revision to Rev 18 of the DA202 Flight Manual - New Oil Pressure Indicator		Rev 0 - Dec-18-12
DA202 TR# 15-01	Temporary Revision TR 15-01 - Coolant Temperature Limit		Rev 0 - Jan-22-15
DA202 TR# 23-01	Temporary Revision to Rev 18 of the DA202 Flight Manual - Amerex 337TS Fire Extinguisher		Rev 0 - Apr-01-23
DA202-100 TR# 12-01	Temporary Revision to Rev 6 of the DA202-100 Flight Manual - Maximum Cylinder Head Temperature		Rev 0 - Nov-09-12
DA202-100 TR# 12-02	Temporary Revision to Rev 6 of the DA202-100 Flight Manual - New Oil Pressure Indicator		Rev 0 - Dec-18-12
DA202-100 TR# 15-01	Temporary Revision TR 15-01 - Coolant Temperature Limit		Rev 0 - Jan-22-15
DA202-100 TR# 23-01	Temporary Revision to Rev 6 of the DA202-100 Flight Manual - Amerex 337TS Fire Extinguisher		Rev 0 - Apr-01-23
DA203-A1	Illustrated Parts Catalogue		Rev 6 - Nov-17-20

Diamond Aircraft Publications				
Doc. No.	Description	Full Listing		Status
<b><u>Service Bulletins</u></b> (A) = Alert, (M) = Mandatory, (O) = Optional, (R) = Recommended				
<b>Chapter 10 - Parking, Mooring, Storage, Return to Service</b>				
DA20-10-01 (R)	Control lock and fixed provisions, Installation			Rev 0 - Jun-19-96
<b>Chapter 12 - Servicing</b>				
DA20-12-01 (R)	Fuel pipette and fixed provision, Installation			Rev 0 - Jun-19-96
<b>Chapter 24 - Electrical Power</b>				
DA20-24-01 (O)	Alternator belt			Rev 0 - Mar-09-96
DA20-24-02 (R)	DC Generation, Improved generator grounding			Rev 0 - Jan-08-96
DA20-24-03 (R)	Electrical cables, Engine compartment			Rev 0 - Apr-18-97
DA20-24-04 (O)	Replacement of Battery Relay Contactor			Rev 0 - Nov-08-12
DA20-24-05 (O)	Replacement of the Aircraft Battery			Rev 0 - Aug-25-25
<b>Chapter 25 - Equipment/Furnishings</b>				
DA20-25-01 (O)	Installation of Rescue Hammer			Rev 0 - Sep-21-11
<b>Chapter 27 - Flight Controls</b>				
DA20-27-01 (M)	Flap actuator, Replacement of 12 volt with 24 volt motor			Rev 0 - Mar-09-96
DA20-27-02 (O)	Trim display modification			Rev 0 - Sep-03-96
DA20-27-03A (A)	Rudder Control Cables, Forward			Rev 0 - Sep-24-96
DA20-27-04A (A)	Rudder pedal adjust cable			Rev 0 - Sep-24-96
DA20-27-05 (M)	Rudder support bracket inspection			Rev 0 - Nov-13-96
DA20-27-06A (A)	Hinges, Flight controls			Rev 0 - Apr-17-97
DA20-27-07 (O)	Rudder Pedal Adjust System			Rev 0 - Apr-21-97
DA20-27-08A (A)	Control Surface Hinge Inspection			Rev 1 - Jan-19-01
DA20-27-09 (O)	Installation of Diamond Flap Module and Microswitch Tray Installation			Rev 0 - Aug-14-19
<b>Chapter 28 - Fuel System</b>				
DA20-28-01 (R)	Fuel cap, Safety chain			Rev 0 - Aug-26-96
DA20-28-02A (A)	Fuel system indicating and storage			Rev 0 - Dec-11-96
DA20-28-03 (O)	Fuel filler cap, Locking			Rev 1 - Sep-09-99
DA20-28-04A (A)	Inspection for twisted Fuel Hoses			Rev 0 - Nov-08-00
<b>Chapter 31 - Indicating / Recording Systems</b>				
DA20-31-01 (O)	Temperature limitation, Structural 55 Degree Celsius			Rev 0 - Mar-09-96

Diamond Aircraft Publications				
Doc. No.	Description	Full Listing		Status
DA20-31-02 (O)	Hourmeter, Engine activated installation			Rev 1 - May-02-06
<b>Chapter 32 - Landing Gear</b>				
DA20-32-01 (R)	Brake System Retrofit			Rev 3 - Nov-28-97
DA20-32-02 (R)	Nose Gear Fork, Fatigue			Rev 0 - Jan-08-99
DA20-32-04 (M/R)	Inspection of NLG Elastomer Spring and Installation of Replacement Elastomer Elements			Rev 1 - Jun-09-08
DA20-32-05 (O)	Replacement of Steel MLG Struts with Aluminum MLG Struts			Rev 3 - Sep-23-21
DA20-32-06 (R)	NLG Wheel and Fork Installation Improvements			Rev 0 - Jul-15-11
<b>Chapter 33 - Lights</b>				
DA20-33-02 (M)	Instrument lighting, Dimming circuit for KLX 135A KLX GPS/COM			Rev 0 - Jan-08-96
DA20-33-03 (O)	Cockpit Night Lighting System Installation			Rev 0 - May-27-13
<b>Chapter 52 - Doors</b>				
DA20-52-01 (R)	Canopy Locking Mechanism Adjustment			Rev 0 - Dec-10-12
<b>Chapter 53 - Fuselage</b>				
DA20-53-01A (A)	Interference, Rudder Pedal/Foot			Rev 0 - Jun-05-97
DA20-53-02A (A)	A-Bolt Washer Size			Rev 0 - Feb-05-99
<b>Chapter 55 - Stabilizers</b>				
DA20-55-02A (A)	Mount, Forward attachment, Horizontal stabilizer inspection			Rev 0 - Mar-09-96
DA20-55-03 (R)	Stabilizer shim, Mount, Forward			Rev 0 - Sep-09-96
DA20-55-04 (R)	Rudder Upper Bearing			Rev 1 - Mar-27-08
<b>Chapter 56 - Windows/Canopy</b>				
DA20-56-01 (R)	Canopy, Side window water drain			Rev 0 - Jan-10-96
DA20-56-02 (R)	Canopy, Spring			Rev 0 - Nov-30-96
<b>Chapter 57 - Wings</b>				
DA20-57-01 (R)	Wing "B" Bolt Access Cover Locking Device			Rev 0 - Mar-09-96
DA20-57-02A (A)	Aileron control fairing modification			Rev 0 - Mar-07-96
<b>Chapter 61 - Propeller</b>				
DA20-61-01 (M)	Propeller pitch stop, ref Hoffmann Instruction No. E592			Rev 0 - Mar-09-96
<b>Chapter 72 - Engine</b>				
DA20-72-01 (M)	Inspection, Coolant bottle			Rev 0 - Mar-06-97
DA20-72-02 (M)	Evans NPG+ Coolant			Rev 0 - Aug-22-06

Diamond Aircraft Publications			
Doc. No.	Description	Full Listing	Status
DA20-72-03 (O)	Use of 50/50 Glycol Coolant types to Comply with EASA AD No. 2007-0155		Rev 2 - Jul-23-09
DA20-72-04A (M)	Change of Measurement from CHT to Coolant Temperature		Rev 0 - Jan-22-15
<b>Chapter 73 - Engine Fuel</b>			
DA20-73-01 (O)	Rotax 912 A3 to Rotax 912 F3 Airframe conversion		Rev 0 - Apr-18-97
DA20-73-02A (A)	Fatigue, Fuel pump outlet		Rev 0 - Apr-17-97
DA20-73-03 (O)	Automotive Fuel Conversion		Rev 2 - Apr-13-98
DA20-73-04A (A)	Automotive Fuel, Fuel Line Blockage		Rev 2 - Mar-23-98
DA20-73-05 (R)	Introduction of a new Fuel Pump Assembly		Rev 0 - Aug-12-11
<b>Chapter 74 - Engine Ignition</b>			
DA20-74-01 (R)	Activation of an Advanced Start Module		Rev 0 - Sep-28-11
<b>Chapter 75 - Engine Air</b>			
DA20-75-01 (M)	Rotax Airbox Installation (DA20/100)		Rev 0 - May-24-01
<b>Chapter 76 - Engine Controls</b>			
DA20-76-01A (A)	Throttle cable replacement		Rev 5 - May-07-97
<b>Chapter 77 - Engine Indicating</b>			
DA20-77-01 (R)	Tachometer, Cable assembly inspection		Rev 0 - Jul-30-96
DA20-77-02 (O)	Electric Tachometer		Rev 2 - Sep-30-16
DA20-77-03 (O)	Superior Labs Tachometer Installation		Rev 1 - Nov-30-06
<b>Chapter 78 - Engine Exhaust</b>			
DA20-78-01 (R)	Exhaust system, Improved joint sealing		Rev 1 - Nov-28-97
DA20-78-02 (O)	Exhaust header, Type 3 & 4		Rev 0 - Apr-18-97
DA20-78-03A (A)	Exhaust header, Security		Rev 0 - Apr-18-97
DA20-78-04A (R)	Exhaust System, Fatigue		Rev 3 - Aug-02-23
<b>Chapter 79 - Engine Oil System</b>			
DA20-79-01 (R)	Remote mounting of oil pressure transducer		Rev 1 - Nov-28-97
DA20-79-02 (O)	Winterization kit		Rev 1 - Sep-18-96
DA20-79-03 (R)	Oil Dipstick, Thermal insulator		Rev 1 - Mar-15-11
DA20-79-04A (A)	Defective oil filter		Rev 1 - Nov-28-97
DA20-79-05 (R)	DA20-A1 - Oil Line Retrofit - F3 Engine		Rev 4 - Jun-13-14
DA20-79-06A (A)	Inspection of Oil Tank Cover		Rev 1 - May-02-00

Diamond Aircraft Publications			
Doc. No.	Description	Full Listing	Status
DA20-79-07 (M)	Oil Quantity Placard		Rev 0 - Sep-18-03
DA20-79-08 (M) or (O)	Introduction of a new Oil Pressure Indicator		Rev 2 - Dec-17-12
<b>Miscellaneous</b>			
DA20-92-04	Installation of Photo Luminescent Placards		Rev 0 - May-27-13
DA20-92-05	Operating Limitation		Rev 0 - May-27-13
<b><u>Service Information Letters</u></b>			
SIL20A1-001	Service Information Letter advising of a Mandatory Service Bulletin released by Rotax SB-912-056/SB-914-038 "Replacement of the Propeller Gearbox for some Rotax Engines Type 912/914 Series".		Rev 0 - Jan-22-08
SIL20A1-002	Service Information Letter advising of a Mandatory Service Bulletin released by Rotax SB-912-051/SB-914-034 "Checking of magnetic Plug on Rotax Engines Type 912/914 Series".		Rev 0 - Jan-31-08
SIL20A1-003	Service Information Letter to introduce ROTAX Service Instructions SI-912-021 and SI-914-023. "Inspection of Carburetors".		Rev 0 - Dec-15-09
SIL20A1-004	Service Information Letter to introduce application of wheel bearing grease for Wheel Assemblies		Rev 0 - Aug-03-10
SIL20A1-005	Service Information Letter to implement FAA AD requiring replacement of fuel pumps in Rotax Aircraft Engines 912 A series.		Rev 0 - Aug-23-10
SIL20A1-006	Service Information Letter to implement FAA AD requiring inspection of the oil loss caused by cracks in the engine crankcase of Rotax Aircraft Engines type 912 S and 914 F Series.		Rev 0 - Oct-19-10
SIL20A1-007	Service Information Letter to introduce ROTAX Service Bulletin, Introduction of a New Oil Dipstick for ROTAX Engine Type 912 and 914 (Series), SB-912-040 R1, SB-914-026 R1.		Rev 0 - Mar-09-11
SIL20A1-008	Service Information Letter to reflect the improvement in the design of the Nose Landing Gear (NLG) Fork Assembly.		Rev 0 - Mar-28-11
SIL20A1-009	Service Information Letter to introduce Airworthiness Directive No.: AD 2011-0067- Mandating accomplishment with Rotax Service Bulletin SB-912-058, which prescribes the replacement of the washer P/ N 944072 on the Flywheel hub at certain engine series.		Rev 0 - Apr-19-11
SIL20A1-010	Service Information Letter to introduce Airworthiness Directive No.: AD 2011-14-09 mandating accomplishment with Rotax Service Bulletin SB-912-058, which prescribes the replacement of washer P/ N 944072 on the Flywheel hub at certain engine series.		Rev 0 - Jul-20-11
SIL20A1-011	Service Information Letter to introduce Emergency Airworthiness Directive No. 2011-0222-E prescribing inspection of the crankshaft journal (power take off side) of certain crank shaft serial numbers and certain engine serial numbers in reference to Rotax Alert Service Bulletin ASB-912-059.		Rev 0 - Nov-21-11

Diamond Aircraft Publications			
Doc. No.	Description	Full Listing	Status
SIL20A1-012	Service Information Letter to introduce Rotax Alert Service Bulletin ASB 912-059 requiring an inspection of the crankshaft journal for certain engine serial numbers.		Rev 0 - Nov-21-11
SIL20A1-013	Service Information Letter to introduce Rotax Alert Service Bulletin ASB 912-060 - Checking of the oil pump fixing torque.		Rev 0 - Jan-24-12
SIL20A1-014	Service Information Letter to introduce EASA Emergency Airworthiness Directive No. 2012-0019-E Deviation in the assembly process of the oil pump attachment bolts		Rev 0 - Jan-30-12
SIL20A1-015	Service Information Letter to introduce Rotax Alert Service Bulletin ASB-912-061R1 prescribing the replacement of the pressure side fuel hose at fuel pumps with a certain part number.		Rev 0 - May-31-12
SIL20A1-016	Service Information Letter to introduce EASA Emergency Airworthiness Directive No. 2012-093-E covering Rotax Alert Service Bulletin ASB-912-061R1 for the replacement of the pressure side fuel hose at fuel pumps with a certain part number.		Rev 0 - May-31-12
SIL20A1-017	Service Information Letter to introduce EASA Emergency Airworthiness Directive No. 2012-0097R1 covering Rotax Alert Service Bulletin ASB-912-061R1 for the replacement of the pressure side fuel hose at fuel pumps with a certain part number.		Rev 0 - Jun-04-12
SIL20A1-018	Service Information Letter to introduce FAA Airworthiness Directive No. 1212-15-01, 14 Aug 12 covering Rotax Alert Service Bulletin ASB-912-061R1, 31 May 12 prescribing replacement of the pressure side fuel hose at fuel pumps with a certain part number.		Rev 0 - Aug-17-12
SIL20A1-019	Cylinder HEad Assembly Inspection - EASA Emergency AD 2013-0117-E and FAA AD 2013-07-012		Rev 0 - Jun-13-13
SIL20A1-020	Rotax Mandatory Service Bulletin SB-912-065		Rev 0 - Oct-10-14
SIL20A1-021	United Instruments SB No. 13		Rev 0 - Mar-30-17
SIL20A1-023	Exhaust System Inspection and Installation		Rev 0 - Feb-11-19
SIL20A1-024	Aircraft cleaning and disinfection recommendations		Rev 0 - May-21-20
SIL20A1-025	Nose landing gear maintenance and inspections		Rev 0 - Jan-12-23
SIL20A1-026	United Instruments Service Note No. 14		Rev 0 - Apr-13-23

#### Rotax Publications

For the complete and up-to-date list of Rotax Publications refer to their Website:

<http://www.flyrotax.com/customer-service/Impressum/technical-publications.aspx>

#### Hoffmann Propeller Publications

For the complete and up-to-date list of Hoffmann Propeller Publications refer to their Website:

<http://www.hoffmann-prop.com/en/index.php>

This list identifies documentation directly applicable to the Safe Operation and Maintenance of the DA20-A1 and DA20-100 Aircraft.

This list includes links to relevant vendor documents that Diamond Aircraft is aware of for the DA20-A1 and DA20-100 aircraft. Vendor documents are not posted on the Diamond Aircraft Website.

Other information pertaining to specific components (e.g. Avionics) should be obtained directly from the Vendor or Manufacturer.

For publication revision and subscription service, please contact the following:

**Diamond Aircraft Industries****North America, Australia, South Africa:**

Diamond Aircraft Industries Inc.  
Customer Support  
1560 Crumlin Sideroad  
London, ON, Canada  
N5V 1S2  
Phone: +1 800-268-4001

**Europe, Other:**

Diamond Aircraft Industries GmbH.  
Customer Support  
N.A. Otto-Strasse 5  
A-2700 Wiener Neustadt  
Austria  
Phone: 011-43-2622-26700

**Rotax****North America:**

Rotech Research Canada Ltd.  
6235 Okanagan Landing Road  
Vernon, BC V1H 1M5  
Canada  
Phone: 250-260-6299

**Europe, Other:**

Bombardier – Rotax GmbH.  
Motorenfabrik  
A-4623 Günskirchen  
Austria  
Phone: 011-43-7246-271-0

**Hoffmann Propeller****North America, Australia, South Africa:**

Authorized Distributor  
Diamond Aircraft Industries Inc.  
Customer Support  
1560 Crumlin Sideroad  
London, ON, Canada  
N5V 1S2  
Phone: 519-457-4041

**Europe, Other:**

Hoffmann Propeller GmbH. & Co.  
Customer Support  
Kupferlingstr. 9  
D-83022 Rosenheim  
Germany  
Phone: 011-49-8031-1878-0