

Diamond Aircraft Publications			
Doc. No.	Description	Revision 106 Updates	Status
DA201-C1 TR-MAM- 22-0016	Flap Actuator Mo	tor	Rev 0 - Dec-16-24
Diamond Aircraft Publications			
Doc. No.	Description	Full Listing	Status
Aircraft Manuals			
DA200-C1	List of Applicable	Publications (this document)	Rev 106 - Dec-31-24
DA201-C1	Aircraft Maintena	nce Manual	Rev 25- Mar-14-23
DA201-C1 TR-MAM- 22-0016	Flap Actuator Mo	tor	Rev 0 - Dec-16-24
DA202-C1	Airplane Flight M	anual (English Day/Night VFR)	Rev 29 - Jun-30-21
DA202-C1 TR# 23-01	Amerex 337TS F	ire Extinguisher	Rev 0 - Apr-01-23
DA203-C1	Illustrated Parts Catalogue		Rev 12 - Aug-27-21

Rev 13- Apr-17-23

DA203-C1

Illustrated Parts Catalogue



Diamond Aircraft Publications				
Doc. No.	Description Full Listing	Status		
Service Bulletins	(A) = Alert, (M) = Mandatory, (O) = Optional, (R) = Recommended			
Chapter 11 - Placards	Chapter 11 - Placards and Markings			
DAC1-11-01 (R)	Chinese Placards and Markings	Rev 3 - Sep-29-14		
Chapter 23 - Commun	nications			
DAC1-23-01 (R)	GMA 340 Isolation Diodes	Rev 0 - Dec-08-04		
DAC1-23-50 (O)	Installation of 27 Ohm Resistor	Rev 0 - Sep-09-09		
Chapter 24 - Electrica	al Power			
DAC1-24-01 (R)	Generator Lower Attaching Bolt Replacement	Rev 1 - Mar-03-10		
DAC1-24-03 (O)	G-35M Battery Option	Rev 2 - Apr-27-10		
DAC1-24-04 (R)	Generator Attachment Bracket	Rev 3 - Jul-18-08		
DAC1-24-05 (O)	Installation of the BC100-1 or the ODS-AGM28LMJ Battery on the Battery Shelf	Rev 2 - Mar-30-23		
DAC1-24-06 (O)	Installation of YTX24HL-BS Battery on Firewall	Rev 0 - Jan-14-04		
DAC1-24-07 (O)	Replacement of Battery/EPU Relay Contactor	Rev 0 - Nov-08-12		
DAC1-24-08 (O)	Installation of the external power unit (EPU) system	Rev 1 - Jan-23-20		
DAC1-24-09 (O)	Installation of the ODS-AGM28LMJ Battery on the Firewall	Rev 1 - Sep-18-23		
Chapter 25 - Equipme	ent and Furnishings			
DAC1-25-01 (R)	EBC502 to Artex ELT Upgrade	Rev 5 - Dec-16-21		
DAC1-25-02 (R)	ME406 ELT Installation on Reverse Panel	Rev 0 - Nov-23-10		
DAC1-25-03 (O)	Installation of Safety Hammer, Type II	Rev 0 - Aug-19-11		
DAC1-25-04 (O)	ELT 1000 Retrofit	Rev 0 - Oct-28-21		
Chapter 27 - Flight Co	ontrols			
DAC1-27-01 (O)	Control Stick Elevator Trim Installation	Rev 0 - Apr-26-01		
DAC1-27-02 (O/R)	Flap Actuator Bushing Retainers	Rev 1 - Feb-01-08		
DAC1-27-03 (M)	Inspection of Flap Bellcrank (Mandatory)	Rev 1 - May-13-19		
DAC1-27-04 (O)	Installation of Diamond Flap Control & Microswitch Tray	Rev 1 - Jan-10-20		
Chapter 28 - Fuel System				
DAC1-28-01 (O)	Type II Fuel System/Pump Retrofit	Rev 0 - Oct-08-98		
DAC1-28-02 (M)	2-Speed Electric Fuel Pump System	Rev 3 - Oct-27-99		



Diamond Aircraft Publications			
Doc. No.	Description	Full Listing	Status
Chapter 30 - Ice and R	ain Protection		
DAC1-30-02 (O)	Installation of a Hea	ated Pitot Static Probe	Rev 1 - Aug-25-22
Chapter 31 - Indicating	g Systems		
DAC1-31-01 (O)	Removal of OAT/Cl	ock AA Battery	Rev 0 - Jun-29-17
Chapter 32 - Landing	Gear		
DAC1-32-01 (O/R)	Nose Gear Shock S	Strut	Rev 0 - Feb-28-07
DAC1-32-02 (O)	Optional Installation of Extended Main Landing Gear Struts		Rev 0 - Jun-05-09
DAC1-32-03 (R)	NLG Wheel and Fo	rk Installation Improvements	Rev 0 - Jul-15-11
Chapter 33 - Lights			
DAC1-33-01 (O)	Recognition Lights		Rev 1 - Feb-21-00
DAC1-33-02 (O)	Installation of Repla	acement Electro Luminescent (EL) Flood Light	Rev 1 - Aug-11-11
DAC1-33-04 (O)	Installation of Backl	ighting on the Instrument Panel	Rev 2 - Feb-06-12
DAC1-33-05 (R)	Installation of RFI P	rotected Lighting Voltage Regulator Assembly	Rev 0 - Feb-23-15
DAC1-33-06 (O)	Installation of LED A	Anti-Collision and Position Light Assembly	Rev 3 - May-13-19
DAC1-33-07 (O)	Installation of Dimm	ning Module	Rev 1 - Jan-10-20
DAC1-33-08 (O)	Installation of LED I	anding and Taxi Lights	Rev 0 - Oct-13-22
Chapter 34 - Navigation	on		
DAC1-34-02 (O)	Installation of Backu	up Artificial Horizon Indicator	Rev 2 - Jan-28-13
DAC1-34-06 (R)	Garmin G500 Softw	vare Upgrade	Rev 0 - Mar-07-14
DAC1-34-09 (O)	Garmin G500 Softw	vare Upgrade 006-B1076-63	Rev 0 - Jun-20-16
DAC1-34-10 (M)	GTX345 and TAS60	05 Audio Lines	Rev 0 - Oct-13-20
DAC1-34-11 (O)	Garmin GI 275 Insta	allation	Rev 0 - May-13-21
DAC1-34-12 (O)	This service bulleting	addresses the installation of COMM 2.	Rev 0- Mar-05-24
Chapter 52 - Doors			
DAC1-52-01 (O)	Canopy, Seal Repla	acement	Rev 0 - Jan-07-99
DAC1-52-03 (R)	Canopy Lock Cover	r Plate Installation	Rev 1 - Aug-17-99
Chapter 53 - Fuselage			
DAC1-53-01 (R)	Spar Bridge Gusset	t Reinforcement	Rev 3 - Sep-15-14
Chapter 55 - Stabilizers			
DAC1-55-01A (A)	Horizontal Stabilize	r Attachment	Rev 3 - Mar-30-01



Diamond Aircraft Publications				
Doc. No.	Description	Full Listing	Status	
Chapter 57 - Wings				
DAC1-57-01 (O)	Installation of Ailero	n Roller Guide Access Panels	Rev 1 - May-13-19	
Chapter 61 - Propeller	s			
DAC1-61-00A (A)	Spinner Rear Bulkhead Replacement		Rev 1 - Apr-02-01	
DAC1-61-01 (R)	Sensenich W69EK7-63 Propeller Installation		Rev 5 - Nov-29-19	
Chapter 71 - Power Pl	ant - General			
DAC1-71-01 (O)	Cowling Thermal Pr	rotection Shielding	Rev 1 - May-16-02	
DAC1-71-02	Engine Mount to Fir	rewall Washers	Rev 0 - Jan-19-04	
DAC1-71-03 (O)	Winterization Kit		Rev 0 - May-19-04	
DAC1-71-04 (O)	Enlarged Cowl Inlet	for Hot Weather Operation	Rev 0 - Jun-29-04	
Chapter 73 - Engine F	uel and Controls			
DAC1-73-04 (O/R)	Engine Fuel Systen	n Conversion IO-240-B17B to IO-240-B3B	Rev 5 - Nov-26-10	
DAC1-73-05 (M)	Operating Limitation	ns with Altitude Compensating Fuel Systems	Rev 1 - Dec-14-07	
Chapter 74 - Engine Ig	ınition			
DAC1-74-01 (R)	Ignition Harness Ro	puting	Rev 1 - Sep-19-14	
DAC1-74-02 (R)	Starting Vibrator Ba	ttery Installation	Rev 0 - Feb-18-00	
DAC1-74-03 (O)	Installation of Optio	nal Push-to-Start Ignition Switch	Rev 2 - Mar-09-11	
DAC1-74-04 (O)	Installation of the Yu	uasa NP1.2-12 starter vibrator battery and battery tray	Rev 0 - Sep-01-22	
Chapter 76 - Engine C	ontrols			
DAC1-76-01 (R)	Mixture Cable Kinki	ng	Rev 1 - Jan-29-99	
DAC1-76-02 (R)	Mixture Cable Rout	ing - Reversed Panel	Rev 0 - Dec-03-03	
DAC1-76-03 (O)	Installation of Mixtu	re Cable for Altitude Compensating Fuel Pump	Rev 2 - Mar-06-06	
DAC1-76-04 (R)	Throttle Cable Firev	vall Feed-Thru	Rev 1 - Jan-28-10	
Chapter 77 - Engine Indicating				
DAC1-77-01 (O)	Installation of Impro	ved Indicating Systems	Rev 5 - Feb-09-23	
Chapter 79 - Engine Oil System				
DAC1-79-01 (O)	Power Plant Cooling	g	Rev 0 - Nov-09-99	
DAC1-79-02 (R)	Oil Filler Bracket Ins	stallation	Rev 0 - Apr-10-01	



Diamond Aircraft Publications			
Doc. No.	Description	Full Listing	Status
Miscellaneous			
DAC1-92-03	Mexican Import Requirements		Rev 0 - Feb-28-07
DAC1-92-07	Operation Limit Changes for EASA Member Countries		Rev 1 - Aug-09-12
DAC1-92-08	Installation of Illum	inated Placards	Rev 0 - Aug-09-12

Complete Information Letters				
Service Information Letters				
SIL20C1-001	Service Information Letter to introduce Garmin Software Service Bulletin No.: 0943 Rev A.	Rev 0 - Jan-11-10		
SIL20C1-002	Service Information Letter to introduce Garmin Service Bulletin No. 0714 Rev. A.	Rev 0 - Mar-24-10		
SIL20C1-003	Service Information Letter to introduce AMM TR # 12-01, Scheduled Servicing for Brake Pedal Pivot	Rev 0 - May-12-10		
SIL20C1-004	Service Information Letter to introduce application of wheel bearing grease for wheel assemblies	Rev 0 - Aug-03-10		
SIL20C1-005	Service Information Letter to introduce new improved design of NLG fork assembly	Rev 0 - Oct-07-10		
SIL20C1-006	Service Information Letter for the inspection and maintenance of the throttle control arms installation	Rev 0 - Jan-22-13		
SIL20C1-007	Service Information Letter to introduce Garmin Service Advisory No. 1361	Rev 0 - Nov-20-13		
SIL20C1-008	Service Information Letter to introduce Andiar Service Alert GAS375-D	Rev 0 - Jan-22-13		
SIL20C1-009	Service Information Letter to introduce Slick Service Bulletin SB1-15A	Rev 1 - Jan-10-19		
SIL20C1-010	Service Information Letter to introduce United Instruments Service Bulletin No.13	Rev 0 - Apr-14-16		
SIL20C1-011	Service Information Letter regarding LPI of the NLG Strut	Rev 0 - Sep-19-18		
SIL20C1-012	Inspection of aircraft step assemblies	Rev 0 - May-07-19		
SIL20C1-013	Aircraft cleaning and disinfection recommendations	Rev 0 - May-21-20		
SIL20C1-014	Nose landing gear maintenance and inspections	Rev 0 - Jan-12-23		
SIL20C1-015	Garmin SB22071	Rev 0 - Aug-10-22		
SIL20C1-016	United Instruments Service Note No. 14	Rev 0 - Apr-13-23		

DOC # DA200-C1 31 December 2024 Page: 5 of 7



Continental Motors Publications

For the complete and up-to-date list of Continental Motors publications, refer to their website:

http://www.genuinecontinental.aero/PublicationList.aspx

Hoffmann Propeller Publications

For the complete and up-to-date list of Hoffmann Propeller publications, refer to their website:

http://www.hoffmann-prop.com/en/index.php

Sensenich Propeller Publications

For the complete and up-to-date list of Sensenich Propeller publications, refer to their website:

http://www.sensenich.com/support/documents



This list identifies documentation directly applicable to the safe operation and maintenance of the DA20-C1 aircraft. It is recommended that operators periodically verify that their documentation is at the correct issue/revision levels. The List of Applicable Publications (LOAP) will be updated at least quarterly, and sent to all registered subscribers. If you have not received your LOAP update for more than three months, contact Diamond Aircraft Customer Support at the following listed numbers immediately.

This list includes links to relevant vendor documents that Diamond Aircraft is aware of for the DA20-C1 aircraft. Vendor documents are not posted on the Diamond Aircraft website.

Other information pertaining to specific components (e.g. avionics) should be obtained directly from the vendor or manufacturer.

For publication revision and subscription service, please contact the following:

Diamond Aircraft Industries

North America, Australia, South Africa:

Diamond Aircraft Industries Inc.

Customer Support 1560 Crumlin Sideroad London, ON, Canada

N5V 1S2

Phone: 519-457-4041

Europe, Other:

Diamond Aircraft Industries GmbH.

Customer Support N.A. Otto-Strasse 5 A-2700 Wiener Neustadt

Austria

Phone: 011-43-2622-26700

Teledyne Continental Motors

Contact TCM directly for publication information.

North America:

Teledyne Continental Motors

P.O. Box 90

Mobile, Alabama, USA

36601

Phone: 334-438-3411

Sensenich Propeller Manufacturing Company

Contact Sensenich directly for publication information.

North America:

Sensenich Wood Propeller Company

2008 Wood Court Plant City, Florida

33567

Phone: 813-752-3711

Hoffmann Propeller

North America, Australia, South Africa: Europe, Other:

Authorized Distributor Hoffmann Propeller GmbH. & Co.

Diamond Aircraft Industries Inc.

Customer Support

Customer Support

Kupferlingstr. 9

1560 Crumlin Sideroad

D-83022 Rosenheim

London, ON, Canada Germany

N5V 1S2

Phone: 519-457-4041 Phone: 011-49-8031-1878-0