

Diamond Aircraft Publications			
Doc. No.	Description	Revision 109 Updates	Status
DAC1-27-05 (O)	Replacement of the flap actuator and installation of the flap resistor assembly		Rev 1 - Mar-13-25
Diamond Aircraft Publications			
Doc. No.	Description	Full Listing	Status
Aircraft Manuals			
DA200-C1	List of Applicable Publications (this document)		Rev 109 - Mar-13-25
DA201-C1	Aircraft Maintenance Manual		Rev 25- Mar-14-23
DA201-C1 TR-MAM- 22-0016	Flap Actuator Motor		Rev 0 - Dec-16-24
DA201-C1 TR- MOD0333	Installation of the Artex ELT 1000		Rev 0 - Jan-15-25
DA202-C1	Airplane Flight Manual (English Day/Night VFR)		Rev 29 - Jun-30-21
DA202-C1 TR# 23-01	Amerex 337TS Fire Extinguisher		Rev 0 - Apr-01-23
DA203-C1	Illustrated Parts Catalogue		Rev 12 - Aug-27-21
DA203-C1	Illustrated Parts Ca	atalogue	Rev 13- Apr-17-23

DOC # DA200-C1 13 March 2025 Page: 1 of 7 NOTE: this document is re-issued at each revision.



Diamond Aircraft Publications					
Doc. No.	Description	Full Listing	Status		
Service Bulletins	(A) = Alert, (M) = M	landatory, (O) = Optional, (R) = Recommended			
Chapter 11 - Placards	Chapter 11 - Placards and Markings				
DAC1-11-01 (R)	Chinese Placards a	Rev 3 - Sep-29-14			
Chapter 23 - Communications					
DAC1-23-01 (R)	GMA 340 Isolation	Diodes	Rev 0 - Dec-08-04		
DAC1-23-50 (O)	Installation of 27 O	hm Resistor	Rev 0 - Sep-09-09		
Chapter 24 - Electrica	l Power				
DAC1-24-01 (R)	Generator Lower A	ttaching Bolt Replacement	Rev 1 - Mar-03-10		
DAC1-24-03 (O)	G-35M Battery Opt	ion	Rev 2 - Apr-27-10		
DAC1-24-04 (R)	Generator Attachm	ent Bracket	Rev 3 - Jul-18-08		
DAC1-24-05 (O)	Installation of the B	C100-1 or the ODS-AGM28LMJ Battery on the Battery Shelf	Rev 2 - Mar-30-23		
DAC1-24-06 (O)	Installation of YTX2	24HL-BS Battery on Firewall	Rev 0 - Jan-14-04		
DAC1-24-07 (O)	Replacement of Ba	ttery/EPU Relay Contactor	Rev 0 - Nov-08-12		
DAC1-24-08 (O)	Installation of the e	xternal power unit (EPU) system	Rev 1 - Jan-23-20		
DAC1-24-09 (O)	Installation of the C	DDS-AGM28LMJ Battery on the Firewall	Rev 1 - Sep-18-23		
Chapter 25 - Equipme	ent and Furnishings				
DAC1-25-01 (R)	EBC502 to Artex E	LT Upgrade	Rev 6 - Jan-13-25		
DAC1-25-02 (R)	ME406 ELT Installa	ation on Reverse Panel	Rev 0 - Nov-23-10		
DAC1-25-03 (O)	Installation of Safet	ty Hammer, Type II	Rev 0 - Aug-19-11		
DAC1-25-04 (O)	ELT 1000 Retrofit		Rev 1 - Jan-13-25		
Chapter 27 - Flight Co	ontrols				
DAC1-27-01 (O)	Control Stick Eleva	tor Trim Installation	Rev 0 - Apr-26-01		
DAC1-27-02 (O/R)	Flap Actuator Bush	ing Retainers	Rev 1 - Feb-01-08		
DAC1-27-03 (M)	Inspection of Flap I	Bellcrank (Mandatory)	Rev 1 - May-13-19		
DAC1-27-04 (O)	Installation of Diam	ond Flap Control & Microswitch Tray	Rev 1 - Jan-10-20		
DAC1-27-05 (O)	Replacement of the	e flap actuator and installation of the flap resistor assembly	Rev 1 - Mar-13-25		
Chapter 28 - Fuel Sys	Chapter 28 - Fuel System				
DAC1-28-01 (O)	Type II Fuel System	n/Pump Retrofit	Rev 0 - Oct-08-98		
DAC1-28-02 (M)	2-Speed Electric Fu	uel Pump System	Rev 3 - Oct-27-99		

DOC # DA200-C1 13 March 2025 Page: 2 of 7



Diamond Aircraft Publications				
Doc. No.	Description	Full Listing	Status	
Chapter 30 - Ice and Rain Protection				
DAC1-30-02 (O)	Installation of a Hea	ated Pitot Static Probe	Rev 1 - Aug-25-22	
Chapter 31 - Indicating	g Systems			
DAC1-31-01 (O)	Removal of OAT/Cl	ock AA Battery	Rev 0 - Jun-29-17	
Chapter 32 - Landing	Gear			
DAC1-32-01 (O/R)	Nose Gear Shock S	Strut	Rev 0 - Feb-28-07	
DAC1-32-02 (O)	Optional Installation	of Extended Main Landing Gear Struts	Rev 0 - Jun-05-09	
DAC1-32-03 (R)	NLG Wheel and Fo	rk Installation Improvements	Rev 0 - Jul-15-11	
Chapter 33 - Lights				
DAC1-33-01 (O)	Recognition Lights		Rev 1 - Feb-21-00	
DAC1-33-02 (O)	Installation of Repla	acement Electro Luminescent (EL) Flood Light	Rev 1 - Aug-11-11	
DAC1-33-04 (O)	Installation of Backl	ighting on the Instrument Panel	Rev 2 - Feb-06-12	
DAC1-33-05 (R)	Installation of RFI P	rotected Lighting Voltage Regulator Assembly	Rev 0 - Feb-23-15	
DAC1-33-06 (O)	Installation of LED A	Anti-Collision and Position Light Assembly	Rev 3 - May-13-19	
DAC1-33-07 (O)	Installation of Dimm	ning Module	Rev 1 - Jan-10-20	
DAC1-33-08 (O)	Installation of LED I	anding and Taxi Lights	Rev 0 - Oct-13-22	
Chapter 34 - Navigation	on			
DAC1-34-02 (O)	Installation of Backu	up Artificial Horizon Indicator	Rev 2 - Jan-28-13	
DAC1-34-06 (R)	Garmin G500 Softw	vare Upgrade	Rev 0 - Mar-07-14	
DAC1-34-09 (O)	Garmin G500 Softw	vare Upgrade 006-B1076-63	Rev 0 - Jun-20-16	
DAC1-34-10 (M)	GTX345 and TAS60	05 Audio Lines	Rev 0 - Oct-13-20	
DAC1-34-11 (O)	Garmin GI 275 Insta	allation	Rev 0 - May-13-21	
DAC1-34-12 (O)	This service bulleting	addresses the installation of COMM 2.	Rev 0- Mar-05-24	
Chapter 52 - Doors				
DAC1-52-01 (O)	Canopy, Seal Repla	acement	Rev 0 - Jan-07-99	
DAC1-52-03 (R)	Canopy Lock Cover	r Plate Installation	Rev 1 - Aug-17-99	
Chapter 53 - Fuselage				
DAC1-53-01 (R)	Spar Bridge Gusset	t Reinforcement	Rev 3 - Sep-15-14	
Chapter 55 - Stabilizers				
DAC1-55-01A (A)	Horizontal Stabilize	r Attachment	Rev 3 - Mar-30-01	



Diamond Aircraft Publications						
Doc. No.	Description	Full Listing	Status			
Chapter 57 - Wings						
DAC1-57-01 (O)	Installation of Ailero	n Roller Guide Access Panels	Rev 1 - May-13-19			
Chapter 61 - Propeller						
DAC1-61-00A (A)	Spinner Rear Bulkh	ead Replacement	Rev 1 - Apr-02-01			
DAC1-61-01 (R)	Sensenich W69EK7	7-63 Propeller Installation	Rev 5 - Nov-29-19			
Chapter 71 - Power Pl	ant - General					
DAC1-71-01 (O)	Cowling Thermal Pr	rotection Shielding	Rev 1 - May-16-02			
DAC1-71-02	Engine Mount to Fir	rewall Washers	Rev 0 - Jan-19-04			
DAC1-71-03 (O)	Winterization Kit		Rev 0 - May-19-04			
DAC1-71-04 (O)	Enlarged Cowl Inlet	for Hot Weather Operation	Rev 0 - Jun-29-04			
Chapter 73 - Engine F	Chapter 73 - Engine Fuel and Controls					
DAC1-73-04 (O/R)	Engine Fuel Systen	n Conversion IO-240-B17B to IO-240-B3B	Rev 5 - Nov-26-10			
DAC1-73-05 (M)	Operating Limitation	ns with Altitude Compensating Fuel Systems	Rev 1 - Dec-14-07			
Chapter 74 - Engine Ignition						
DAC1-74-01 (R)	Ignition Harness Ro	puting	Rev 1 - Sep-19-14			
DAC1-74-02 (R)	Starting Vibrator Ba	ttery Installation	Rev 0 - Feb-18-00			
DAC1-74-03 (O)	Installation of Optio	nal Push-to-Start Ignition Switch	Rev 2 - Mar-09-11			
DAC1-74-04 (O)	Installation of the Yu	uasa NP1.2-12 starter vibrator battery and battery tray	Rev 0 - Sep-01-22			
Chapter 76 - Engine Controls						
DAC1-76-01 (R)	Mixture Cable Kinki	ng	Rev 1 - Jan-29-99			
DAC1-76-02 (R)	Mixture Cable Rout	ing - Reversed Panel	Rev 0 - Dec-03-03			
DAC1-76-03 (O)	Installation of Mixtu	re Cable for Altitude Compensating Fuel Pump	Rev 2 - Mar-06-06			
DAC1-76-04 (R)	Throttle Cable Firev	vall Feed-Thru	Rev 1 - Jan-28-10			
Chapter 77 - Engine Indicating						
DAC1-77-01 (O)	Installation of Impro	ved Indicating Systems	Rev 5 - Feb-09-23			
Chapter 79 - Engine O	il System					
DAC1-79-01 (O)	Power Plant Cooling	g	Rev 0 - Nov-09-99			
DAC1-79-02 (R)	Oil Filler Bracket Ins	stallation	Rev 0 - Apr-10-01			



Diamond Aircraft Publications			
Doc. No.	Description	Full Listing	Status
Miscellaneous			
DAC1-92-03	Mexican Import Requirements		Rev 0 - Feb-28-07
DAC1-92-07	Operation Limit Changes for EASA Member Countries		Rev 1 - Aug-09-12
DAC1-92-08	Installation of Illuminated Placards		Rev 0 - Aug-09-12

Service Information Letters			
SIL20C1-001	Service Information Letter to introduce Garmin Software Service Bulletin No.: 0943 Rev A.	Rev 0 - Jan-11-10	
SIL20C1-002	Service Information Letter to introduce Garmin Service Bulletin No. 0714 Rev. A.	Rev 0 - Mar-24-10	
SIL20C1-003	Service Information Letter to introduce AMM TR # 12-01, Scheduled Servicing for Brake Pedal Pivot	Rev 0 - May-12-10	
SIL20C1-004	Service Information Letter to introduce application of wheel bearing grease for wheel assemblies	Rev 0 - Aug-03-10	
SIL20C1-005	Service Information Letter to introduce new improved design of NLG fork assembly	Rev 0 - Oct-07-10	
SIL20C1-006	Service Information Letter for the inspection and maintenance of the throttle control arms installation	Rev 0 - Jan-22-13	
SIL20C1-007	Service Information Letter to introduce Garmin Service Advisory No. 1361	Rev 0 - Nov-20-13	
SIL20C1-008	Service Information Letter to introduce Andiar Service Alert GAS375-D	Rev 0 - Jan-22-13	
SIL20C1-009	Service Information Letter to introduce Slick Service Bulletin SB1-15A	Rev 1 - Jan-10-19	
SIL20C1-010	Service Information Letter to introduce United Instruments Service Bulletin No.13	Rev 0 - Apr-14-16	
SIL20C1-011	Service Information Letter regarding LPI of the NLG Strut	Rev 0 - Sep-19-18	
SIL20C1-012	Inspection of aircraft step assemblies	Rev 0 - May-07-19	
SIL20C1-013	Aircraft cleaning and disinfection recommendations	Rev 0 - May-21-20	
SIL20C1-014	Nose landing gear maintenance and inspections	Rev 0 - Jan-12-23	
SIL20C1-015	Garmin SB22071	Rev 0 - Aug-10-22	
SIL20C1-016	United Instruments Service Note No. 14	Rev 0 - Apr-13-23	

DOC # DA200-C1 13 March 2025 Page: 5 of 7



Continental Motors Publications

For the complete and up-to-date list of Continental Motors publications, refer to their website:

http://www.genuinecontinental.aero/PublicationList.aspx

Hoffmann Propeller Publications

For the complete and up-to-date list of Hoffmann Propeller publications, refer to their website:

http://www.hoffmann-prop.com/en/index.php

Sensenich Propeller Publications

For the complete and up-to-date list of Sensenich Propeller publications, refer to their website:

http://www.sensenich.com/support/documents



This list identifies documentation directly applicable to the safe operation and maintenance of the DA20-C1 aircraft. It is recommended that operators periodically verify that their documentation is at the correct issue/revision levels. The List of Applicable Publications (LOAP) will be updated at least quarterly, and sent to all registered subscribers. If you have not received your LOAP update for more than three months, contact Diamond Aircraft Customer Support at the following listed numbers immediately.

This list includes links to relevant vendor documents that Diamond Aircraft is aware of for the DA20-C1 aircraft. Vendor documents are not posted on the Diamond Aircraft website.

Other information pertaining to specific components (e.g. avionics) should be obtained directly from the vendor or manufacturer.

For publication revision and subscription service, please contact the following:

Diamond Aircraft Industries

North America, Australia, South Africa:

Diamond Aircraft Industries Inc.

Customer Support 1560 Crumlin Sideroad London, ON, Canada

N5V 1S2

Phone: 519-457-4041

Europe, Other:

Diamond Aircraft Industries GmbH.

Customer Support N.A. Otto-Strasse 5 A-2700 Wiener Neustadt

Austria

Phone: 011-43-2622-26700

Teledyne Continental Motors

Contact TCM directly for publication information.

North America:

Teledyne Continental Motors

P.O. Box 90

Mobile, Alabama, USA

36601

Phone: 334-438-3411

Sensenich Propeller Manufacturing Company

Contact Sensenich directly for publication information.

North America:

Sensenich Wood Propeller Company

2008 Wood Court Plant City, Florida

33567

Phone: 813-752-3711

Hoffmann Propeller

North America, Australia, South Africa: **Europe, Other:**

Authorized Distributor Hoffmann Propeller GmbH. & Co.

Diamond Aircraft Industries Inc. **Customer Support Customer Support** Kupferlingstr. 9 1560 Crumlin Sideroad D-83022 Rosenheim London, ON, Canada

N5V 1S2

Phone: 519-457-4041

Germany

Phone: 011-49-8031-1878-0

NOTE: this document is re-issued at each revision.