

| Diamond Aircraft Publications  |                                                 |                      |                     |
|--------------------------------|-------------------------------------------------|----------------------|---------------------|
| Doc. No.                       | Description                                     | Revision 111 Updates | Status              |
| DA201-C1 AMM-TR-MAM-22-0035    | Inspection of Flap Bellcrank                    |                      | Rev 0 - Aug-14-25   |
| Diamond Aircraft Publications  |                                                 |                      |                     |
| Doc. No.                       | Description                                     | Full Listing         | Status              |
| <b><u>Aircraft Manuals</u></b> |                                                 |                      |                     |
| DA200-C1                       | List of Applicable Publications (this document) |                      | Rev 111 - Aug-26-25 |
| DA201-C1                       | Aircraft Maintenance Manual                     |                      | Rev 25- Mar-14-23   |
| DA201-C1 TR-MAM-22-0016        | Flap Actuator Motor                             |                      | Rev 0 - Dec-16-24   |
| DA201-C1 TR-MOD0333            | Installation of the Artex ELT 1000              |                      | Rev 0 - Jan-15-25   |
| DA201-C1 AMM-TR-25-10          | Fuel Line Torques                               |                      | Rev 0 - Jun-18-25   |
| DA201-C1 AMM-TR-MAM-22-0035    | Inspection of Flap Bellcrank                    |                      | Rev 0 - Aug-14-25   |
| DA202-C1                       | Airplane Flight Manual (English Day/Night VFR)  |                      | Rev 29 - Jun-30-21  |
| DA202-C1 TR# 23-01             | Amerex 337TS Fire Extinguisher                  |                      | Rev 0 - Apr-01-23   |
| DA203-C1                       | Illustrated Parts Catalogue                     |                      | Rev 12 - Aug-27-21  |
| DA203-C1                       | Illustrated Parts Catalogue                     |                      | Rev 13- Apr-17-23   |

| Diamond Aircraft Publications                                                                   |                                                                                 |              |                   |
|-------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------|--------------|-------------------|
| Doc. No.                                                                                        | Description                                                                     | Full Listing | Status            |
| <b><u>Service Bulletins</u></b> (A) = Alert, (M) = Mandatory, (O) = Optional, (R) = Recommended |                                                                                 |              |                   |
| <b>Chapter 11 - Placards and Markings</b>                                                       |                                                                                 |              |                   |
| DAC1-11-01 (R)                                                                                  | Chinese Placards and Markings                                                   |              | Rev 3 - Sep-29-14 |
| <b>Chapter 23 - Communications</b>                                                              |                                                                                 |              |                   |
| DAC1-23-01 (R)                                                                                  | GMA 340 Isolation Diodes                                                        |              | Rev 0 - Dec-08-04 |
| DAC1-23-50 (O)                                                                                  | Installation of 27 Ohm Resistor                                                 |              | Rev 0 - Sep-09-09 |
| <b>Chapter 24 - Electrical Power</b>                                                            |                                                                                 |              |                   |
| DAC1-24-01 (R)                                                                                  | Generator Lower Attaching Bolt Replacement                                      |              | Rev 1 - Mar-03-10 |
| DAC1-24-03 (O)                                                                                  | G-35M Battery Option                                                            |              | Rev 2 - Apr-27-10 |
| DAC1-24-04 (R)                                                                                  | Generator Attachment Bracket                                                    |              | Rev 3 - Jul-18-08 |
| DAC1-24-05 (O)                                                                                  | Installation of the BC100-1 or the ODS-AGM28LMJ Battery on the Battery Shelf    |              | Rev 2 - Mar-30-23 |
| DAC1-24-06 (O)                                                                                  | Installation of YTX24HL-BS Battery on Firewall                                  |              | Rev 0 - Jan-14-04 |
| DAC1-24-07 (O)                                                                                  | Replacement of Battery/EPU Relay Contactor                                      |              | Rev 0 - Nov-08-12 |
| DAC1-24-08 (O)                                                                                  | Installation of the external power unit (EPU) system                            |              | Rev 1 - Jan-23-20 |
| DAC1-24-09 (O)                                                                                  | Installation of the ODS-AGM28LMJ Battery on the Firewall                        |              | Rev 1 - Sep-18-23 |
| <b>Chapter 25 - Equipment and Furnishings</b>                                                   |                                                                                 |              |                   |
| DAC1-25-01 (R)                                                                                  | EBC502 to Artex ELT Upgrade                                                     |              | Rev 6 - Jan-13-25 |
| DAC1-25-02 (R)                                                                                  | ME406 ELT Installation on Reverse Panel                                         |              | Rev 0 - Nov-23-10 |
| DAC1-25-03 (O)                                                                                  | Installation of Safety Hammer, Type II                                          |              | Rev 0 - Aug-19-11 |
| DAC1-25-04 (O)                                                                                  | ELT 1000 Retrofit                                                               |              | Rev 1 - Jan-13-25 |
| <b>Chapter 27 - Flight Controls</b>                                                             |                                                                                 |              |                   |
| DAC1-27-01 (O)                                                                                  | Control Stick Elevator Trim Installation                                        |              | Rev 0 - Apr-26-01 |
| DAC1-27-02 (O/R)                                                                                | Flap Actuator Bushing Retainers                                                 |              | Rev 1 - Feb-01-08 |
| DAC1-27-03 (M)                                                                                  | Inspection of Flap Bellcrank (Mandatory)                                        |              | Rev 1 - May-13-19 |
| DAC1-27-04 (O)                                                                                  | Installation of Diamond Flap Control & Microswitch Tray                         |              | Rev 1 - Jan-10-20 |
| DAC1-27-05 (O)                                                                                  | Replacement of the flap actuator and installation of the flap resistor assembly |              | Rev 1 - Mar-13-25 |
| <b>Chapter 28 - Fuel System</b>                                                                 |                                                                                 |              |                   |
| DAC1-28-01 (O)                                                                                  | Type II Fuel System/Pump Retrofit                                               |              | Rev 0 - Oct-08-98 |
| DAC1-28-02 (M)                                                                                  | 2-Speed Electric Fuel Pump System                                               |              | Rev 3 - Oct-27-99 |

| Diamond Aircraft Publications               |                                                                   |              |                   |
|---------------------------------------------|-------------------------------------------------------------------|--------------|-------------------|
| Doc. No.                                    | Description                                                       | Full Listing | Status            |
| <b>Chapter 30 - Ice and Rain Protection</b> |                                                                   |              |                   |
| DAC1-30-02 (O)                              | Installation of a Heated Pitot Static Probe                       |              | Rev 1 - Aug-25-22 |
| <b>Chapter 31 - Indicating Systems</b>      |                                                                   |              |                   |
| DAC1-31-01 (O)                              | Removal of OAT/Clock AA Battery                                   |              | Rev 0 - Jun-29-17 |
| <b>Chapter 32 - Landing Gear</b>            |                                                                   |              |                   |
| DAC1-32-01 (O/R)                            | Nose Gear Shock Strut                                             |              | Rev 0 - Feb-28-07 |
| DAC1-32-02 (O)                              | Optional Installation of Extended Main Landing Gear Struts        |              | Rev 0 - Jun-05-09 |
| DAC1-32-03 (R)                              | NLG Wheel and Fork Installation Improvements                      |              | Rev 0 - Jul-15-11 |
| <b>Chapter 33 - Lights</b>                  |                                                                   |              |                   |
| DAC1-33-01 (O)                              | Recognition Lights                                                |              | Rev 1 - Feb-21-00 |
| DAC1-33-02 (O)                              | Installation of Replacement Electro Luminescent (EL) Flood Light  |              | Rev 1 - Aug-11-11 |
| DAC1-33-04 (O)                              | Installation of Backlighting on the Instrument Panel              |              | Rev 2 - Feb-06-12 |
| DAC1-33-05 (R)                              | Installation of RFI Protected Lighting Voltage Regulator Assembly |              | Rev 0 - Feb-23-15 |
| DAC1-33-06 (O)                              | Installation of LED Anti-Collision and Position Light Assembly    |              | Rev 3 - May-13-19 |
| DAC1-33-07 (O)                              | Installation of Dimming Module                                    |              | Rev 1 - Jan-10-20 |
| DAC1-33-08 (O)                              | Installation of LED Landing and Taxi Lights                       |              | Rev 0 - Oct-13-22 |
| <b>Chapter 34 - Navigation</b>              |                                                                   |              |                   |
| DAC1-34-02 (O)                              | Installation of Backup Artificial Horizon Indicator               |              | Rev 2 - Jan-28-13 |
| DAC1-34-06 (R)                              | Garmin G500 Software Upgrade                                      |              | Rev 0 - Mar-07-14 |
| DAC1-34-09 (O)                              | Garmin G500 Software Upgrade 006-B1076-63                         |              | Rev 0 - Jun-20-16 |
| DAC1-34-10 (M)                              | GTX345 and TAS605 Audio Lines                                     |              | Rev 0 - Oct-13-20 |
| DAC1-34-11 (O)                              | Garmin GI 275 Installation                                        |              | Rev 0 - May-13-21 |
| DAC1-34-12 (O)                              | This service bulletin addresses the installation of COMM 2.       |              | Rev 0- Mar-05-24  |
| <b>Chapter 52 - Doors</b>                   |                                                                   |              |                   |
| DAC1-52-01 (O)                              | Canopy, Seal Replacement                                          |              | Rev 0 - Jan-07-99 |
| DAC1-52-03 (R)                              | Canopy Lock Cover Plate Installation                              |              | Rev 1 - Aug-17-99 |
| <b>Chapter 53 - Fuselage</b>                |                                                                   |              |                   |
| DAC1-53-01 (R)                              | Spar Bridge Gusset Reinforcement                                  |              | Rev 3 - Sep-15-14 |
| <b>Chapter 55 - Stabilizers</b>             |                                                                   |              |                   |
| DAC1-55-01A (A)                             | Horizontal Stabilizer Attachment                                  |              | Rev 3 - Mar-30-01 |

| Diamond Aircraft Publications                |                                                                              |              |                   |
|----------------------------------------------|------------------------------------------------------------------------------|--------------|-------------------|
| Doc. No.                                     | Description                                                                  | Full Listing | Status            |
| <b>Chapter 57 - Wings</b>                    |                                                                              |              |                   |
| DAC1-57-01 (O)                               | Installation of Aileron Roller Guide Access Panels                           |              | Rev 1 - May-13-19 |
| <b>Chapter 61 - Propellers</b>               |                                                                              |              |                   |
| DAC1-61-00A (A)                              | Spinner Rear Bulkhead Replacement                                            |              | Rev 1 - Apr-02-01 |
| DAC1-61-01 (R)                               | Sensenich W69EK7-63 Propeller Installation                                   |              | Rev 5 - Nov-29-19 |
| <b>Chapter 71 - Power Plant - General</b>    |                                                                              |              |                   |
| DAC1-71-01 (O)                               | Cowling Thermal Protection Shielding                                         |              | Rev 1 - May-16-02 |
| DAC1-71-02                                   | Engine Mount to Firewall Washers                                             |              | Rev 0 - Jan-19-04 |
| DAC1-71-03 (O)                               | Winterization Kit                                                            |              | Rev 0 - May-19-04 |
| DAC1-71-04 (O)                               | Enlarged Cowl Inlet for Hot Weather Operation                                |              | Rev 0 - Jun-29-04 |
| <b>Chapter 73 - Engine Fuel and Controls</b> |                                                                              |              |                   |
| DAC1-73-04 (O/R)                             | Engine Fuel System Conversion IO-240-B17B to IO-240-B3B                      |              | Rev 5 - Nov-26-10 |
| DAC1-73-05 (M)                               | Operating Limitations with Altitude Compensating Fuel Systems                |              | Rev 1 - Dec-14-07 |
| <b>Chapter 74 - Engine Ignition</b>          |                                                                              |              |                   |
| DAC1-74-01 (R)                               | Ignition Harness Routing                                                     |              | Rev 1 - Sep-19-14 |
| DAC1-74-02 (R)                               | Starting Vibrator Battery Installation                                       |              | Rev 0 - Feb-18-00 |
| DAC1-74-03 (O)                               | Installation of Optional Push-to-Start Ignition Switch                       |              | Rev 2 - Mar-09-11 |
| DAC1-74-04 (O)                               | Installation of the Yuasa NP1.2-12 starter vibrator battery and battery tray |              | Rev 0 - Sep-01-22 |
| <b>Chapter 76 - Engine Controls</b>          |                                                                              |              |                   |
| DAC1-76-01 (R)                               | Mixture Cable Kinking                                                        |              | Rev 1 - Jan-29-99 |
| DAC1-76-02 (R)                               | Mixture Cable Routing - Reversed Panel                                       |              | Rev 0 - Dec-03-03 |
| DAC1-76-03 (O)                               | Installation of Mixture Cable for Altitude Compensating Fuel Pump            |              | Rev 2 - Mar-06-06 |
| DAC1-76-04 (R)                               | Throttle Cable Firewall Feed-Thru                                            |              | Rev 1 - Jan-28-10 |
| <b>Chapter 77 - Engine Indicating</b>        |                                                                              |              |                   |
| DAC1-77-01 (O)                               | Installation of Improved Indicating Systems                                  |              | Rev 5 - Feb-09-23 |
| <b>Chapter 79 - Engine Oil System</b>        |                                                                              |              |                   |
| DAC1-79-01 (O)                               | Power Plant Cooling                                                          |              | Rev 0 - Nov-09-99 |
| DAC1-79-02 (R)                               | Oil Filler Bracket Installation                                              |              | Rev 0 - Apr-10-01 |

# DA20-C1

## List of Applicable Publications

| Diamond Aircraft Publications             |                                                                                                         |              |                   |
|-------------------------------------------|---------------------------------------------------------------------------------------------------------|--------------|-------------------|
| Doc. No.                                  | Description                                                                                             | Full Listing | Status            |
| <b>Miscellaneous</b>                      |                                                                                                         |              |                   |
| DAC1-92-03                                | Mexican Import Requirements                                                                             |              | Rev 0 - Feb-28-07 |
| DAC1-92-07                                | Operation Limit Changes for EASA Member Countries                                                       |              | Rev 1 - Aug-09-12 |
| DAC1-92-08                                | Installation of Illuminated Placards                                                                    |              | Rev 0 - Aug-09-12 |
| <b><u>Service Information Letters</u></b> |                                                                                                         |              |                   |
| SIL20C1-001                               | Service Information Letter to introduce Garmin Software Service Bulletin No.: 0943 Rev A.               |              | Rev 0 - Jan-11-10 |
| SIL20C1-002                               | Service Information Letter to introduce Garmin Service Bulletin No. 0714 Rev. A.                        |              | Rev 0 - Mar-24-10 |
| SIL20C1-003                               | Service Information Letter to introduce AMM TR # 12-01, Scheduled Servicing for Brake Pedal Pivot       |              | Rev 0 - May-12-10 |
| SIL20C1-004                               | Service Information Letter to introduce application of wheel bearing grease for wheel assemblies        |              | Rev 0 - Aug-03-10 |
| SIL20C1-005                               | Service Information Letter to introduce new improved design of NLG fork assembly                        |              | Rev 0 - Oct-07-10 |
| SIL20C1-006                               | Service Information Letter for the inspection and maintenance of the throttle control arms installation |              | Rev 0 - Jan-22-13 |
| SIL20C1-007                               | Service Information Letter to introduce Garmin Service Advisory No. 1361                                |              | Rev 0 - Nov-20-13 |
| SIL20C1-008                               | Service Information Letter to introduce Andiar Service Alert GAS375-D                                   |              | Rev 0 - Jan-22-13 |
| SIL20C1-009                               | Service Information Letter to introduce Slick Service Bulletin SB1-15A                                  |              | Rev 1 - Jan-10-19 |
| SIL20C1-010                               | Service Information Letter to introduce United Instruments Service Bulletin No.13                       |              | Rev 0 - Apr-14-16 |
| SIL20C1-011                               | Service Information Letter regarding LPI of the NLG Strut                                               |              | Rev 0 - Sep-19-18 |
| SIL20C1-012                               | Inspection of aircraft step assemblies                                                                  |              | Rev 0 - May-07-19 |
| SIL20C1-013                               | Aircraft cleaning and disinfection recommendations                                                      |              | Rev 0 - May-21-20 |
| SIL20C1-014                               | Nose landing gear maintenance and inspections                                                           |              | Rev 0 - Jan-12-23 |
| SIL20C1-015                               | Garmin SB22071                                                                                          |              | Rev 0 - Aug-10-22 |
| SIL20C1-016                               | United Instruments Service Note No. 14                                                                  |              | Rev 0 - Apr-13-23 |

**Continental Motors Publications**

For the complete and up-to-date list of Continental Motors publications, refer to their website:

<http://www.genuinecontinental.aero/PublicationList.aspx>

**Hoffmann Propeller Publications**

For the complete and up-to-date list of Hoffmann Propeller publications, refer to their website:

<http://www.hoffmann-prop.com/en/index.php>

**Sensenich Propeller Publications**

For the complete and up-to-date list of Sensenich Propeller publications, refer to their website:

<http://www.sensenich.com/support/documents>



## DA20-C1 List of Applicable Publications

This list identifies documentation directly applicable to the safe operation and maintenance of the DA20-C1 aircraft. It is recommended that operators periodically verify that their documentation is at the correct issue/revision levels. The List of Applicable Publications (LOAP) will be updated at least quarterly, and sent to all registered subscribers. If you have not received your LOAP update for more than three months, contact Diamond Aircraft Customer Support at the following listed numbers immediately.

This list includes links to relevant vendor documents that Diamond Aircraft is aware of for the DA20-C1 aircraft. Vendor documents are not posted on the Diamond Aircraft website.

Other information pertaining to specific components (e.g. avionics) should be obtained directly from the vendor or manufacturer.

For publication revision and subscription service, please contact the following:

| Diamond Aircraft Industries                                                                                                                                                                                       |                                                                                                                                                                        |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <b>North America, Australia, South Africa:</b><br>Diamond Aircraft Industries Inc.<br>Customer Support<br>1560 Crumlin Sideroad<br>London, ON, Canada<br>N5V 1S2<br>Phone: 519-457-4041                           | <b>Europe, Other:</b><br>Diamond Aircraft Industries GmbH.<br>Customer Support<br>N.A. Otto-Strasse 5<br>A-2700 Wiener Neustadt<br>Austria<br>Phone: 011-43-2622-26700 |
| Teledyne Continental Motors                                                                                                                                                                                       |                                                                                                                                                                        |
| Contact TCM directly for publication information.<br><b>North America:</b><br>Teledyne Continental Motors<br>P.O. Box 90<br>Mobile, Alabama, USA<br>36601<br>Phone: 334-438-3411                                  |                                                                                                                                                                        |
| Sensenich Propeller Manufacturing Company                                                                                                                                                                         |                                                                                                                                                                        |
| Contact Sensenich directly for publication information.<br><b>North America:</b><br>Sensenich Wood Propeller Company<br>2008 Wood Court<br>Plant City, Florida<br>33567<br>Phone: 813-752-3711                    |                                                                                                                                                                        |
| Hoffmann Propeller                                                                                                                                                                                                |                                                                                                                                                                        |
| <b>North America, Australia, South Africa:</b><br>Authorized Distributor<br>Diamond Aircraft Industries Inc.<br>Customer Support<br>1560 Crumlin Sideroad<br>London, ON, Canada<br>N5V 1S2<br>Phone: 519-457-4041 | <b>Europe, Other:</b><br>Hoffmann Propeller GmbH. & Co.<br>Customer Support<br>Kupferlingstr. 9<br>D-83022 Rosenheim<br>Germany<br>Phone: 011-49-8031-1878-0           |