

Diamond Aircraft Publications						
Doc. No.	Description	Revision 25 Updates	Status			
D42L-IPC-003	Illustrated Parts	Catalogue	Rev 5 - 15-Oct-21			

NOTE: The revision to the IPC is a full release. There is no incremental revision provided.

Diamond Aircraft Publications					
Doc. No.	Description	Full Listing	Status		
Aircraft Manuals					
D42L-LOAP	List of Applicable Pu	ublications - (this document)	Rev 26 - 15-Oct-21		
D42L-AMM-001	Aircraft Maintenance Manual		Rev 5 - 15-Oct-12		
D42L-AMM-001 TR 13-01	AMM Temporary Revision 13-01 Inclusion of NG Airframes		Rev 0 - 21-Mar-13		
D42L-AFM-002	Airplane Flight Manual		Rev 7 - 23-May-12		
D42L-AFM-002	Airplane Flight Manual - Incremental Revision		Rev 7 - 23-May-12		
	. ,	Revision 10-01 has been removed from the website. been incorporated into Revision 7 of the AFM.			
DA42L-AFM-002_S1	AFM Supplement 1	- Nose FWD Bulkhead Ballast Installation	Rev 1 - 23-May-12		
DA42L-AFM-002_S2	AFM Supplement 2	- Lighted Fuel Pump Switch	Rev 0 - 10-Dec-09		
DA42L-AFM-002_S3	AFM Supplement 3	- Winterization Kit	Rev 0 - 03-Dec-10		
DA42L-AFM-002_S4	AFM Supplement 4	- WAAS Operations	Rev 1 - 23-May-12		
DA42L-AFM-002_S5	AFM Supplement 5	- G1000 Synthetic Vision Technology	Rev 0 - 28-Feb-12		
DA42L-AFM-002_S6	AFM Supplement 6	- Terrain Awareness and Warning System - Class B (TAWS-B)	Rev 0 - 23-Jul-13		
DA42L-AFM-002_S7	AFM Supplement 7	- Garmin GTX 33 ES with ADS-B Out	Rev 0 - 10-Apr-16		
DA42L-AFM-002 TR 14-01	AFM Temporary Rev	vision 14-01 - Lycoming Engines on the DA42NG	Rev 0 - 24-Feb-14		
DA42L-AFM-002 TR 15-01	AFM Temporary Rev	vision 15-01 - Normal Take Off Procedure	Rev 0 - 15-Apr-15		
D42L-IPC-003	Illustrated Parts Cat	alogue	Rev 5 - 15-Oct-21		



Diamond Aircraft Publications					
Doc. No.	Description	Full Listing	Status		
Service Bulletins	(A) = Alert, (M) = Mandatory, (O) = Optional, (R) = Recommended				
Chapter 25 - Equipment and Furnishings					
D42L-25-01 (O)	DA42 L360 Ballast	Rev 0 - 02-Dec-09			
Chapter 27 - Flight C	ontrols				
D42L-27-01 (O)	Modification to the	Rev 0 - 22-Oct-09			
Chapter 28 - Fuel System					
D42L-28-01 (O)	Lighted Fuel Pump Switch		Rev 0 - 10-Dec-09		
D42L-28-02 (M)	Fuel Transfer Pum	Rev 0 - 30-May-12			
Chapter 32 - Landing	g Gear				
D42L-32-01 (R)	CHECK GEAR Ani	nunciation	Rev 1 - 10-May-21		
Chapter 34 - Navigati	ion				
D42L-34-01 (O)	G1000 System Software Version 1054.02 Update for the D42L 360 Aircraft		Rev 0 - 15-Aug-11		
D42L-34-02 (O)	Availability of the G	G1000 Synthetic Vision & Pathways Option - Garmin SB 1039 A	Rev 0 - 26-Sep-12		
D42L-34-03 (O)	ADF System Impro	ovements	Rev 2 - 05-Oct-12		
D42L-34-04 (O)	G1000 System So	ftware Version 1054.03 Update for DA42 L360 Aircraft	Rev 1 - 11-Oct-12		
D42L-34-05 (O)	Installation of Garr	nin Wide Area Augmentation	Rev 0 - 13-Mar-13		
D42L-34-07 (O)	GTX 33ES Installa	tion	Rev 0 - 06-Jun-16		
D42L-34-08 (O)	G1000 System So	ftware Version 1054.04 Update for DA42 L360 Aircraft	Rev 0 - 11-Dec-17		
Chapter 79 - Engine Oil					
D42L-79-01 (O)	Installation of an E	xternal Oil Cooler Scoop	Rev 3 - 07-Feb-12		

NOTE: There are also Service Bulletins released for the DA42 TDI that affect DA42 L360 aircraft. This can be determined by the range of Serial Numbers affected. The link below will bring you to the complete list of DA42 TDI Service Bulletins.

http://support.diamond-air.at/da42_sb+M52087573ab0.html



Diamond Aircraft Publications						
Doc. No.	Description	Full Listing	Status			
Service Information Letters						
SILD42L-001	•	ange Installation Hardware Inspection on Lycoming Engines using 2 inch bolts and nuts of P/N C-060 and C-061	Rev 0 - 23-Aug-10			
SILD42L-004	To release the FA	A issued Airworthiness Directive 2011-26-04.	Rev 0 - 05-Jan-12			
SILD42L-005	To release the EA	SA Airworthiness Directive No. 2012-0174.	Rev 0 - 12-Sep-12			
SILD42L-006	To release the FA	A Airworthiness Directive No. 2012-17-07.	RESCINDED			
SILD42L-007	To release the FA	A Airworthiness Directive No. 2012-17-07.	Rev 0 - 13-Sep-12			
SILD42L-008	Garmin Service Ad	dvisory No. 1309.	Rev 0 - 13-Jun-13			
SILD42L-009	Slick SB No. SB1- gear	15A - Potential decreased service life of Slick magneto distributor	Rev 1 - 10-Jan-19			
SILD42L-010	Garmin G1000 so	ftware version 006-B1054-04	Rev 0 - 02-Sep-16			
SILD42L-011	FAA AD 2020-25-1	12 - replacement of SAP crankshaft assemblies	Rev 0 - 15-Jan-21			

Textron Lycoming Publications

For the complete and up-to-date list of Textron Lycoming publications refer to their website:

https://www.lycoming.com/contact/knowledge-base/publications

mt-Propeller Publications

For the complete and up-to-date list of mt-Propeller publications refer to their website:

http://www.mt-propeller.com/index.htm



This list identifies documentation directly applicable to the safe operation and maintenance of the DA42 L360 Aircraft. It is recommended that operators periodically verify that their documentation is at the correct issue/revision level. The List of Applicable Publications (LOAP) will be updated at least quarterly, and sent to all registered subscribers. If you have not received your LOAP update for more than three months, contact Diamond Aircraft Customer Support at the following listed numbers immediately.

This list includes links to relevant vendor sites/documents that Diamond Aircraft is aware of for the DA42 L360 aircraft. Vendor documents are not posted on the Diamond Aircraft Website.

Other information pertaining to specific components (e.g. avionics) should be obtained directly from the vendor or manufacturer.

For publication revision and subscription service, please contact the following:

Diamond Aircraft Industries

North America, Australia, South Africa: Europe, Other:

Diamond Aircraft Industries Inc.

Diamond Aircraft Industries GmbH.

Customer SupportCustomer Support1560 Crumlin SideroadN.A. Otto-Strasse 5London, ON, CanadaA-2700 Wiener Neustadt

N5V 1S2 Austria

Phone: 519-457-4041 Fax: 519-457-4045 Phone: 011-43-2622-26700 Fax: 011-43-2622-26780

Textron Lycoming

Contact Textron Lycoming directly for publication information.

North America:

Textron Lycoming 652 Oliver Street Williamsport, PA, USA

17701

Phone: 570-523-6181

mt-Propeller

Contact mt-propeller directly for publication information.

North America and Europe:

mt-propeller

Airport Straubing Wallmuhle

D-94348 Atting

Germany

Phone: +49-(9429)-9409-0 Internet: www.mt-propeller.com

Garmin International

Contact Garmin International Inc. directly for publication information.

North America:

Garmin International, Inc. 1200 East 151st Street Olathe, Kansas, USA

66062

Phone: 913-397-8200