



# DA42 L360

## List of Applicable Publications

Diamond Aircraft Publications			
Doc. No.	Description	Revision 27 Updates	Status
DA42L-AFM-002 TR 24-01	AFM Temporary Revision 24-01 - Door Latching and Locking		Rev 0 - 16-Dec-24

Diamond Aircraft Publications			
Doc. No.	Description	Full Listing	Status
<b><u>Aircraft Manuals</u></b>			
D42L-LOAP	List of Applicable Publications - (this document)		Rev 27 - 10-Mar-25
D42L-AMM-001	Aircraft Maintenance Manual		Rev 5 - 15-Oct-12
D42L-AMM-001 TR 13-01	AMM Temporary Revision 13-01 Inclusion of NG Airframes		Rev 0 - 21-Mar-13
D42L-AFM-002	Airplane Flight Manual		Rev 7 - 23-May-12
D42L-AFM-002	Airplane Flight Manual - Incremental Revision		Rev 7 - 23-May-12
NOTE: Temporary Revision 10-01 has been removed from the website. The TR has been incorporated into Revision 7 of the AFM.			
DA42L-AFM-002_S1	AFM Supplement 1 - Nose FWD Bulkhead Ballast Installation		Rev 1 - 23-May-12
DA42L-AFM-002_S2	AFM Supplement 2 - Lighted Fuel Pump Switch		Rev 0 - 10-Dec-09
DA42L-AFM-002_S3	AFM Supplement 3 - Winterization Kit		Rev 0 - 03-Dec-10
DA42L-AFM-002_S4	AFM Supplement 4 - WAAS Operations		Rev 1 - 23-May-12
DA42L-AFM-002_S5	AFM Supplement 5 - G1000 Synthetic Vision Technology		Rev 0 - 28-Feb-12
DA42L-AFM-002_S6	AFM Supplement 6 - Terrain Awareness and Warning System - Class B (TAWS-B)		Rev 0 - 23-Jul-13
DA42L-AFM-002_S7	AFM Supplement 7 - Garmin GTX 33 ES with ADS-B Out		Rev 0 - 10-Apr-16
DA42L-AFM-002 TR 14-01	AFM Temporary Revision 14-01 - Lycoming Engines on the DA42NG		Rev 0 - 24-Feb-14
DA42L-AFM-002 TR 15-01	AFM Temporary Revision 15-01 - Normal Take Off Procedure		Rev 0 - 15-Apr-15
DA42L-AFM-002 TR 24-01	AFM Temporary Revision 24-01 - Door Latching and Locking		Rev 0 - 16-Dec-24
D42L-IPC-003	Illustrated Parts Catalogue		Rev 5 - 15-Oct-21



# DA42 L360

## List of Applicable Publications

Diamond Aircraft Publications			
Doc. No.	Description	Full Listing	Status
<b>Service Bulletins</b> (A) = Alert, (M) = Mandatory, (O) = Optional, (R) = Recommended			
<b>Chapter 25 - Equipment and Furnishings</b>			
D42L-25-01 (O)	DA42 L360 Ballast Installation		Rev 0 - 02-Dec-09
<b>Chapter 27 - Flight Controls</b>			
D42L-27-01 (O)	Modification to the Variable Elevator Stop System		Rev 0 - 22-Oct-09
<b>Chapter 28 - Fuel System</b>			
D42L-28-01 (O)	Lighted Fuel Pump Switch		Rev 0 - 10-Dec-09
D42L-28-02 (M)	Fuel Transfer Pump Circuit Breaker Change		Rev 0 - 30-May-12
<b>Chapter 32 - Landing Gear</b>			
D42L-32-01 (R)	CHECK GEAR Annunciation		Rev 1 - 10-May-21
<b>Chapter 34 - Navigation</b>			
D42L-34-01 (O)	G1000 System Software Version 1054.02 Update for the D42L 360 Aircraft		Rev 0 - 15-Aug-11
D42L-34-02 (O)	Availability of the G1000 Synthetic Vision & Pathways Option - Garmin SB 1039 A		Rev 0 - 26-Sep-12
D42L-34-03 (O)	ADF System Improvements		Rev 2 - 05-Oct-12
D42L-34-04 (O)	G1000 System Software Version 1054.03 Update for DA42 L360 Aircraft		Rev 1 - 11-Oct-12
D42L-34-05 (O)	Installation of Garmin Wide Area Augmentation		Rev 0 - 13-Mar-13
D42L-34-07 (O)	GTX 33ES Installation		Rev 0 - 06-Jun-16
D42L-34-08 (O)	G1000 System Software Version 1054.04 Update for DA42 L360 Aircraft		Rev 0 - 11-Dec-17
<b>Chapter 79 - Engine Oil</b>			
D42L-79-01 (O)	Installation of an External Oil Cooler Scoop		Rev 3 - 07-Feb-12

NOTE: There are also Service Bulletins released for the DA42 TDI that affect DA42 L360 aircraft. This can be determined by the range of Serial Numbers affected. The link below will bring you to the complete list of DA42 TDI Service Bulletins.

[http://support.diamond-air.at/da42\\_sb+M52087573ab0.html](http://support.diamond-air.at/da42_sb+M52087573ab0.html)

**Diamond Aircraft Publications**

Doc. No.	Description	Full Listing	Status
<b><u>Service Information Letters</u></b>			
SILD42L-001	Mt-Propeller -B Flange Installation Hardware Inspection on Lycoming Engines using SAE No. 2 mod 1/2 inch bolts and nuts of P/N C-060 and C-061		Rev 0 - 23-Aug-10
SILD42L-004	To release the FAA issued Airworthiness Directive 2011-26-04.		Rev 0 - 05-Jan-12
SILD42L-005	To release the EASA Airworthiness Directive No. 2012-0174.		Rev 0 - 12-Sep-12
<del>SILD42L-006</del>	<del>To release the FAA Airworthiness Directive No. 2012-17-07.</del>		RESCINDED
SILD42L-007	To release the FAA Airworthiness Directive No. 2012-17-07.		Rev 0 - 13-Sep-12
SILD42L-008	Garmin Service Advisory No. 1309.		Rev 0 - 13-Jun-13
SILD42L-009	Slick SB No. SB1-15A - Potential decreased service life of Slick magneto distributor gear		Rev 1 - 10-Jan-19
SILD42L-010	Garmin G1000 software version 006-B1054-04		Rev 0 - 02-Sep-16
SILD42L-011	FAA AD 2020-25-12 - replacement of SAP crankshaft assemblies		Rev 0 - 15-Jan-21

**Textron Lycoming Publications**

For the complete and up-to-date list of Textron Lycoming publications refer to their website:

<https://www.lycoming.com/contact/knowledge-base/publications>

**mt-Propeller Publications**

For the complete and up-to-date list of mt-Propeller publications refer to their website:

<http://www.mt-propeller.com/index.htm>



# DA42 L360

## List of Applicable Publications

This list identifies documentation directly applicable to the safe operation and maintenance of the DA42 L360 Aircraft. It is recommended that operators periodically verify that their documentation is at the correct issue/revision level. The List of Applicable Publications (LOAP) will be updated at least quarterly, and sent to all registered subscribers. If you have not received your LOAP update for more than three months, contact Diamond Aircraft Customer Support at the following listed numbers immediately.

This list includes links to relevant vendor sites/documents that Diamond Aircraft is aware of for the DA42 L360 aircraft. Vendor documents are not posted on the Diamond Aircraft Website.

Other information pertaining to specific components (e.g. avionics) should be obtained directly from the vendor or manufacturer.

For publication revision and subscription service, please contact the following:

### Diamond Aircraft Industries

#### North America, Australia, South Africa:

Diamond Aircraft Industries Inc.  
Customer Support  
1560 Crumlin Sideroad  
London, ON, Canada  
N5V 1S2  
Phone: 519-457-4041 Fax: 519-457-4045

#### Europe, Other:

Diamond Aircraft Industries GmbH.  
Customer Support  
N.A. Otto-Strasse 5  
A-2700 Wiener Neustadt  
Austria  
Phone: 011-43-2622-26700 Fax: 011-43-2622-26780

### Textron Lycoming

Contact Textron Lycoming directly for publication information.

#### North America:

Textron Lycoming  
652 Oliver Street  
Williamsport, PA, USA  
17701  
Phone: 570-523-6181

### mt-Propeller

Contact mt-propeller directly for publication information.

#### North America and Europe:

mt-propeller  
Airport Straubing Wallmuhle  
D-94348 Atting  
Germany  
Phone: +49-(9429)-9409-0

Internet: [www.mt-propeller.com](http://www.mt-propeller.com)

### Garmin International

Contact Garmin International Inc. directly for publication information.

#### North America:

Garmin International, Inc.  
1200 East 151st Street  
Olathe, Kansas, USA  
66062  
Phone: 913-397-8200