

DA20i (Certification Designation DV 20 E)

LIST OF APPLICABLE DIAMOND PUBLICATIONS · last update: 2025-01-08



Doc. No.	Description	Initial Issue	Revision	Ser.Nos. affected (SB/SI)	Remarks	PDF available
4.01.25-E	AIRPLANE FLIGHT MANUAL (english) Airplane Flight Manual (AFM)	2015-12-15	2	2022-03-22		X
4.01.25-E	AIRPLANE FLIGHT MANUAL (english) - SUPPLEMENTS none					-
4.01.25-E	AIRPLANE FLIGHT MANUAL (english) - VALID TEMPORARY REVISIONS TR-MÂM-20-475, New Fire Extinguisher	2023-08-08	-			X
4.01.25-E	AIRPLANE FLIGHT MANUAL (english) - OBSOLETE TEMPORARY REVISIONS					
	TR-MÂM-20-456, Ventilation	2021-09-30	-		obsolete with Rev. 2	-
	TR-MÂM-20-459, Fuel Pressure Sensor Location	2020-08-14	-		obsolete with Rev. 2	-
	TR-MÂM-20-460, Manual Corrections	2020-12-22	-		obsolete with Rev. 2	-
	TR-OÂM-20-245, External Alternator	2020-10-20	-		obsolete with Rev. 2	-
	TR-OÂM-20-271, LED Taxi- and Landing Lights	2019-09-17	-		obsolete with Rev. 2	-
4.02.25	AIRPLANE MAINTENANCE MANUAL (english) - BASIC MANUAL Airplane Maintenance Manual (AMM)	2015-12-15	2	2022-03-15		X
4.02.25	AIRPLANE MAINTENANCE MANUAL (english) - VALID TEMPORARY REVISIONS AMM-TR-MÂM-20-475, New Fire Extinguisher	2023-08-08	-			X
4.02.25	AIRPLANE FLIGHT MANUAL (english) - OBSOLETE TEMPORARY REVISIONS					
	AMM-TR-MÂM-20-446, Weighing Report Improvement	2018-03-30	-		obsolete with Rev. 2	-
	AMM-TR-MÂM-20-450, Wiring Improvement	2018-10-01	-		obsolete with Rev. 2	-
	AMM-TR-MÂM-20-459, Fuel Pressure Sensor Location	2020-09-14	-		obsolete with Rev. 2	-
	AMM-TR-MÂM-20-460, Manual Corrections	2020-12-22	-		obsolete with Rev. 2	-
	AMM-TR-OÂM-20-245, External Alternator	2020-10-25	-		obsolete with Rev. 2	-
	AMM-TR-OÂM-20-271, LED Taxi- and Landing Lights	2019-09-19	-		obsolete with Rev. 2	-

DA20i (Certification Designation DV 20 E)

LIST OF APPLICABLE DIAMOND PUBLICATIONS · last update: 2025-01-08



Doc. No.	Description	Initial Issue	Revision	Ser.Nos. affected (SB/SI)	Remarks	PDF available
SERVICE BULLETIN LIST						
SB20E-001	not issued yet					-
MSB20E-002/4	Software for the Engine, EMU and Avionic Systems	2016-02-11	4	2023-05-08	DV 20 E S/N 20.E001 and subsequent	X
SERVICE INFORMATION LIST						
SI20E-001/2	Descriptions of DAI technical publication systems and handling of documents	2021-12-23	2	2024-03-21	all DV 20 E S/N's	X
SI20E-002	Rotax Service Bulletin SB-912i-006, Exchange of stator assy at certain engine serial numbers	2016-05-30	-		all DV 20 E S/N's	X
SI20E-003	Garmin Service Advisory No. 1612 Rev. A, Update of the IGRF (International Geomagnetic Reference Field) Magnetic Field Model from base year 2010 to 2015	2016-07-15	-		all DV 20 E airplanes	X
SI20E-004	Rotax Alert Service Bulletin ASB-912 i-007, Inspection of the correct positioning of the sealing plug in ignition housing	2017-06-07	-		all DV 20 E airplanes	X
SI20E-005	EASA Emergency AD: Accomplishment with Rotax Alert Service Bulletin ASB-912i-007, which prescribes an inspection of the correct positioning of the sealing plug in ignition housing	2017-06-14	-		all DV 20 E airplanes	EASA EAD: 2017-0101-E X
SI20E-006	Rotax Service Bulletin SB-912i-008R1, Inspection and/or replacement of the valve push-rod assy	2018-03-12	-		all DV 20 E airplanes	X
SI20E-007	Rotax Service Bulletin No. SB-912i-009, Replacement of oil filter	2018-03-12	-		all DV 20 E airplanes	X
SI20E-008	EASA Emergency AD: Accomplishment with Rotax Alert Service Bulletin ASB-912 i-010iS, which prescribes an inspection and/or replacement of certain fuel pump assy part- and serial numbers	2019-03-19	-		all DV 20 E airplanes	EASA EAD: 2019-0055-E X
SI20E-009	EASA AD: Inspection and/or replacement of the valve push-rod ball sockets of each valve push-rod	2019-06-14	-		all DV 20 E airplanes	EASA AD: 2017-0208 X
SI20E-010	EASA Emergency AD: Rotax Alert Service Bulletin ASB-912i-011, Replacement of fuel pump assy for Rotax Engine Type 912 i and 915 iA (Series)	2019-10-14	-		all DV 20 E airplanes	EASA EAD: 2019-0253-E X
SI20E-011	Garmin Service Bulletin No. 2082 Rev. A, Update of the GPS Software	2020-07-18	-		all DV 20 E airplanes	X
SI20E-012	United Instruments Service Note No. 5934-14, Replacement of nonconforming static port threads	2023-04-17	-		All DV20 E airplanes with 5934 Series Altimeters installed	X
SI20E-013	Rotax Service Bulletin No. SB-912 i-014, Replacement of Propeller Shaft	2023-07-26	-		all DV 20 E airplanes	X
SI20E-014	EASA-EAD: Replacement of propeller shaft	2023-08-17	-		all DV 20 E airplanes	EASA-EAD: 2023-0156-E X
SI20E-015/1	Rotax Alert Service Bulletin No. ASB-912 i-016R1, Inspection and/or replacement of oil spray nozzle	2024-12-17	1	2024-12-23	all DV 20 E airplanes	NEW X
SI20E-016	Rotax Service Bulletin No. SB-912 i-015, Inspection and/or replacement of the expansion tank assy	2024-12-19	-		all DV 20 E airplanes	X