

TEMPORARY REVISION

TR-MÄM 40-1087

USE OF ALT. STATIC SOURCE

This temporary revision TR-MÄM 40-1087 is approved in conjunction with the Mandatory Design Change Advisory MÄM 40-1087, and is valid in conjunction with the latest revision of the DA 40 NG Airplane Flight Manual (AFM), until this temporary revision has been incorporated into the AFM.

The limitations and information contained herein either supplement, or in the case of conflict, override those in the AFM.

The technical information contained in this document has been approved by the Canadian Department of Transport.

Doc. No.	Chapter	Affected Pages
6.01.15-E	4B	4B-1, 4B-30

Instructions:

- Print this document on 8.5" x 11" yellow paper (single sided).
- Copy on yellow paper (single sided) at a reduced size of 72% to get the correct size for the AFM.
- Cut the paper to 6" x 8.5" and punch the holes on the left side of each page.
- Insert the cover page as the first page of the AFM.
- Insert the pages of this temporary revision in front of the corresponding pages in the AFM.
- Keep this temporary revision until the information has been incorporated into the DA 40 NG AFM.

CHAPTER 4B

ABNORMAL OPERATING PROCEDURES

Page

4B.1	PRECAUTIONARY LANDING	4B-2
4B.2	INSTRUMENT INDICATIONS OUTSIDE OF GREEN RANGE	4B-4
4B.2.1	RPM	4B-4
4B.2.2	COOLANT TEMPERATURE	4B-5
4B.2.3	OIL TEMPERATURE	4B-6
4B.2.4	OIL PRESSURE	4B-7
4B.2.5	GEARBOX TEMPERATURE	4B-8
4B.2.6	FUEL TEMPERATURE	4B-9
4B.2.7	VOLTAGE	4B-10
4B.2.8	CURRENT	4B-11
4B.3	CAUTION-ALERTS	4B-12
4B.3.1	ECU A FAILURE	4B-12
4B.3.2	ECU B FAILURE	4B-14
4B.3.3	FUEL QUANTITY LOW	4B-16
4B.3.4	COOLANT LEVEL	4B-18
4B.3.5	PITOT HEATING FAILURE	4B-19
4B.3.6	ENGINE CAUTION (IF WHITE WIRE ANNUNCIATOR IS INSTALLED)	4B-19
4B.4	CANOPY IN COOLING GAP POSITION	4B-20
4B.5	FAILURES IN FLAP OPERATING SYSTEM	4B-21
4B.6	LIGHTNING STRIKE	4B-23
4B.7	LANDING WITH MASS ABOVE MAXIMUM LANDING MASS	4B-24
4B.8	STARTING THE ENGINE WITH EXTERNAL POWER	4B-25
4B.8.1	BEFORE STARTING ENGINE	4B-25
4B.8.2	STARTING ENGINE	4B-27
4B.9	ERRONEOUS INDICATIONS OF AIRSPEED OR ALTITUDE	4B-30

4B.9 ERRONEOUS INDICATIONS OF AIRSPEED OR ALTITUDE

Erroneous indications on the airspeed indicator, altimeter, vertical speed indicator, or erroneous behavior of the autopilot (if equipped) may be the result of a blocked static source.

1. Alternate static source OPEN
2. Pitot heat ON
3. Emergency window(s) CLOSE

END OF CHECKLIST