

MODEL DA 40 NG

| Revision 81 Updates | | | | |
|---------------------|---|-----|------------|--|
| Doc. No. | Description | Rev | Status | |
| MSB 40NG-084 | Actions to prevent Passenger Door Separation: Installation of Placards, AFM Procedure update and Inspection/Data Gathering. | - | 2025-03-20 | |
| TR-MÄM-40-1209/a | Equipment List | а | 2025-03-21 | |

| Full Listing | | | |
|-------------------|--|-----|------------|
| Doc. NO. | Description | Rev | Status |
| 6.05.15 Chapter 1 | List of Applicable Publications (LOAP) - This document | 81 | 2025-03-20 |
| Aircraft Manuals | | | |
| 6.01.15-E | Airplane Flight Manual (AFM) | 4 | 2024-12-31 |
| Supplement A01 | Garmin G1000 Avionics System | 2 | 2015-04-08 |
| Supplement A02 | Garmin G1000 NXi Avionics System | 1 | 2019-02-08 |
| Supplement A03 | Intercom System PM 1000 II, PS Engineering Inc | - | 2017-09-05 |
| Supplement A05 | Conventional Cockpit DA 40 NG Club | - | 2011-03-15 |
| Supplement A13 | Autopilot System KAP 140, Bendix/King | 1 | 2011-03-15 |
| Supplement A29 | DA 40 NG Garmin Transponder GTX 328 | - | 2011-03-15 |
| Supplement A30 | DA 40 NG Garmin COM/NAV, SL 30 | - | 2011-03-15 |
| Supplement A33 | Garmin G1000 SBAS and P-RNAV Operation | 2 | 2014-07-01 |
| Supplement E7 | Operation with Ventilation Inlet Baffle | 1 | 2014-07-01 |
| Supplement N017 | Operation in CIS | 2 | 2013-12-17 |
| Supplement N023 | Operation in Brazil | - | 2022-05-16 |
| Supplement N048 | Operation in the Ukraine | - | 2011-07-01 |
| Supplement O01 | Use of the DA 40 NG as Tow-Plane | 1 | 2014-07-01 |
| Supplement O02 | Landing Gear with Large Tyres and 1280 kg Maximum Landing Mass | 2 | 2014-07-01 |
| Supplement O03 | Cold Weather Operation | 1 | 2014-07-01 |
| Supplement O04 | Diesel Operation | - | 2013-12-06 |
| Supplement O09 | Operation with D64-9028-11-01 Fuel Pumps | 3 | 2024-11-26 |
| Supplement S04 | 406 MHz Emergency Locator Transmitter Artex ME 406 | - | 2010-04-01 |

© DAI 2024 ALL RIGHTS RESERVED, PROPRIETARY DOCUMENT Internet: www.diamondaircraft.com Service & Support Portal: partners.diamondaircraft.com



MODEL DA 40 NG

| Full Listing | | | |
|---------------------------|--|-------|---------------------|
| Doc. NO. | Description | Rev | Status |
| Supplement S06 | G1000 Synthetic Vision Technology | 1 | 2011-03-15 |
| Supplement S07 | Recirculating Air - Cabin Cooling | 7 | 2016-06-22 |
| Supplement S10 | Flight Data Logging Device | - | 2016-01-29 |
| Supplement S11 | Garmin GTX 335R/345R transponders with ADS-B | - | 2019-04-15 |
| Supplement O09 | Operation with D64-9028-11-01 Fuel Pumps | 3 | 2024-11-26 |
| TR-MÄM-40-1203/a | Door Latching and Locking | а | 2025-02-18 |
| TR-MÄM-40-1209/a | Equipment List | а | 2025-03-21 |
| 6.02.15 | Airplane Maintenance Manual | 5 | 2024-07-15 |
| 6.02.15-S10 | Installation Instructions for System S10, Flight Data Logging Device | - | 2016-02-03 |
| AMM-TR-25-04 | Coolant Level Sensor Operational Test | - | 2025-02-13 |
| AMM-TR-MÄM-40-1203 | Visual Indicator for the Position of the Passenger Door Handle | - | 2025-01-06 |
| 6.03.15 | Illustrated Parts Catalogue (IPC) | (N/A) | Available Online |
| Service Bulletins | | | |
| MSB 40NG-002 | Software for E4-A (AE300) Engine, approved versions | 18 | 2023-09-21 |
| MSB 40NG-003 | Software for Garmin G1000; approved software systems, manifests and configurations | 16 | 2024-04-01 |
| OSB 40NG-004 | Installation of a coated safety walk | - | 2010-07-20 |
| OSB 40NG-006 | Import Requirements to CIS | - | 2011-07-11 |
| OSB 40NG-007 | Installation of a fuel pressure pulsation damper | 1 | 2014-10-03 |
| RSB 40NG-010 | Installation of check valves on fuel pumps | - | 2011-11-17 |
| RSB 40NG-011 (REVOKED) | Exchange of charged air elbow | - | 2012-02-28 |
| MSB 40NG-012 | Replacement of aft engine shock mounts | 2 | 2013-03-15 |



| Full Listing | | | |
|--------------|--|-----|------------|
| Doc. NO. | Description | Rev | Status |
| RSB 40NG-013 | Replacement of air conditioning system | - | 2012-07-26 |
| MSB 40NG-015 | Installation of a rudder cable guard | 1 | 2013-02-21 |
| MSB 40NG-016 | Correction of Airspeed Indicator (ASI) markings | 2 | 2013-06-12 |
| OSB 40NG-017 | CG adjustment | - | 2012-10-09 |
| MSB 40NG-018 | Exchange of charged air tubing; incl. WI Rev. 3 | 1 | 2012-11-26 |
| RSB 40NG-019 | Replacement of the Charged Air Hoses with glass fiber reinforced silicone hoses | - | 2013-06-20 |
| MSB 40NG-020 | Inspection of the nose landing gear (NLG) pivot of NLG-legs installed under OÄM 40-334 (landing gear with large tires) for cracks and possible rework or replacement | 6 | 2016-06-27 |
| OSB 40NG-021 | Installation of alternator regulator, Austro Engine P/N E4A-91-200-000 | - | 2015-02-25 |
| OSB 40NG-022 | Installation of an engine oil quick drain-valve | - | 2014-07-21 |
| OSB 40NG-023 | Installation of a radiator baffle | - | 2013-11-29 |
| OSB 40NG-024 | Installation of Battery Heaters | - | 2013-12-02 |
| OSB 40NG-025 | Installation of an engine master switch guard | - | 2014-06-24 |
| OSB 40NG-026 | Installation of LED Taxi and Landing Lights | - | 2014-06-25 |
| OSB 40NG-027 | Installation of LED Position Lights and ACL | - | 2015-11-02 |
| OSB 40NG-028 | Installation of Sun visors | - | 2014-06-27 |
| OSB 40NG-030 | Installation of Provisions for Operation with Diesel fuel | - | 2014-09-26 |
| RSB 40NG-031 | Installation of permanent maintenance access holes in wings | - | 2014-10-09 |
| OSB 40NG-032 | Installation provisions for a safety mesh to protect the fuel vent covers into the wings | 2 | 2019-03-26 |
| OSB 40NG-035 | Installation of a hydraulic NLG damper | - | 2014-12-02 |
| OSB 40NG-036 | Installation of the Coolant Level Sensor D4D-9075-26-26 | - | 2015-02-03 |
| OSB 40NG-037 | Installation of a GPS-Tracker as Carry-On Equipment | - | 2015-04-09 |
| OSB 40NG-038 | Improvement of powerplant cooling | - | 2015-05-26 |
| OSB 40NG-039 | Replacement of nose landing gear strut | - | 2015-05-28 |
| OSB 40NG-040 | Installation of the nose landing gear fairings for the lowered nose landing gear (MÄM 40-791/OSB 40NG-039) | 1 | 2015-06-14 |
| RSB 40NG-041 | Inspection of NLG elastomer pack center tube | 1 | 2015-12-16 |
| RSB 40NG-042 | Inspection and improved bushing installation of charged air duct assy | - | 2016-03-07 |
| OSB 40NG-044 | Maintenance Access Holes in the Elevator | - | 2016-02-03 |



| Full Listing | | | |
|--------------|--|-----|------------|
| Doc. NO. | Description | Rev | Status |
| MSB 40NG-046 | Inspection of turbocharger V-clamp | 2 | 2016-07-22 |
| OSB 40NG-047 | Operation of the air conditioning system during T/O and Landing | - | 2016-07-14 |
| MSB 40NG-048 | Inspection of autopilot bridle cable clamps | 2 | 2016-12-01 |
| OSB 40NG-049 | Replacement of main landing gear strut | - | 2016-09-23 |
| RSB 40NG-051 | Installation of a chafe protector on the turbocharger intake hose | - | 2016-10-24 |
| RSB 40NG-052 | Improved mounting of 2nd Alternator | - | 2017-03-08 |
| RSB 40NG-053 | Replacement of steel pin of door handle mechanism of canopy and passenger door with an improved design | - | 2017-06-14 |
| OSB 40NG-055 | Replacement of the charge air hoses and tubers | | 2017-08-18 |
| OSB 40NG-057 | Activation of Garmin GTX 335R/345R transponders' ADS-B functions | - | 2019-04-15 |
| MSB 40NG-058 | Removal of Pilot Gust Lock Mount | 1 | 2018-11-20 |
| MSB 40NG-059 | DA 40 NG NLG Tire Pressure Placard | 1 | 2019-05-16 |
| OSB 40NG-060 | Instructions for removal of the RACC system | - | 2019-05-10 |
| OSB 40NG-062 | Installation of the Garmin G1000 NXi Phase II equipment and software | - | 2019-04-22 |
| MSB 40NG-063 | MLG Support Plate | - | 2019-06-18 |
| MSB 40NG-064 | Fuel Tank Interconnect Hose (Flexible Coupling) Replacement | 3 | 2025-01-23 |
| MSB 40NG-065 | Baggage Net Latches | 1 | 2021-07-06 |
| MSB 40NG-066 | Cowling Lightning Protection | 2 | 2020-10-09 |
| MSB 40NG-067 | Installation of 7 dB Attenuators | - | 2020-01-24 |
| MSB 40NG-068 | Replacement of NLG tube-type tire with tubeless tire. | - | 2020-06-16 |
| OSB 40NG-069 | Installation of Garmin Flight Stream (FS510) | - | 2020-10-20 |
| MSB 40NG-070 | Inspection of safety ropes in the engine installation | - | 2021-02-01 |
| OSB 40NG-071 | Installation of stainless steel underbelly fire protection | - | 2021-08-12 |
| OSB 40NG-072 | Installation of alternate coolant tank D44-7521-00-00_3 | - | 2021-04-23 |
| OSB 40NG-073 | Installation of redesigned map lights | - | 2021-05-17 |
| OSB 40NG-074 | Installation of a bubble canopy | - | 2021-08-19 |
| RSB 40NG-076 | Upper cowling air duct modification | - | 2022-03-17 |
| MSB 40NG-077 | Inspection of gearbox oil | - | 2022-08-25 |
| MSB 40NG-078 | Inspection of rudder cables in the footwells | 1 | 2022-11-24 |



| Full Listing | | | |
|---------------------------|--|-----|------------|
| Doc. NO. | Description | Rev | Status |
| RSB 40NG-079 | Installation of a stiffener on the alternator cable | - | 2023-03-30 |
| MSB 40NG-080 | Inspection of starter wiring connection | 2 | 2023-09-28 |
| OSB 40NG-081 | Installation of Amerex 337TS fire extinguisher | - | 2023-08-03 |
| OSB 40NG-082 | Installation of alternate electric fuel pumps | - | 2023-07-06 |
| MSB 40NG-084 | Actions to prevent Passenger Door Separation: Installation of Placards, AFM Procedure update and Inspection/Data Gathering. | - | 2025-03-20 |
| Service Information Lette | ers | | |
| SI40NG-001 | Descriptions of DAI technical publication systems and handling of documents | 1 | 2017-08-28 |
| SI40NG-002 | AE Mandatory Service Bulletin MSB-E4-009/2, Possible exchange of the engine high pressure pump | 1 | 2014-01-10 |
| SI40NG-003 | EASA-EAD: High Pressure Fuel Pump - Inspection/Replacement | - | 2010-10-12 |
| SI40NG-005 | Garmin Service Advisory No. 1051 Rev. A, 2010 IGRF (International Geomagnetic Reference Field) Magnetic Field Model | - | 2011-02-10 |
| SI40NG-006 | EASA-AD: High Pressure Fuel Pump - Inspection/Replacement | - | 2011-03-09 |
| SI40NG-007 | Installation and tightening torque of worm drive clamps in the charge-air and liquid cooling system | 1 | 2013-01-18 |
| SI40NG-008 | Garmin Service Advisory No. 1118 Rev. A, Momentary failure indications (Red-X) can occur when sorting stored flight plans | - | 2011-05-17 |
| SI40NG-009 | Garmin Service Advisory No. 1129 Rev. A, Momentary loss of GRS 77/77H and GDC 74A/74B/74H functions | - | 2011-05-31 |
| SI40NG-010 | Garmin Service Advisory No. 1029 Rev. D, European Geostationary Navigation Overlay System (EGNOS) Safety-of-Life (SoL) Service is Fully Operational | - | 2011-07-11 |
| SI40NG-011 | Garmin Service Advisory No. 1141 Rev. A, Garmin SBAS-capable receivers may experience loss of LPV or LNAV/VNAV capability due to incoherent EGNOS satellite GEO ranging data | - | 2011-08-22 |
| SI40NG-012 | AE Mandatory Service Bulletin Revision MSB-E4-013/1, Gearbox oil inspection - Additional oil check for early debris indication | 1 | 2011-08-22 |
| SI40NG-013 | Measures that result from performing Austro Engine Mandatory Service Bulletin MSB-E4-013/1 | - | 2011-11-30 |
| SI40NG-014 | Austro Engine Mandatory Service Bulletin MSB-E4-014/1, Replacement of the Fuel Return Line and Banjo Fitting | - | 2012-04-23 |
| SI40NG-015 | Garmin Service Bulletin No. 1210 Rev. A, SafeTaxi® Availability In Europe | - | 2012-05-22 |
| SI40NG-016 | AE Mandatory Service Bulletin Revision MSB-E4-014/2, Replacement of the Fuel Injector Return Line and the Banjo Fitting | - | 2012-06-18 |



| Full Listing | | | |
|--------------|---|-----|------------|
| Doc. NO. | Description | Rev | Status |
| SI40NG-017 | EASA-AD: Installation of a temporary placard in the cockpit | - | 2012-09-12 |
| SI40NG-018 | Garmin Service Alert No. 1228, SIDs and STARs non-JETs Limitation | - | 2012-11-06 |
| SI40NG-019 | Austro Engine Mandatory Service Bulletin No. MSB-E4-007/3, Replacement of Waste Gate Controller | - | 2012-12-11 |
| SI40NG-020 | EASA-AD: Inspection, and replacement if necessary, of the charged air tubing from the turbocharger to the intercooler for chafing marks | - | 2013-01-22 |
| SI40NG-021 | EASA-AD: Inspection of the markings of the safety belts | 1 | 2014-04-08 |
| SI40NG-022 | MT-Propeller Service Bulletin No. 27, Inspection and modification of certain governor type- and serial numbers | - | 2013-02-28 |
| SI40NG-023 | Garmin Service Advisory No. 1309, Verification of displayed heading is not noticeable drifting prior Take-Off | - | 2013-03-04 |
| SI40NG-024 | EASA-AD: Replacement of certain Waste Gate Controller part numbers with an improved design at its E4 engines | - | 2013-03-14 |
| SI40NG-025 | Proper draining of the fuel system | - | 2013-06-19 |
| SI40NG-026 | Garmin Service Advisory No. 1309 Rev. B, Verification of displayed heading is not noticeable drifting prior Take-Off | - | 2013-04-12 |
| SI40NG-027 | EASA-AD: Alternative P/N waste gate controllers be installed as replacement parts, Austro Engine Mandatory Service Bulletin No. MSB-E4-007/4 | - | 2013-05-06 |
| SI40NG-028 | FAA-AD: Inspection and replacement if necessary of the charged air tubing from the turbocharger to the intercooler for chafing marks | - | 2013-05-27 |
| SI40NG-029 | Identification of stainless steel control cables | - | 2013-06-17 |
| SI40NG-030 | FAA-AD: Replacement of certain Waste Gate Controller part numbers with an improved design | - | 2013-07-22 |
| SI40NG-031 | Garmin Service Advisory No. 1344 Rev. A, CDI / HSI scaling on a limited number of LPV and LNAV/VNAV approaches are incorrect | - | 2013-08-21 |
| SI40NG-032 | Garmin Service Advisory No. 1348 Rev. A, Approach waypoints are not properly loaded or displayed when using a vector transition at certain approaches | - | 2013-08-21 |
| SI40NG-033 | Austro Engine Mandatory Service Bulletin No. MSB-E4-007/6, Replacement of Waste Gate Controller | 1 | 2013-09-20 |
| SI40NG-034 | Garmin Terrain Data Alert No. 1351 Rev. B, Anomalies when using Synthetic Vision Technology in Northwest Greenland | 1 | 2015-03-03 |
| SI40NG-035 | EASA-AD: Austro Engine E4 Waste Gate Controller | - | 2013-09-16 |
| SI40NG-036 | United Instruments Inc. Service Bulletin No. 12, Paint on dial may crack and separate from the surface | 1 | 2013-10-31 |



| Full Listing | | | |
|--------------|---|-----|------------|
| Doc. NO. | Description | Rev | Status |
| SI40NG-037 | Garmin Service Advisory No. 1352 Rev. A, Course deviation indicator (CDI) may deflect in the wrong direction in certain situations | - | 2013-09-26 |
| SI40NG-038 | Garmin Service Advisory No. 1363 Rev. A, User-modified terminal procedure stored in a Flight Plan may cause error condition | - | 2013-11-21 |
| SI40NG-039 | Garmin Service Advisory No. 1344 Rev. B, LPV and LNAV/VNAV Approach Full Scale Deflection | - | 2013-12-18 |
| SI40NG-040 | Garmin Service Advisory No. 1372 Rev. A, Unavailable RNAV (GPS) approaches due to lack of VDA | - | 2013-12-18 |
| SI40NG-041 | EASA-AD: Austro Engine E4 Waste Gate Controller | - | 2014-03-03 |
| SI40NG-042 | Andair GAS375 Gascolator Filters | 1 | 2014-06-25 |
| SI40NG-043 | FAA-AD: Removing of certain Austro Engine part number (P/N) waste gate controllers from service | - | 2014-05-07 |
| SI40NG-044 | Austro Engine Mandatory Service Bulletin No. MSB-E4-017, Check and if necessary replacement of the Timing Chain | - | 2014-07-03 |
| SI40NG-045 | Garmin Service Advisory No. 1449 Rev. A, Unexpected flight paths may be displayed when sequencing to some vector transition approaches | - | 2014-09-05 |
| SI40NG-046 | Installation of charged air hose P/N D44-8122-00-10_2 | - | 2015-07-24 |
| SI40NG-047 | Garmin Service Alert No. 1538 Rev. A, Operations with Altimeter Set to QFE (height above field elevation) | - | 2015-08-12 |
| SI40NG-048 | Andair Service Alert: Certain fuel valve systems with extension may have a possible lack of engagement between the universal joint assembly and the top of the valve assembly | - | 2015-09-17 |
| SI40NG-050 | FAA-AD: Austro Engine E4 Engines | - | 2016-03-04 |
| SI40NG-051 | Austro Engine MSB-E4-020, Inspection of Gearbox Housing | - | 2016-03-04 |
| SI40NG-052 | United Instruments Inc. SB No. 13, Specific 5934 Series Altimeters manufactured between January 2015 and February 2016 are susceptible to develop a slow diaphragm leak which would affect the accuracy of the altimeters | - | 2016-04-29 |
| SI40NG-053 | Garmin Service Advisory No. 1372 Rev. B, unavailable RNAV (GPS) approaches | - | 2016-06-24 |
| SI40NG-054 | Garmin Service Advisory No. 1612 Rev. A, Update of the IGRF (International Geomagnetic Reference Field) Magnetic Field Model from base year 2010 to 2015 | - | 2016-09-19 |
| SI40NG-055 | EASA-AD: Inspections of the auto pilot bridle clamps | - | 2016-09-27 |
| SI40NG-056 | EASA-AD: Repetitive visual inspections and, depending on findings, replacement of turbocharging-V-band Clamps with an improved design | - | 2016-10-11 |
| SI40NG-057 | Installation of turbo charge air system | 1 | 2016-11-14 |



| Full Listing | | | |
|--------------|--|-----|------------|
| Doc. NO. | Description | Rev | Status |
| SI40NG-058 | FAA-AD: Inspections of the auto pilot bridle clamps in the pitch and roll control system | - | 2016-11-02 |
| SI40NG-059 | FAA-AD: Repetitive visual inspections and, depending on findings, replacement of turbocharging-V-band Clamps | - | 2016-11-15 |
| SI40NG-060 | FAA-AD: Certain altimeters displaying higher than actual altitude due to a slow diaphragm leak which were examined in United Instruments SB No. 13 | - | 2017-03-24 |
| SI40NG-061 | Austro Engine MSB-E4-022/1, Replacement of certain batches of the Waste Gate Controller at E4 engines and the installation of a spring loaded circlip on all engines | - | 2017-11-13 |
| SI40NG-062 | Austro Engine MSB-E4-024/1, Replacement of the standard circlip at the Waste Gate Controller at E4 engines with a spring loaded circlip | - | 2017-11-13 |
| SIDA40-002 | Change in Type Design Responsibility | - | 2017-11-15 |
| SI40NG-063 | FAA AD 2018-07-16 and EASA-AD 2017-0250: Lifetime limit to waste gate controller and replacement of waste gate rod circlips to prevent unsafe condition due to disconnection | - | 2018-04-04 |
| SI40NG-065 | Air Intake System Hose | 2 | 2018-10-18 |
| SI40NG-066 | Production Residue found in Air Filter | - | 2018-09-20 |
| SI40NG-067 | Austro Engine MSB-E4-025 Fuel Injectors DA 40 NG | - | 2018-10-22 |
| SI40NG-068 | EASA AD 2019-0041: Life limit to Austro Engine timing chain and fuel injectors | - | 2019-03-08 |
| SI40NG-069 | Governor Adjustment of MIN/MAX Stop Settings | - | 2019-06-20 |
| SI40NG-070 | Fire Resistant Cowlings | - | 2019-10-03 |
| SI40NG-071 | TCCA AD No. CF-2019-39: Fuel tank interconnect hose replacement | 1 | 2025-01-23 |
| SI40NG-074 | DUPONT product discontinuation letter | - | 2020-05-20 |
| SI40NG-075 | Aircraft cleaning and disinfection recommendations | - | 2020-05-21 |
| SI40NG-077 | FAA AD 2020-22-14: Replacement of the wastegate controller and control rod circlip | - | 2021-01-01 |
| SI40NG-078 | EASA AD 2021-0550-E and Austro Engine MSB-E4-030 - Oil pump replacement | - | 2021-02-25 |
| SI40NG-079 | EASA AD 2021-0550-E and Austro Engine MSB-E4-030 Rev. 3 - Oil Pump Replacement - updated serial number effectivity | - | 2021-03-18 |
| SI40NG-080 | EASA AD 2021-0143-E and Austro Engine MSB-E4-031 - Oil pump replacement | - | 2021-06-16 |
| SI40NG-081 | Austro Engine MSB-E4-034/2, MSB-E4-035, and EASA AD 2021-0203-E | - | 2021-09-23 |
| SI40NG-082 | HPP gear modification | - | 2021-09-30 |
| SI40NG-083 | Austro Engine MSB-E4-036 and EASA AD 2021-0274-E | - | 2021-12-16 |



| Full Listing | | | |
|--------------|---|-----|------------|
| Doc. NO. | Description | Rev | Status |
| SI40NG-084 | Nose landing gear maintenance and inspections. | - | 2023-01-12 |
| SI40NG-085 | Austro Engine MSB-E4-039 - Oil analysis and piston replacement | - | 2022-11-17 |
| SI40NG-087 | Garmin Service Advisory No. 22106 Rev. A - G1000 NXi Systems Database Update | - | 2022-12-06 |
| SI40NG-089 | United Instruments Service Note No. 14 | - | 2023-04-13 |
| SI40NG-090 | Service Information Letter to introduce Austro Engine MSB-E4-042_r0 | - | 2024-02-07 |
| SI40NG-091 | To announce the late release of MSB 40NG-064 Rev 3 | | 2024-02-27 |
| SI40NG-095 | EASA AD-2024-0172-E Piston Borescope Inspection | - | 2024-08-29 |
| SI40NG-094 | Closing and latching the passenger door. | - | 2024-08-30 |