Diamond Aircraft Industries GmbH N. A. Otto-Straße 5 A-2700 Wiener Neustadt Austria

DAI OSB 40NG-007/1 Page 1 of 3 03-Oct-2014

OPTIONAL SERVICE BULLETIN OSB 40NG-007/1

supersedes OSB 40NG-007

I TECHNICAL DETAILS

I.1 Category

Optional.

I.2 Airplanes affected

Type: DA 40 NG

Serial numbers: 40.N001 through 40.N014

D4.301, D4.326

I.3 Date of effectivity

14-Nov-2011

I.4 Time of Compliance

At owners discretion.

I.5 Subject

Installation of a fuel pressure pulsation damper.

ATA-Code: 28-00

I.6 Reason

For the DA 40 NG Series a fuel pressure pulsation damper upstream of the high pressure pump has been introduced to reduce the amplitude of the fuel pressure oscillations at the high pressure fuel pump. This Service Bulletin describes the retrofit installation on airplanes already in service.

I.7 Concurrent Documents

None.

I.8 Approval

The technical information or instructions contained in this document relate to the Design Change Advisory No. MÄM 40-468, which has been approved under the authority of EASA Design Organization Approval ref. EASA.21J.052.



Diamond Aircraft Industries GmbH N. A. Otto-Straße 5 A-2700 Wiener Neustadt Austria

DAI OSB 40NG-007/1 Page 2 of 3 03-Oct-2014

The technical content of this document has been approved under the authority of DOA ref. EASA.21J.052.

I.9 Accomplishments / Instructions

Comply with WI-OSB 40NG-007, latest effective issue.

I.10 Mass (Weight) and CG

The change in mass and CG is negligible.

II PLANNING INFORMATION

II.1 Material and Availability

See WI-0SB 40NG-007, latest effective issue.

II.2 Special Tools

None.

II.3 Labour Effort

Approx. 1.5 hours.

II.4 Credit

None.

II.5 Reference Documents

DA 40 NG Airplane Maintenance Manual, Doc. No. 6.02.15, latest effective issue.

III REMARKS

- 1. All work must be done by a certified aircraft service station or a certified aircraft maintenance mechanic.
- 2. All work, in particular that which is not especially described in this Service Bulletin, must be done in accordance with the referenced Maintenance Manual.
- 3. Completion of all work must be recorded in the log book.
- 4. In case of doubt contact Diamond Aircraft Industries GmbH.



Diamond Aircraft Industries GmbH N. A. Otto-Straße 5 A-2700 Wiener Neustadt Austria

DAI OSB 40NG-007/1 Page 3 of 3 03-Oct-2014

EXECUTION REPORT TO SERVICE BULLETIN OSB 40NG-007/1

AIRPLANE DATA	
Airplane Serial Number:	
Airplane Registration:	
Airplane Operator:	
Hours of operation of airplane:	
No. of landings:	
Hours of operation-engine	
Typical operation of airplane:	private, club, training, other
Date, Name, Sign	

Please fax the completed form to Fax No. +43-2622-26700-1369 or e-mail to airworthiness@diamond-air.at