Diamond Aircraft Industries GmbH N. A. Otto-Straße 5 A-2700 Wiener Neustadt Austria

DAI RSB 40NG-013 Page 1 of 3 26-Jul-2012

RECOMMENDED SERVICE BULLETIN RSB 40NG-013

I TECHNICAL DETAILS

I.1 Category

Recommended.

Airplanes affected

Type: DA 40 NG

Serial numbers: 40.N011, 40.N012, 40.N015, 40.N016, 40.N035, 40.N065

I.2 Date of effectivity

26-Jul-2012

I.3 <u>Time of Compliance</u>

At owners discretion.

I.4 Subject

Replacement of air conditioning system.

ATA-Code: 21-50, 24-30

I.5 Reason

Diamond aircraft has developed a new air conditioning unit. The benefits compared to the previous unit are 4kg weight saving, increased cooling performance and reduced CG aft travel. This Service Bulletin describes the replacement of the previous air conditioning unit with the new system.

I.6 Concurrent Documents

None.

I.7 Approval

The technical information or instructions contained in this document relate to the Design Change Advisories No. OÄM 40-316/i and OÄM 40-314/j, which have been approved under the authority of EASA Design Organization Approval ref. EASA.21J.052.

The technical content of this document has been approved under the authority of DOA ref. EASA.21J.052.

I.8 Accomplishments / Instructions

Comply with WI-RSB 40NG-013, latest effective issue.

Diamond Aircraft Industries GmbH N. A. Otto-Straße 5 A-2700 Wiener Neustadt Austria

DAI RSB 40NG-013 Page 2 of 3 26-Jul-2012

I.9 Mass (Weight) and CG

Mass (Weight) and CG affected.

II PLANNING INFORMATION

II.1 Material and Availability

See WI-RSB 40NG-013, latest effective issue.

II.2 Special Tools

None.

II.3 Labour Effort

Approx. 6 hours.

II.4 Credit

None.

II.5 Reference Documents

DA 40 NG Airplane Maintenance Manual, Doc. No. 6.02.15, latest effective issue.

III REMARKS

- All work must be done by a certified aircraft service station or a certified aircraft maintenance mechanic.
- 2. All work, particular those that are not especially described in this Service Bulletin, must be done in accordance with the referenced Maintenance Manual.
- 3. Completion of all work must be recorded in the log book.
- 4. In case of doubt contact Diamond Aircraft Industries GmbH.



Diamond Aircraft Industries GmbH N. A. Otto-Straße 5 A-2700 Wiener Neustadt Austria

DAI RSB 40NG-013 Page 3 of 3 26-Jul-2012

EXECUTION REPORT TO SERVICE BULLETIN RSB 40NG-013

AIRPLANE DATA		
Airplane Serial Number		
Airplane Registration		
Airplane Operator		
Hours of operation of airplane		
No. of landings		
Hours of operation-engine		
Typical operation of airplane	private, club, training, other _	
Typical operation of airplane	private, club, training, other _	
Typical operation of airplane	private, club, training, other _	
Typical operation of airplane	private, club, training, other _	
Typical operation of airplane	private, club, training, other _	
Typical operation of airplane Date, Name, Sign	private, club, training, other _	

Please fax the completed form to Fax No. +43-2622-26700-1369 or e-mail to airworthiness@diamond-air.at