

Diamond Aircraft Industries GmbH N. A. Otto-Straße 5 2700 Wiener Neustadt Austria

DAI RSB 40-078 DAI RSB D4-093 DAI RSB F4-031 DAI RSB 40NG-031 Page 1 of 3 09-Oct-2014

RECOMMENDED SERVICE BULLETIN RSB 40-078 RSB D4-093 RSB F4-031 RSB 40NG-031

I TECHNICAL DETAILS

I.1 Category

Recommended.

I.2 Airplanes affected

Type: DA 40, DA 40 D, DA40 F, DA 40 NG

Serial numbers: 40.006 through 40.009

40.011 and subsequent
D4.001 and subsequent
40.DS001 and subsequent
40.FC001 and subsequent
40.N001 and subsequent

I.3 Date of effectivity

09-Oct-2014

I.4 <u>Time of Compliance</u>

At owner's discretion.

I.5 Subject

Installation of permanent maintenance access holes in wings.

I.6 Reason

Install maintenance access holes in the wings to gain easier access to the aileron push rod roller guides. The access holes will be help to change the aileron push rod roller guides.

I.7 Concurrent Documents

None.



Diamond Aircraft Industries GmbH N. A. Otto-Straße 5 2700 Wiener Neustadt Austria

DAI RSB 40-078 DAI RSB D4-093 DAI RSB F4-031 DAI RSB 40NG-031 Page 2 of 3 09-Oct-2014

I.8 Approval

The technical information or instructions contained in this document relate to the Design Change Advisory No. OÄM 40-386, which has been approved under the authority of EASA Design Organization Approval ref. EASA.21J.052.

The technical content of this document has been approved under the authority of DOA ref. EASA.21J.052.

I.9 <u>Accomplishments / Instructions</u>

See WI-RSB 40-078 / WI-RSB D4-093 / WI-RSB F4-031 / WI-RSB 40NG-031, latest effective issue.

I.10 Mass (Weight) and CG

None.

II PLANNING INFORMATION

II.1 Material and Availability

See WI-RSB 40-078 / WI-RSB D4-093 / WI-RSB F4-031 / WI-RSB 40NG-031, latest effective issue.

II.2 Special Tools

None.

II.3 Labour Effort

Approx. 7 hours.

II.4 Credit

None.

II.5 Reference Documents

DA 40 Airplane Maintenance Manual, Doc. No. 6.02.01, latest effective issue.

DA 40 NG Airplane Maintenance Manual, Doc. No. 6.02.15, latest effective issue.

III <u>REMARKS</u>

- 1. All work must be done by a certified aircraft service station or a certified aircraft maintenance mechanic.
- 2. All work, particular that, which is not especially described in this Service Bulletin, must be done in accordance with the referenced Maintenance Manual.
- 3. Completion of all work must be recorded in the log book.
- 4. In case of doubt contact Diamond Aircraft Industries GmbH.



Diamond Aircraft Industries GmbH N. A. Otto-Straße 5 2700 Wiener Neustadt Austria

DAI RSB 40-078 DAI RSB D4-093 DAI RSB F4-031 DAI RSB 40NG-031 Page 3 of 3 09-Oct-2014

EXECUTION REPORT TO SERVICE BULLETIN RSB 40-078 RSB D4-093 RSB F4-031 RSB 40NG-031

AIRPLANE INFORMATION			
Airplane Serial Number			_
Airplane Registration			_
Airplane Operator			_
Hours of operation of airplane			_
No. of landings			_
Hours of operation-engine			_
Typical operation of airplane	private,	club, training, other	
Date, Name, Sign			

Please fax the completed form to Fax No. +43-2622-26700-1369 or e-mail to airworthiness@diamond-air.at