## **Diamond Aircraft Industries**

# **OPTIONAL SERVICE BULLETIN**



Model DA 40 NG

# OPTIONAL SERVICE BULLETIN NO. OSB 40NG-071 REV. 0

# I TECHNICAL DETAILS

## I.1 Category

Optional.

#### **1.2** Airplanes Affected

Type: DA 40 NG

S/N: All

#### **I.3** Date of Effectivity

12 August 2021

#### I.4 Time of Compliance

At owner's discretion.

#### I.5 Subject

Installation of stainless steel underbelly fire protection on DA 40 NGs.

#### I.6 Reason

Due to the increasingly limited availability of fire resistant paint used on the underbelly of the DA 40 NG, Diamond Aircraft has reintroduced the use of stainless steel sheets on the underbelly of the aircraft for fire protection. This service bulletin describes the installation of the aforementioned stainless steel sheets.

#### **I.7** Concurrent Documents

None.

#### I.8 Approval

The technical information and instructions contained in this document relate to Design Change Advisory No. OÄM 40-1038, which has been approved as part of the type design.

# I.9 Accomplishment/Instructions

See WI-OSB 40NG-071, latest effective issue.

# I.10 Mass (Weight) and CG

The change in mass and CG is negligible.

Page 1 of 3 12 August 2021

## **Diamond Aircraft Industries**

# **OPTIONAL SERVICE BULLETIN**



Model DA 40 NG

# **II PLANNING INFORMATION**

# II.1 Material and Availability

See WI-OSB 40NG-071, latest effective issue.

#### II.2 Special Tools

None.

#### II.3 Labour Effort

Approximately 1 hour will be required to accomplish this service bulletin.

This estimate is for direct labour performed by a technician, and it does not include setup, planning, familiarization, cure time, part fabrication, or tool acquisition.

#### II.4 Credit

None.

#### II.5 Reference Documents

DA 40 NG Aircraft Maintenance Manual Doc. No. 6.02.15, latest effective issue

# **III REMARKS**

- 1. All work must be done by a certified aircraft service station or a certified aircraft maintenance mechanic.
- 2. All work, in particular which is not especially described in this service bulletin, must be done in accordance with the referenced maintenance manual.
- 3. Completion of all work must be recorded in the logbook.
- 4. In case of doubt, contact Diamond Aircraft Industries Inc.

Page 2 of 3 12 August 2021

# **Diamond Aircraft Industries**

# **OPTIONAL SERVICE BULLETIN**





# EXECUTION REPORT TO SERVICE BULLETIN OSB 40NG-071 REV. 0

AIRPLANE INFORMATION	
Airplane Serial Number	
Airplane Registration	
Airplane Operator	
Hours of Operation of Airplane	
No. of Landings	
Hours of Operation of Engine	
Typical Operation of Airplane	(private, club, training, other)
Date, Name, Signature	

Please e-mail the completed form to Techpubs@diamondaircraft.com.