

SERVICE INFORMATION NO. SI 40NG-007/1

SUPERSEDES SERVICE INFORMATION NO. SI 40NG-007

NOTE: SI's are used only:
1) To distribute information from DAI to our customers.
2) To distribute applicable information/documents from our suppliers to our customers with additional information.
Typically there is no revision service for SI's. Each new information or change of that will be sent along with a new SI.

I. TECHNICAL DETAILS

1.1 Airplanes affected:

All DA 40 NG airplanes

1.2 Subject:

Installation and tightening torque of worm drive clamps in the charge-air and liquid cooling system.

ATA-Code: 75 and 81

1.3 Reason:

To avoid improper installation and tightening of the worm drive clamps in the charge-air and liquid cooling system.

1.4 Information:

All information previously contained in this Service Information has been incorporated into the AMM with AMM-TR-MÄM-40-630.

II. OTHERS

In case of doubt contact Diamond Aircraft Industries. (mail to: support@diamond-air.at)