

SERVICE INFORMATION NO. SI 40NG-042/1

SUPERSEDES SERVICE INFORMATION NO. SI 40NG-042

NOTE: SI's are used only:
1) To distribute information from DAI to our customers.
2) To distribute applicable information/documents from our suppliers to our customers with additional information.
Typically there is no revision service for SI's. Each new information or change of that will be sent along with a new SI.

I. TECHNICAL DETAILS

1.1 Airplanes affected:

All DA 40 NG airplanes

1.2 Subject:

Andair GAS375 Gascolator Filters

ATA-Code: 71-00

1.3 Reason:

Andair has issued a Service Alert describing that some GAS375 Gascolators have been fitted with filters with the incorrect part number on them. The filters in question are part numbers FIA375-10M, but the -10M suffix has been omitted. It should be noted that the filters do have the correct mesh fitted, and will function correctly, but the incorrect part number marked on them could lead to someone ordering an incorrect replacement.

Diamond Aircraft performed additional investigations and considers the Andair Service Alert as no longer applicable for the DA 40 NG.

1.4 Information:

Not Applicable

II. OTHERS

In case of doubt contact Diamond Aircraft Industries GmbH.