

# LIST OF APPLICABLE PUBLICATIONS

## MODEL DA 40

### Revision 5 Updates

Doc. No.	Description	Rev	Status
SI40-161	Slick SB No. SB1-15A - Potential decreased service life of Slick magneto distributor gear assemblies	-	10-Jan-19

### Full Listing

Doc. No.	Description	Rev	Status
6.05.01 Chapter 1	List of Applicable Publications (LOAP) - This document	5	10-Jan-19

### Aircraft Manuals

Doc. No.	Description	Rev	Status
<b>6.01.01</b>	<b>Flughandbuch (FHB) - Deutsch</b>	9	31-Jan-14
Ergänzung A1	COM/NAV, KX 125	1	20-Apr-01
Ergänzung A2	Intercom, PM 1000 II	1	20-Apr-01
Ergänzung A3	Transponder, KT 76A	1	20-Apr-01
Ergänzung A4	GPS, KLN 89B	1	20-Apr-01
Ergänzung A5	CDI, KI 208	1	20-Apr-01
Ergänzung A6	GPS, KLN 94, VFR-Betrieb	2	9-Sep-01
Ergänzung A7	Audio Amp./Intercom/Marker, KMA 28	1	20-Apr-01
Ergänzung A8	COM/NAV, KX 155A + KX 165A	2	3-Oct-01
Ergänzung A9	Radiokompaß (ADF), KR 87	2	17-Feb-03
Ergänzung A10	DME-Anlage, KN 62A	2	17-Feb-03
Ergänzung A11	Kompaßsystem, KCS 55A	3	17-Feb-03
Ergänzung A12	Transponder, KT 76C	1	20-Apr-01
Ergänzung A13	Autopilot, KAP 140	1	26-May-03
Ergänzung A14	GPS, KLN 94, IFR-Betrieb	2	9-Sep-01
Ergänzung A15	GPS Annunciation Control Unit, MD 41	1	20-Apr-01
Ergänzung A16	MFD/GPS, KMD 150	-	20-Sep-01
Ergänzung A17	COM/NAV/GPS, GNS 430	2	17-Feb-03
Ergänzung A18	Audioanlage, GMA 340	1	17-Feb-03
Ergänzung A19	Transponder, GTX 327	-	1-Oct-01
Ergänzung A20	CDI, GI 106A	-	1-Oct-01

### 6.05.01 Chapter 1 R5

# LIST OF APPLICABLE PUBLICATIONS

## MODEL DA 40

Ergänzung A21	COM/NAV/GPS, GNS 530	1	15-Mar-02
Ergänzung A22	Strike Finder, SF 2000	-	2001-10-10
Ergänzung A23	GPS-Anzeigegerät, MD 41-1488/1484	1	20-Dec-02
Ergänzung A24	Stormscope, WX-500	2	28-Feb-03
Ergänzung A25	Audioanlage, GMA 340, VFR-Betrieb	1	20-Feb-03
Ergänzung A26	COM/NAV/GPS, GNS 430, VFR-Betrieb	-	2002-03-20
Ergänzung A27	Ground COM #2-Schalter	-	2002-04-05
Ergänzung A29	Transponder, Garmin GTX 330	-	2002-03-20
Ergänzung E1	Digitale Uhr, LC-2	1	20-Apr-01
Ergänzung E2	Attitude Indicator, AIM 1100-28L(0F)	1	20-Apr-01
Ergänzung E3	Attitude Indicator, AIM 1100-28LK(0F) DIA	1	20-Apr-01
Ergänzung E4	Digitale Uhr, Model 803	-	2002-03-20
Ergänzung E7	Betrieb mit Winterverschluss Frischlufteinlass	1	27-Apr-05
Ergänzung O1	Verwendung als Schleppflugzeug	1	28-Nov-01
Ergänzung O2	Betrieb mit Winterkit	-	2001-11-26
Ergänzung S1	ELT, E-01	1	20-Apr-01
Ergänzung S4	406 MHz ELT Artex ME 406 und ME 406 'ACE'	1	10-Apr-07
TR-MÄM-40-766	Einsteigen und Verlassen des Flugzeugs	-	2014-07-05
TR-MÄM-40-816	Kraftstoff - Kontrollmesser	-	2015-11-18
TR-OÄM-40-375	Verstellbare Sitzlehne - Hydrolok	-	2015-04-23
TR-OÄM-40-401	Not - Ausstiegshammer	-	2017-03-13
<b>6.01.01-E</b>	<b>Airplane Flight Manual - English</b>	9	31-Jan-14
Supplement A1	COM/NAV, KX 125	1	20-Apr-01
Supplement A2	Intercom System PM 1000 II, PS Engineering Inc.	2	15-Mar-05
Supplement A3	Transponder, KT 76A	1	20-Apr-01
Supplement A4	GPS, KLN 89B	1	20-Apr-01
Supplement A5	CDI, KI 208	1	20-Apr-01
Supplement A6	GPS, KLN 94, VFR Operation	2	9-Sep-01
Supplement A7	Audio Amp./Intercom/Marker, KMA 28	1	20-Apr-01
Supplement A8	COM/NAV, KX 155A + KX 165A	2	3-Oct-01

### 6.05.01 Chapter 1 R5

# LIST OF APPLICABLE PUBLICATIONS

## MODEL DA 40

Supplement A9	Automatic Direction Finder, KR 87	2	17-Feb-03
Supplement A10	Distance Measuring Equipment, KN 62A	2	17-Feb-03
Supplement A11	Compass System KCS 55A Bendix/King	4	15-Mar-05
Supplement A12	Transponder KT 76C Bendix/King	2	15-Mar-05
Supplement A13	Autopilot System KAP140 Bendix/King	2	15-Mar-05
Supplement A14	GPS KLN 94 Bendix(King, IFR Operation	3	15-Mar-05
Supplement A15	GPS Annunciation Control Unit MD 41 MID-Continent	2	15-Mar-05
Supplement A16	MFD/GPS, KMD 150	-	2001-11-26
Supplement A17	COM/NAV/GPS, GNS 430	3	17-Feb-03
Supplement A18	Audio Panel, GMA 340	2	22-Jun-05
Supplement A19	Transponder GTX 327 Garmin	1	15-Mar-05
Supplement A20	Course Deviation Indicator GI 106A Garmin	1	15-Mar-05
Supplement A21	COM/NAV/GPS, GNS 530	1	15-Mar-02
Supplement A22	Strike Finder, SF 2000	-	2001-10-10
Supplement A23	GPS Annunciation Unit, MD 41-1488/1484	1	20-Dec-02
Supplement A24	Stormscope, WX-500	2	28-Feb-03
Supplement A25	Audio Panel GMA 340 Garmin, VFR Operation	2	15-Mar-05
Supplement A26	COM/NAV/GPS, GNS 430, VFR Operation	-	2002-08-02
Supplement A27	Ground COM #2 Switch	-	2002-04-05
Supplement A29	Transponder, Garmin GTX 330	-	2003-06-25
Supplement E1	Digital Chronometer, LC-2	1	20-Apr-01
Supplement E2	Attitude Indicator AIM 1100-28L(OF) BF Goodrich	2	15-Mar-05
Supplement E3	Attitude Indicator AIM 1100-28LK(OF) DIA BF Goodrich	2	15-Mar-05
Supplement E4	Digital Chronometer Model 803 Davtron	1	15-Mar-05
Supplement E7	Operation with Ventilation Inlet Baffle	1	27-Apr-05
Supplement N023	Operation in Brazil	-	2008-07-04
Supplement O1	Use as Tow-Plane	1	28-Nov-01
Supplement O2	Operation with Winter Kit	-	2001-11-26
Supplement S1	Emergency Locator Transmitter Model E-01 Ack	2	15-Mar-05
Supplement S2	ELT, JE2-NG	-	2001-06-01
Supplement S4	406 MHz ELT Artex ME 406 and ME 406 'ACE'	1	10-Apr-07

### 6.05.01 Chapter 1 R5

# LIST OF APPLICABLE PUBLICATIONS

## MODEL DA 40

TR-MÄM-40-766	Entering and Exiting the Airplane	-	2014-07-05
TR-MÄM-40-816	Alternate Means for Fuel Quantity Measure	-	2015-11-18
TR-OÄM-40-375	Front Seats with Adjustable Backrest - Hydrolok	-	2015-04-23
TR-OÄM-40-401	Emergency Egress Hammer	-	2017-03-13
TR-17-01	Change in Type Design Responsibility	-	2017-11-15
TR-MÄM-40-1020	Removal of Pilot Gust Lock Mount	-	2018-09-13
<b>6.02.01</b>	<b>Airplane Maintenance Manual</b>	7	2013-04-01
<b>6.02.01 Addendum 1</b>	<b>Transport Canada Approved AWL</b>	-	2017-11-15
AMM-TR-MÄM-40-475	Major Structural Inspection Interval	-	2013-01-23
AMM-TR-MÄM-40-617	Use of AVGAS 100	-	2013-08-26
AMM-TR-MÄM-40-619	Passenger Door Improvement	-	2016-05-12
AMM-TR-MÄM-40-635	Adjust Taxi Light Procedure	-	2013-02-21
AMM-TR-MÄM-40-650	Fuel Filter Element Check Valve	-	2013-06-18
AMM-TR-MÄM-40-680	Clarification Engine Maintenance	-	2013-06-17
AMM-TR-MÄM-40-709	Stall Warning System	-	2013-10-10
AMM-TR-MÄM-40-728	Lubrication Schedule	-	2013-11-04
AMM-TR-MÄM-40-760	Wiggins Clamp (Turbo Charger Clamp)	-	2014-06-24
AMM-TR-MÄM-40-785	Replacement of Passenger Door Hinges	-	2014-09-25
AMM-TR-MÄM-40-789	Turbo Charger Clamp	-	2014-12-17
AMM-TR-MÄM-40-792	Additional Elevator Mass	-	2015-02-11
AMM-TR-MÄM-40-806	Silicate Cartridge	-	2015-05-12
AMM-TR-MÄM-40-808	Inspection of NLG Elastomer Pack Center Tube	-	2015-07-08
AMM-TR-MÄM-40-824	New Type 6 Lubricants	-	2015-12-16
AMM-TR-MÄM-40-841	Fuel Tank Maintenance	-	2016-05-02
AMM-TR-MÄM-40-846	Door Handle Improvement	-	2016-12-07
AMM-TR-MÄM-40-860	Vent Line Routing	-	2016-06-28
AMM-TR-MÄM-40-865	Conservation of Exterior Parts	-	2017-05-08
AMM-TR-OÄM-40-063	Towing Device	-	2013-07-10
AMM-TR-OÄM-40-252	Front Seats with Adjustable Backrest	-	2013-05-15
AMM-TR-OÄM-40-348	Fuel Quantity of Filler Placard	-	2015-12-22

### 6.05.01 Chapter 1 R5

# LIST OF APPLICABLE PUBLICATIONS

## MODEL DA 40

AMM-TR-OÄM-40-369	Whelen LED Position / Anti Collision Lights	-	2013-11-06
AMM-TR-OÄM-40-375	Front Seats with Adjustable Backrest - Hydrolok	-	2015-04-27
AMM-TR-OÄM-40-401	Emergency Egress Hammer	-	2017-03-13
AMM-TR-MÄM-40-1018	Fuel Filter Element Check Valve	-	2018-08-14

### 6.03.01 Illustrated Parts Catalogue (IPC)

#### Service Bulletins

OSB40-01/2	Retrofit installation of design features	2	2-Dec-05
MSB40-02/1	ATA-Code 32; Replacement of the brake lines	1	25-Mar-02
OSB40-03/1	Retrofit installation for Night-VFR	1	24-Sep-01
OSB40-04/3	Retrofit installation for IFR operation	3	16-Jan-03
OSB40-05	Door lock for canopy and passenger door	-	10-Oct-01
OSB40-06	ELT Jolliet JE2-NG	-	10-Oct-01
MSB40-007/4	Exhaust system	4	16-Feb-05
RSB40-08	Airplane Flight Manual, Temporary revision	-	5-Mar-02
MSB40-09	DC Generator	-	30-Apr-02
OSB40-010/3	Long range fuel tank	3	21-Dec-09
RSB40-011/1	Starter Relay	1	17-Feb-03
MSB40-012	Mixture control cable	-	19-Jul-02
RSB40-013	Throttle cable control	-	27-Aug-03
OSB40-014	Landing gear	-	8-Nov-02
OSB40-015	Winterization kit	-	7-Jan-03
OSB40-016/3	Landing gear, Speed kit	3	16-Jun-06
MSB40-018/2	Autopilot KAP140	2	4-Dec-03
OSB40-021/2	CG adjustment	2	9-Oct-12
OSB40-022	Indicating and recording system	-	16-Jul-03
OSB40-024	Maplight cover	-	3-Nov-03
OSB40-025/1	Main landing gear struts	1	20-Mar-06
MSB40-026/1	Airplane Maintenance Manual, Temporary revision	1	30-Oct-03
OSB40-027	Installation of the "Slick Start" Ignition system	-	10-Dec-03
OSB40-028/1	Installation of baggage extension and baggage tray	1	16-Jun-06

### 6.05.01 Chapter 1 R5

# LIST OF APPLICABLE PUBLICATIONS

## MODEL DA 40

OSB40-029/1	Installation of maintenance access holes in rear seats	1	24-Jun-05
MSB40-030/3	Inspection of the universal joints between fuel selector handle and fuel selector valve	3	31-Jan-06
OSB40-031/1	Installation of Winter Baffle in Wing Fresh Air Inlet	1	16-Jun-06
MSB40-033	Exhaust System	-	15-Feb-05
OSB40-035/1	Installation of a sheep skin cover on the front seat	1	16-Jun-06
OSB40-037	Installation of maintenance access holes in front seats	-	23-May-05
RSB40-040	Exhaust system - improved installation	-	21-Jun-05
OSB40-042/1	Mechanical installation of a GARMIN GDL69/A XM Data Link system	1	21-Nov-05
OSB40-043/1	Mechanical installation of a Becker ADF3500 and or Honeywell KN63 DME	1	21-Nov-05
MSB40-044/1	Installation of muffler brace	1	11-Jan-06
RSB40-045	Installation of a EMI-Filter on the ELT Remote Control Cable	-	14-Oct-05
MSB40-046/3	Inspection of the nose landing gear leg	3	17-Nov-08
RSB40-047/4	Replacement of the Right Hand Aileron	4	4-Nov-14
MSB40-048/2	Contamination in Engine Fuel System	2	26-Sep-06
OSB40-050	Installation of external static pressure source for KAP140 autopilot system	-	30-Oct-06
RSB40-052	Seal between the firewall shield and the fuselage	-	25-Feb-10
MSB40-054/1	Reinforcement of the pitot, static and stall warning line installation	1	27-Aug-08
OSB40-057/2	Increase of Take-Off Mass to 1200 kg, Adjustment of Elevator Travel and Replacement of Limitations Placard	2	3-Sep-13
MSB40-058	Installation of the inline 100 ohm resistor, on the AUX line of the alternator, on a circuit board	-	14-Feb-08
OSB40-059	Installation of Taller Main Landing Gear	-	19-Jul-07
MSB40-060/1	Wing Skin to Spar Bond	1	21-Dec-09
OSB40-061/1	Maintenance Access Holes in the Elevator	1	3-Feb-16
OSB40-062	Installation of the Artex ME406 "ACE" ELT	-	1-Apr-09
MSB40-064	Replacement of Jumper Wires	-	16-Nov-09
OSB40-066	Installation of Large Rudder	-	23-Feb-10
MSB40-067	Check of emergency exit lever	-	14-Jul-10
OSB40-069	Installation of a coated safety walk	-	20-Jul-10
MSB40-070/1	Replacement of Passenger Door Retaining Bracket incl. WI Rev. 1	1	17-Jan-11
OSB40-072	Installation of a reinforced nose wheel fork	-	14-Nov-11

### 6.05.01 Chapter 1 R5

# LIST OF APPLICABLE PUBLICATIONS

## MODEL DA 40

OSB40-073	Installation of a tall canopy bubble to the existing canopy frame	-	8-Jan-13
MSB40-074	Reinforcement of aft main spar	-	10-May-13
OSB40-075/1	Use of Avgas 100	1	26-Sep-13
OSB40-076	Installation of CO Detector P/N 452-201-010 as a replacement for P/N 452-201-004	-	31-Oct-13
OSB40-077	Installation of LED Taxi and Landing Lights	-	25-Jun-14
RSB40-078	Installation of permanent maintenance access holes in wings	-	9-Oct-14
OSB40-079	Installation provisions for a safety mesh to protect the fuel vent covers into the wings	-	2-Dec-14
RSB40-082/1	Inspection of NLG elastomer pack center tube	1	16-Dec-15
RSB40-083	Replacement of steel pin of door handle mechanism of canopy and passenger door with an improved design	-	14-Jun-17
OSB40-084	Installation of COM/GPS Antenna	-	16-Apr-18
MSB40-085/1	Removal of Pilot Gust Lock Mount	1	2018-11-20

### Service Information Letters

SI40-001/3	Descriptions of DAI technical publication systems and handling of documents	3	28-Aug-17
SI40-002	Engine Driven Fuel Pump	-	29-Mar-01
SI40-003	Vision Microsystem VM 1000	-	19-Apr-01
SI40-004/1	KLN 94 GPS Navigation System	1	12-Jun-03
SI40-005	Fuel line and support clamp	-	23-Aug-01
SI40-006	Exhaust system	-	19-Oct-01
SI40-007	Garmin GNS 430	-	18-Feb-02
SI40-008	Vision Microsystem, Engine indication	-	2-May-02
SI40-009	Lycoming Engine	-	22-Jan-03
SI40-010	Lycoming Engine	-	20-May-03
SI40-013/1	MT-Propeller	1	6-Nov-03
SI40-014	Doors	-	21-Apr-04
SI40-015	Autopilot KAP 140; Honeywell installation bulletin no. 511	-	8-Oct-04
SI40-016	Garmin GTX 330; Mandatory Software Service Bulletin No. 0409	-	14-Oct-04
SI40-017	Lycoming Engine Diaphragm-Type Fuel Pump Inspection/Replacement	-	3-Mar-05
SI40-018	Navigational Information provided by Garmin GNS 430 & GNS 530	-	7-Mar-05

### 6.05.01 Chapter 1 R5

# LIST OF APPLICABLE PUBLICATIONS

## MODEL DA 40

SI40-019	Garmin GNS 430 Service Alert	-	11-Apr-05
SI40-020	Software Upgrade for Garmin 500 Series Units	-	17-May-05
SI40-021	Software Upgrade for Garmin 400 Series Units	-	17-May-05
SI40-022	Garmin Service Alert - Direct-To waypoint selection	-	1-Aug-05
SI40-023	Lycoming-MSB-548A - Diaphragm-Type fuel pump inspection/replacement	-	8-Sep-05
SI40-025	EASA AD 2005-0023, Lycoming SB and SI for Exhaust valve and guide - Inspection	-	8-Nov-05
SI40-026	Garmin G1000 System Software Version Update	-	14-Nov-05
SI40-027	Inspection of the nose landing gear leg - ACG-AD	-	24-Nov-05
SI40-028	GDL 69/69A Software upgrade	-	10-Jan-06
SI40-029	GTX 327 or GTX 32 Software upgrade	-	31-Jan-06
SI40-030	FAA-AD 2005-26-10 and ECI SB, Replacement of classic cast cyl.	-	28-Feb-06
SI40-031	Lycoming SB and SI for Exhaust valve and guide - Inspection	-	24-Mar-06
SI40-032	EASA-AD: Inspection / Replacement of the fuel selector / fuel valve universal joints	-	27-Mar-06
SI40-033	Garmin GNS 430/430A use of additional TERRAIN functionality	-	25-Apr-06
SI40-034	Garmin GNS 530/530A use of additional TERRAIN functionality	-	25-Apr-06
SI40-035	Garmin SB: GTX 330/GTX 330 D new Software Version	-	4-May-06
SI40-036	Garmin GNS 430/430A and GNS 530/530A use of additional TERRAIN functionality	-	23-May-06
SI40-037	FAA AD 2006-12-07 and ECI SB for Replacement of classic cast cylinders	-	20-Jun-06
SI40-038	Garmin GDL 69/69A XM Satellite Datalink Storm Cell Tracking Limitation	-	27-Jun-06
SI40-039	Garmin 500 Series TAWS Inhibit Mode Functionality	-	22-Aug-06
SI40-040	Garmin G1000 System Software Version Update	-	12-Sep-06
SI40-041	Contamination of the Engine Fuel System - Inspection	-	27-Sep-06
SI40-042	Garmin G1000 System Software Version Update	-	11-Oct-06
SI40-043	Garmin G1000 System Software Version Update	-	23-Nov-06
SI40-044	Garmin G1000 SB New Magnetic Field Model	-	11-Jan-07
SI40-045	Garmin SA, Multiple Initial Approach Fixes in the Transition List	-	22-Jan-07
SI40-046	ACK Service Bulletin SB E-01.9	-	22-Jan-07
SI40-047	Garmin SB, SW Version 5.02 for GNS 430/530 Series Units	-	22-Jan-07

### 6.05.01 Chapter 1 R5



# LIST OF APPLICABLE PUBLICATIONS

## MODEL DA 40

SI40-048/a	Garmin SB, SW Upgrade to Version 4.06 for GTX 330/330D and GTX 33/33D, non-G1000 applications only	-	7-Feb-07
SI40-049	Electronic Checklist	-	31-Jan-07
SI40-050	Garmin Service Alert 070227-00	-	2-Mar-07
SI40-052/1	Garmin SB No. 0713 Rev. D, inspection of GSM 85 servo gearbox	1	6-May-08
SI40-053	Garmin SB No. 0710 Rev. A, Hardware Changes to GTX 33/33D units	-	29-May-07
SI40-054	Garmin SB No. 0714 Rev. A, Hardware Changes to GTX 330/330D units	-	29-May-07
SI40-055	Garmin SB No. 0702 Rev. A, GLD 69/69A Software Upgrade to Version 3.10	-	11-Jun-07
SI40-056	Garmin SB No. 0713 Rev. D, inspection of GSM 85 servo gearbox	-	20-Jun-07
SI40-057/1	Garmin Service Alert 070801-00	-	23-Aug-07
SI40-058	Garmin Service Advisory 070816-00, GRS 77	-	17-Aug-07
SI40-059	not issued yet		0-Jan-00
SI40-060	Garmin Service Bulletin No. 0705, Main Software Version 6.03 for 500 Series Units	-	7-Sep-07
SI40-061	Garmin Service Bulletin No. 0735, GRS 77	-	10-Sep-07
SI40-062/1	Garmin Service Bulletin No. 0736B, G1000 System ID Tool	1	21-Dec-07
SI40-063	Garmin Software Service Bulletin No. 0730 Rev. A	-	25-Sep-07
SI40-064	Garmin Software Service Bulletin No. 0739	-	22-Oct-07
SI40-066	Garmin Service Bulletin No. 0738 Rev. B, Transient Voltage Suppressor	-	23-Oct-07
SI40-067	Garmin Software Service Bulletin No. 0739B	-	21-Dec-07
SI40-068	Garmin Software Service Bulletin No. 0706	-	21-Dec-07
SI40-069	Garmin Software Service Bulletin No. 0739 Rev. C	-	28-Nov-07
SI40-070	not issued yet		0-Jan-00
SI40-071	Garmin Service Alert No. 0801, Supplemental Data Cards	-	11-Feb-08
SI40-072	Precision Airmotive LLC Safety Alert	-	5-Mar-08
SI40-073	FAA Emergency AD: Inspections and if necessary corrective actions	-	14-Mar-08
SI40-075	FAA AD: Inspection and if necessary corrective actions	-	18-Apr-08
SI40-076	Garmin Service Alert No. 0811, Flight Plan Sequencing Issue	-	21-Apr-08
SI40-079	Garmin Service Alert No. 0816, Forward Looking Terrain Avoidance (FLTA)	-	9-May-08
SI40-080	Garmin Service Alert No. 0817, Forward Looking Terrain Avoidance (FLTA)	-	13-May-08

### 6.05.01 Chapter 1 R5

# LIST OF APPLICABLE PUBLICATIONS

## MODEL DA 40

SI40-081/1	Honeywell Service Bulletin KAP 140-22-102, Reduce the possibility of intermittent failures because of top cover on KC 140	1	27-Oct-08
SI40-082/1	Honeywell Service Bulletin KC 140-22-102, Replace top cover to make sure connector pins engage correctly	1	27-Oct-08
SI40-083	Garmin Service Bulletin No. 0823, GDU 104X CRS/BARO Knob Interference	-	11-Jul-08
SI40-084	Garmin Service Alert No. 0824, GDU 104X CRS/BARO Knob Interference	-	11-Jul-08
SI40-085	Garmin Service Advisory No. 0825, LPV and LNAV/VNAV approaches with three-character airport identifiers	-	25-Jul-08
SI40-086	Garmin Service Bulletin No. 0823 Rev. B, GDU 104X CRS/BARO Knob Interference	-	5-Aug-08
SI40-087	Garmin Service Alert No. 0824 Rev. B, GDU 104X CRS/BARO Knob Interference	-	5-Aug-08
SI40-088	FAA AD: Inspection and if necessary replacement of externally mounted fuel injector fuel lines	-	29-Jul-08
SI40-089	Garmin Service Advisory No. 0826 Rev. A, Traffic symbols on GDU displays with SVT (Synthetic Vision Technology)	-	11-Aug-08
SI40-090	Garmin Service Advisory No. 0831 Rev. A, Automatic approach course selection	-	21-Aug-08
SI40-091	Garmin Service Advisory No. 0829 Rev. A, SVT runway will appear higher or lower than the actual runway	-	17-Nov-08
SI40-092	Garmin Service Advisory No. 0826 Rev. B, , Traffic symbols on GDU displays with SVT (Synthetic Vision Technology) may appear to be cropped	-	17-Nov-08
SI40-093	Garmin Service Advisory No. 0838 Rev. A, GPS/WAAS Loss of Reception	-	17-Nov-08
SI40-094	Honeywell-SB KS 270C-22-09, Exchange of the tach generator	-	27-Oct-08
SI40-095	Honeywell-SB KS 271C-22-10, Exchange of the tach generator	-	27-Oct-08
SI40-097	Garmin Software Service Bulletin No. 0845, New Software for (non-WAAS) 500 Series Units	-	18-Dec-08
SI40-098	Garmin Software Service Bulletin No. 0846 Rev. A, GTX 330/330D and GTX 33/33D Software Version 6.00 Non-G1000/G900X Applications Only	-	9-Dec-08
SI40-099	EASA-AD: Wings - Upper Wing Skin-to-Main Spar Adhesive Joint - Inspection/Repair	-	18-Dec-08
SI40-100	EASA-AD: Nose Landing Gear Leg - Inspection / Replacement	-	3-Feb-09
SI40-101	FAA-AD: Inspection and if necessary corrective actions	-	3-Feb-09
SI40-102	Garmin Service Advisory No. 0904 Rev. A, Synthetic Vision Technology (SVT)	-	6-Feb-09
SI40-104	Garmin Service Advisory No. 0908 Rev. A, Garmin Integrated Flight Deck Systems Equipped with the Honeywell Model KN63 DME	-	16-Mar-09
SI40-105	Garmin Software Service Bulletin No. 0846 Rev. B, GTX 330/330D and GTX 33/33D Software Version 6.00 Non-G1000/G900X/GNS480 Applications Only	-	12-Mar-09

### 6.05.01 Chapter 1 R5

# LIST OF APPLICABLE PUBLICATIONS

## MODEL DA 40

SI40-106	Garmin Service Advisory No. 0914 Rev. A, Possible temporary loss of heading/ attitude information	-	8-May-09
SI40-107	Garmin Service Advisory No. 0915 Rev. A, Navigation suspending during non-precision approaches	-	11-May-09
SI40-108	FAA-AD: Nose Landing Gear Leg - Inspection / Replacement	-	19-May-09
SI40-109	Garmin Service Advisory No. 0912 Rev. A, SBAS Operations in Australia, New Zealand and South Pacific Regions	-	4-Jun-09
SI40-110	Garmin Service Advisory No. 0922 Rev. A, VOR or LOC/ILS Approaches	-	8-Jul-09
SI40-111	Garmin Service Advisory No. 0929 Rev. A, Momentary failure indications (Red-X) can occur when deleting stored data	-	13-Jul-09
SI40-112	Illustrated Parts Catalogue (IPC) - Change of the available media	-	5-Oct-09
SI40-113	Garmin Service Bulletin No. 0919 Rev. A, G1000 System Software Update	-	5-Oct-09
SI40-114	Garmin Service Advisory No. 0944 Rev. A, SVT Pathways may be displayed at a higher altitude than expected	-	5-Oct-09
SI40-115	Garmin Mandatory Service Bulletin No. 0823 Rev. C, GDU 104X CRS/BARO Knob Interference	-	9-Dec-09
SI40-116	Garmin Service Alert No. 0824 Rev. C, GDU 104X CRS/BARO Knob Interference	-	9-Dec-09
SI40-117	FAA-AD: To prevent failure of the propeller hub causing blade separation and subsequent loss of airplane control	-	11-Dec-09
SI40-118	FAA-AD: To prevent loss of engine power due to cracks at the head-to-barrel interface and possible engine failure caused by separation of a cylinder head	-	22-Feb-10
SI40-118/1	FAA-AD: To prevent loss of engine power due to cracks at the head-to-barrel interface and possible engine failure caused by separation of a cylinder head	1	1-Mar-10
SI40-119	Onic Service Bulletin DES-353 Rev. A	-	18-Feb-10
SI40-120	FAA-AD: To prevent loss of propeller pitch control, damage to the propeller governor, and internal damage to the engine	-	6-Jul-10
SI40-121/1	EASA-AD: Rear passenger door retaining bracket - Replacement	1	4-Mar-14
SI40-122	FAA-AD: Passenger door retaining bracket - Replacement	-	17-Dec-10
SI40-123	Garmin Service Advisory No. 1051 Rev. A & Software Service Bulletin No. 0533 Rev. B, 2010 IGRF (International Geomagnetic Reference Field) Magnetic Field Model	-	16-Feb-11
SI40-124	Garmin Service Advisory No. 1118 Rev. A, Momentary failure indications (Red-X) can occur when sorting stored flight plans	-	17-May-11
SI40-125	Garmin Service Advisory No. 1129 Rev. A, Momentary loss of GRS 77/77H and GDC 74A/74B/74H functions	-	31-May-11

### 6.05.01 Chapter 1 R5

# LIST OF APPLICABLE PUBLICATIONS

## MODEL DA 40

SI40-126	FAA-AD: Removal of the fuel servo in reference to AVStar Fuel Systems Mandatory Service Bulletin AFS-SB6	-	16-Aug-11
SI40-127	FAA-AD: To prevent failure of the fuel injector fuel lines that would allow fuel to spray into the engine compartment, resulting in an engine fire	-	22-Dec-11
SI40-128	FAA-AD: Removal of the fuel servo in reference to AVStar Fuel Systems Mandatory Service Bulletin AFS-SB6 Rev. 2	-	10-Feb-12
SI40-129	FAA-AD: Inspection/Repair/Replacement of certain "machined from billet" Volare LLC HA-6 carburetors	-	23-Feb-12
SI40-130	Garmin Service Alert No. 1228, SIDs and STARs non-JETs Limitation	-	6-Nov-12
SI40-131/1	EASA-AD: Inspection of the markings of the safety belts	1	8-Apr-14
SI40-132	MT-Propeller Service Bulletin No. 27, Inspection and modification of certain governor type- and serial numbers	-	28-Feb-13
SI40-133	Garmin Service Advisory No. 1309, Verification of displayed heading is not noticeable drifting prior Take-Off	-	4-Mar-13
SI40-134	Garmin Service Advisory No. 1309 Rev. B, Verification of displayed heading is not noticeable drifting prior Take-Off	-	12-Apr-13
SI40-135	Identification of stainless steel control cables	-	17-Jun-13
SI40-136	EASA-AD: Modification of the aft main spar in the cabin area	-	18-Jul-13
SI40-137/1	Garmin Terrain Data Alert No. 1351 Rev. B, Anomalies when using Synthetic Vision Technology in Northwest Greenland	1	3-Mar-15
SI40-138	Garmin Service Advisory No. 1352 Rev. A, Course deviation indicator (CDI) may deflect in the wrong direction in certain situations	-	26-Sep-13
SI40-139	Garmin STC Service Bulletin No. 1334 Rev. A, update of G1000 equipped aircraft to G1000 System Software Version 0321.23	-	24-Oct-13
SI40-140	United Instruments Inc. Service Bulletin No. 12, Paint on dial may crack and separate from the surface	-	31-Oct-13
SI40-141	Garmin Service Advisory No. 1363 Rev. A, User-modified terminal procedure stored in a Flight Plan may cause error condition	-	21-Nov-13
SI40-142	FAA-AD: Modification of the aft main spar in the cabin area	-	5-Dec-13
SI40-143	Garmin Service Advisory No. 1344 Rev. B, LPV and LNAV/VNAV Approach Full Scale Deflection	-	18-Dec-13
SI40-144	Garmin Service Advisory No. 1372 Rev. A, Unavailable RNAV (GPS) approaches due to lack of VDA	-	18-Dec-13
SI40-145/1	Andair GAS375 Gascolator Filters	1	25-Jun-14
SI40-146	FAA-AD: Modification of the aft main spar in the cabin area	-	27-Aug-14
SI40-147	Lycoming Service Bulletin No. 615 Diaphragm-Type Fuel Pump Replacement	-	7-Jan-15

### 6.05.01 Chapter 1 R5

# LIST OF APPLICABLE PUBLICATIONS

## MODEL DA 40

SI40-148	Lycoming Service Bulletin No. 617 Diaphragm-Type Fuel Pump Replacement	-	9-Feb-15
SI40-150	Garmin Service Alert No. 1538 Rev. A, Operations with Altimeter Set to QFE (height above field elevation)	-	12-Aug-15
SI40-151	Andair Service Alert: Certain fuel valve systems with extension may have a possible lack of engagement between the universal joint assembly and the top of the valve assembly	-	17-Sep-15
SI40-152	FAA-AD: Inspection, replacement if necessary, and proper clamping of externally mounted fuel injector fuel lines	-	1-Oct-15
SI40-153	Garmin STC Service Bulletin No. 1534 Rev. A, Installation instructions for a G1000 configuration update that prevents the loss of Engine Indication System	-	1-Mar-16
SI40-154	United Instruments Inc. SB No. 13, Specific 5934 Series Altimeters manufactured between January 2015 and February 2016 are susceptible to develop a slow diaphragm leak which would affect the accuracy of the altimeters	-	29-Apr-16
SI40-155	Garmin Service Advisory No. 1372 Rev. B, unavailable RNAV (GPS) approaches	-	24-Jun-16
SI40-156	Garmin Service Advisory No. 1612 Rev. A, Update of the IGRF (International Geomagnetic Reference Field) Magnetic Field Model from base year 2010 to 2015	-	19-Sep-16
SI40-157	Lycoming Service Bulletin No. 612, Oil Level Gage Replacement	-	10-Jan-17
SI40-158	FAA-AD: Certain altimeters displaying higher than actual altitude due to a slow diaphragm leak which were examined in United Instruments SB No. 13	-	24-Mar-17
SI40-159	Lycoming Service Bulletin No. 632, Identification of Connecting Rod assemblies or Connecting Rod Bushings on certain engine serial numbers	-	21-Jul-17
SI40-160	FAA-AD: Inspection of connecting rods and replacement of affected connecting rod small end bushing	-	29-Aug-17
SI40-161	Slick SB No. SB1-15A - Potential decreased service life of Slick magneto distributor gear assemblies	-	10-Jan-19
SIDA40-002	Change in Type Design Responsibility	-	15-Nov-17

### 6.05.01 Chapter 1 R5