

Diamond Aircraft Industries GmbH N. A. Otto-Straße 5 2700 Wiener Neustadt Austria

DAI OSB 40-076 DAI OSB F4-030 Page 1 of 3 31-Oct-2013

OPTIONAL SERVICE BULLETIN OSB 40-076 OSB F4-030

I TECHNICAL DETAILS

I.1 Category

Optional.

I.2 Airplanes affected

Type: DA 40, DA 40 F

Serial numbers: 40.696 and subsequent

40.F001 and subsequent 40.FC001 and subsequent

I.3 Date of effectivity

31-Oct-2013

I.4 Time of Compliance

At owner's discretion

I.5 Subject

Installation of CO Detector P/N 452-201-010 as a replacement for P/N 452-201-004.

ATA-Code: 31-00

I.6 Reason

The CO Detector P/N 452-201-004 is no longer available from the manufacturer. This Service Bulletin describes the installation of CO Detector P/N 452-201-010 as a replacement for P/N 452-201-004.

I.7 Concurrent Documents

None.

I.8 Approval

The technical information or instructions contained in this document relate to the Design Change Advisory No. MÄM 40-281, OÄM 40-222, OÄM 40-253, which have been approved under the authority of EASA Design Organization Approval ref. EASA.21J.052.

The technical content of this document has been approved under the authority of DOA ref. EASA.21J.052.



Diamond Aircraft Industries GmbH N. A. Otto-Straße 5 2700 Wiener Neustadt Austria

DAI OSB 40-076 DAI OSB F4-030 Page 2 of 3 31-Oct-2013

I.9 Accomplishments / Instructions

Comply with WI-OSB 40-076 / WI-OSB F4-030, latest effective issue.

I.10 Mass (Weight) and CG

No change.

II PLANNING INFORMATION

II.1 Material and Availability

See WI-OSB 40-076 / WI-OSB F4-030, latest effective issue.

II.2 Special Tools

None.

II.3 Labour Effort

Approx. 1hours.

II.4 Credit

None.

II.5 Reference Documents

DA 40 Series Airplane Maintenance Manual, Doc. No. 6.02.01, latest effective issue.

III REMARKS

- 1. All work must be done by a certified aircraft service station or a certified aircraft maintenance mechanic.
- 2. All work, in particular that which is not especially described in this Service Bulletin, must be done in accordance with the referenced Maintenance Manual.
- Completion of all work must be recorded in the log book.
- 4. In case of doubt contact Diamond Aircraft Industries GmbH.



Diamond Aircraft Industries GmbH N. A. Otto-Straße 5 2700 Wiener Neustadt Austria

DAI OSB 40-076 DAI OSB F4-030 Page 3 of 3 31-Oct-2013

EXECUTION REPORT TO SERVICE BULLETIN OSB 40-076 OSB F4-030

Date, Name, Sign		
Typical operation of airplane	private, club, training, other	
Hours of operation-engine		
No. of landings		
Hours of operation of airplane		
Airplane Operator		
Airplane Registration		
Airplane Serial Number		
AIRPLANE INFORMATION		

Please fax the completed form to Fax No. +43-2622-26700-1369 or e-mail to airworthiness@diamond-air.at