

OPTIONAL SERVICE BULLETIN NO. OSB 40-088 REV. 1
SUPERSEDES OSB 40-088 REV. 0

I TECHNICAL DETAILS

I.1 Category

Optional

I.2 Airplanes Affected

Type: DA 40

Serial Numbers: 40.006 through 40.009, 40.011 through 40.079, 40.081 through 40.083, 40.085 and subsequent

I.3 Date of Effectivity

31 August 2020

I.4 Time of Compliance

At owner's discretion.

I.5 Subject

Installation of LED position lights and anti-collision lights (ACLs).

ATA Code: 33-40

I.6 Reason

LED position and ACLs have been approved for installation on DA 40 aircraft. This service bulletin describes the installation on airplanes in service.

I.7 Concurrent Documents

None

I.8 Approval

The technical information and instructions contained in this document relate to Design Change Advisory No. OÄM 40-369, and are approved as part of the type design.

I.9 Accomplishment/Instructions

See WI-OSB 40-088, latest effective issue.

I.10 Mass (Weight) and CG

See WI-OSB 40-088, latest effective issue.

II PLANNING INFORMATION

II.1 Material and Availability

See WI-OSB 40-088, latest effective issue.

II.2 Special Tools

None.

II.3 Labour Effort

Appr. 2 hours.

This estimate is for direct labour performed by a technician, and it does not include setup, planning, familiarization, cure time, part fabrication, or tool acquisition.

II.4 Credit

None.

II.5 Reference Documents

DA 40 Airplane Maintenance Manual, Doc. No. 6.02.01, latest effective issue.

III REMARKS

1. All work must be completed by the appropriate authorized personnel.
2. All work, particular that, which is not especially described in this service bulletin, must be done in accordance with the referenced maintenance manual.
3. Completion of all work must be recorded in the logbook.
4. In case of doubt, contact Diamond Aircraft Industries.

To obtain satisfactory results, procedures specified in this service bulletin must be accomplished in accordance with accepted methods and current government regulations. Diamond Aircraft cannot be responsible for the quality of work performed in accomplishing the requirements of this service bulletin. Diamond Aircraft reserves the right to void continued warranty coverage in the area affected by this service bulletin if it is not incorporated.

If you no longer own the aircraft to which this service bulletin applies, please forward it to the current owner and send the name of the current owner to Diamond Aircraft at the address below.

Diamond Aircraft Industries Inc.
1560 Crumlin Sideroad, London, Ontario, Canada
N5V 1S2

Customer Support:
Phone: (519) 457-4041, Fax: (519) 457-4045
E-mail: support-canada@diamondaircraft.com

Technical Publications:
E-mail: techpubs@diamondaircraft.com



**EXECUTION REPORT TO
SERVICE BULLETIN
OSB 40-088 REV. 1**

AIRPLANE DATA

Airplane serial number _____

Airplane registration _____

Airplane operator _____

Hours of operation airplane (TSN) _____

Typical operation of airplane private, club, training, other: _____

MAINTENANCE DATA:

Date of work _____

Work performed by _____

Date _____

Name _____ Signature _____

Please e-mail the completed form to Techpubs@diamondaircraft.com