

SERVICE INFORMATION NO. SI40-002

I. TECHNICAL DETAILS

1.1 Airplanes affected:

DA 40: all airplanes equipped with a Lycoming IO360 engine

1.2 Subject:

engine driven fuel pump (Diaphragm-Type Fuel Pump)

ATA-Code: None

1.3 Reason:

Due to quality problems of fuel pumps, Lycoming requires a fuel pump inspection and if affected a fuel pump replacement. This is published in the **Lycoming Mandatory Service Bulletin No. 548**.

1.4 Information:

For detailed information about the affected fuel pumps and a description of the inspection and replacement and the time of compliance see the attached Lycoming SB 548.

II. OTHERS

Lycoming SB 548 is attached to this Service Information.

Orders of spare parts and applications for reimbursement should be addressed directly to the nearest Textron Lycoming Distributor.