

SERVICE INFORMATION NO. SI40-005

I. TECHNICAL DETAILS

1.1 Airplanes affected:

DA 40: all airplanes

1.2 Subject:

Fuel line (Stainless Steel Tube Assy.) and Support Clamp Inspection and Installation

ATA-Code: None

1.3 Reason:

Check of fuel lines due to the occurrence of fuel line breakage.

For detailed information see the attached **TEXTRON Lycoming Mandatory Service Bulletin No. 342D**

1.4 Information:

For detailed information about the affected equipment and a description of the necessary action see **Mandatory Service Bulletin No. 342D**

II. OTHERS

Lycoming Mandatory Service Bulletin 342D is attached to this Service Information.