

## **SERVICE INFORMATION NO. SI40-010**

### **I. TECHNICAL DETAILS**

#### **1.1 Airplanes affected**

DA 40, all serial numbers with Lycoming engines.

#### **1.2 Subject**

Engine fuel and control.

ATA-Code: 73-00

#### **1.3 Reason**

Service Bulletin PRS-105 from PRECISION AIRMOTIVE CORPORATION according to the repair of certain fuel injection servos of the RSA-5 series.

#### **1.4 Information**

The Service Bulletin PRS-105 from PRECISION AIRMOTIVE CORPORATION and especially the time of compliance (item C. in the Service Bulletin PRS-105) must be considered.

The Service Bulletin PRS-105 from PRECISION AIRMOTIVE CORPORATION is applicable without any restrictions. No further work will be necessary on the aircraft itself.

### **II. OTHERS**

The Service Bulletin PRS-105 is attached to this Service Information.



**PRECISION**  
AIRMOTIVE CORPORATION

14800 40<sup>th</sup> Avenue NE  
MARYSVILLE, WASHINGTON 98271  
FAA-PMA FACILITY #PQ111NM

# Service Bulletin Fuel Systems

Bulletin No.: FRS-105

Date 5/6/03

**SUBJECT: SERVO METERED FUEL PRESSURE PORT LEAKAGE**

## **SECTION I - PLANNING INFORMATION**

### **A. EFFECTIVITY:**

All RSA-5, and RSA-10 series Fuel Injection Servos manufactured, overhauled, rebuilt, or repaired by Precision Airmotive Corporation (PAC) between January 30, 2003, and April 24, 2003. A serial number listing is included in section II.

### **B. REASON:**

A number of fuel injection servos have been found to seep fuel from the metered fuel pressure port, due to scoring caused by a damaged test fitting. This bulletin identifies affected servos and provides information for repair.

### **C. COMPLIANCE:**

Within the next 10 hours of flight, but no later than July 1, 2003.

## **SECTION II - IDENTIFICATION OF AFFECTED SERVOS**

### **A. SERVOS MANUFACTURED, OVERHAULED, REBUILT, OR REPAIRED BY PRECISION AIRMOTIVE:**

The following serial number listing identifies fuel injection servos which were processed by PAC during the applicable time period, and have not yet been recovered by PAC (as of 5/5/03). Servos which have been corrected by PAC will be identified with an "M" stamped on the lower right corner of the data tag.

Part Number	Serial Number(s)
2524054-11	70287001
	70287002
	70287003
	70287004
	70287005
	70287006
	70287007
	70287008
	70287009
	70287010
	70307501
	70307502
	70307503
	70307504
	70313201

Part Number	Serial Number(s)
2524054-11 (Continued)	31121
	37957
	40376
	47291
	47331
	47356
	51273
	54867
	59147
	61491
	71233
80691	
210063	
961610	
1768641	

Part Number	Serial Number(s)
2524054-11 (Continued)	1989442
	70044909
	70098509
	70122603
	70122705
	70132807
	70135305
	70162808
	70190407
	87171247
	87171248
	88012053
	8163
	33067
	34539

Part Number	Serial Number(s)
2524054-11 (Continued)	55753 70177 1126638 70002304 70079204 70102208
2524147-13	87261334
2524163-15	22138 25099 26780 29848 34119 37739 45177 49989 54239 62444
2524213-11	33767
2524273-12	70283906 70279901L 70279902R 3510 18805 42936 45499 66750 68160 75994 70111203 70118608 85000 70253502
2524275-16	23745
2524291-11	73273 70053303 60008 63409 29808124
2524297-10	70267808 14889 24383
2524307-10	16874
2524311-10	29840
2524318-10	70274304 70313401 70178202
2524335-10	673320
2524422-9	70343301 70343302 70343303 70343304 70343305 70343306
2524450-9	70287301 70287302 70287303 70287304 70287305 70287308 70287307

Part Number	Serial Number(s)
2524450-9 (Continued)	31797 36496 39000 41530 41834 44025 45371 53602 61398 68562 70193704 70204504
2524500-9	70259605R 77635 70020104 70096708
2524556-9	19114 37257 60938 73501 77566 81445 82140 84542 137794 70176008 70253503 77583
2524590-8	61489 67597 87501887
2524592-8	70028507
2524649-11	70036003
2524752-7	70323501 70323502 70323503 70323504 70323505 70323506
2524791-7	77684
2524858-5	70279602 70279603 70288101 70288102 70288103 70288104 70288105
2524863-1	70286901 70286902
2524938-2	70351701 1793413
2524979-1	70267504 70287901
2549006-1	70288001
2549036-3	70253805 70263003 70002703 70007810

Part Number	Serial Number(s)
2549038-3 (Continued)	70025103 70090007 70111507 70113810 70133404 70136406 70139406 70148509 70149610 70151101 70151102 70151110 70152903 70152909 70154608 70166904 70167003 70167004 70188406 70188408
2576524-2	70286603
2576536-2	70280709 70282504 70283405 70286801 70286802 70286803 70286804 70286805 70286806 70286807 70286808 70286809 70286810 70287501 70287502 70287503 70287504 70287505 70287506 70287507 70287508 70287509 70287510 70288201 70288202 70288203 70288204 70288205 70288206 70288207 70288208 70288209 70288210 70288401 70288402 70288403 70288404 70288405 70288406 70288407

Part Number	Serial Number(s)
2576536-2 (Continued)	70288408
	70288409
	70288410
	70288701
	70288702
	70288703
	70288704
	70306901
	70306902
	70306903
	70306904
	70306905
	70306906
	70306907
	70306908
	70306909
	70306910
	70307201
	70307202
	70307203
	70307204
	70307205
	70307206
	70307207
	70307208
	70307209
	70307210
	70307301
	70307302
	70307303
	70307304
	70307305
	70307306
	70307307
	70307308
	70307309
	70307310
	70315701
	70315702
	70315703
	70315704
	70315705
	70315706
	70315707
	70315708
	70315709
	70315710
	70325401
	70325402
	70325403
	70325404
	70325405
	70325406
	70325407
	70325408
	70325409
	70325410
70325501	
70325502	
70325503	
70325504	

Part Number	Serial Number(s)	
2576536-2 (Continued)	70325505	
	70325506	
	70325507	
	70325508	
	70325509	
	70325510	
	70345501	
	70345502	
	70345503	
	70345504	
	70345505	
	70345506	
	70345507	
	70345508	
	70345509	
	70244804	
	70283304	
	70132609	
	70132610	
	70135606	
	70145210	
	70145401	
	70146406	
	70149001	
	70194702	
	70200704	
	70137904	
	70131607	
	70131807	
	70149007	
	70177908	
	2576540-7	70280503
		70283601
		70283602
		70283603
		70283604
		70283605
		70283606
		70283607
		70283608
		70283609
	70283610	
	2576542-1	70326101
		70326102
		70328201
		70328202
		70328203
	70328204	
2576544-2	70277606	
	70287201	
	70287202	
	70287203	
	70287204	
	70287205	
	70287206	
	70287207	
	70287208	
	70287209	
	70287210	
	70320001	
	70320002	

Part Number	Serial Number(s)
2576544-2 (Continued)	70320003
	70320004
	70320005
	70320007
	70320008
2576554-2	70185905
	70269605
	70273706
	70273709
	70273710
	70282402
	70288301
	70288302
	70288303
	70288304
70288305	
70288307	
70259705	
70139409	
2576562-2	70210410
	70262804
	70264603
	70288106
	70276407
2576568-1	70271007
	70288501
	70288502
	70288503
	70288504
	70288505
	70288506
	70288507
	70305203
	70305205
	70305206
	70305207
	70305208
	70305209
	70305210
70332601	
70332602	
70332603	
70332604	
70332607	
70332608	
2576586-1	70287801
	70287802
	70287803
	70287804
	70287805
2576590-1	70332701
	70332702
2576592-1	70283101
	70283104
2576592-1	70306801
	70306802
	70306803
	70306804
	70306805

Part Number	Serial Number(s)
2576630-1	70286105
	70286301
	70286302
	70286303
	70286304
	70286305
	70286306
	70286307
	70286308
	70286309
	70286310
	70286401
	70286402
	70286403
	70286404
	70286405
	70286406
	70286407
	70286408
	70286409
	70286410
	70286501
	70286502
	70286503
	70286504
	70286505
	70286506
	70286507
	70286508
	70286509
	70286510
	70287401
	70287402
	70287403
	70287404
	70287405
70287406	
70287407	
70287408	

Part Number	Serial Number(s)
2576630-1 (Continued)	70287409
	70287410
	70287701
	70287702
	70287703
	70287704
	70287705
	70287706
	70287707
	70287708
	70287709
	70287710
	70313501
	70313502
	70313503
	70313504
	70313505
	70313506
	70313507
	70313508
	70313509
	70313510
	70313601
	70313602
	70313603
	70313604
	70313605
	70313606
	70313607
	70313608
	70313609
	70313610
	70313701
	70313702
	70313703
	70313704
70313705	
70313706	

Part Number	Serial Number(s)
2576630-1 (Continued)	70313707
	70313708
	70313709
	70313710
	70331101
	70331102
	70331103
	70331104
	70331105

### SECTION III – ACCOMPLISHMENT INSTRUCTIONS:

- A) If the aircraft has had a replacement servo (or replacement engine) installed between January 30, 2003 and the date of this publication, identify the serial number and determine if the unit is affected by this bulletin. If so, remove the servo from the aircraft and call Precision Airmotive Corporation's product support department to arrange repair of the affected servo. The servo will be repaired and returned to the operator. It should then be reinstalled in accordance with applicable engine and airframe maintenance manuals.

### SECTION IV – WARRANTY INFORMATION:

- A) Remove and replace labor will be reimbursed in accordance with the published Lycoming or TCM labor allowance at the maintenance facility's posted shop rate.

Contact Information: Precision Airmotive Corporation  
Product Support Department  
(360)651-8282