

## **SERVICE INFORMATION NO. SI 40-082/1**

### **SUPERSEDES SERVICE INFORMATION No. SI 40-082**

**NOTE:** SI's are used only:

1) To distribute information from DAI to our customers.

2) To distribute applicable information/documents from our suppliers to our customers with additional information.

Typically there is no revision service for SI's. Each new information or change of that will be sent along with a new SI.

## **I. TECHNICAL DETAILS**

### **1.1 Airplanes affected:**

All DA 40 airplanes and  
all DA 40 F airplanes  
equipped with Honeywell KAP 140 A/P System

### **1.2 Subject:**

Honeywell Service Bulletin KC 140-22-102  
ATA-Code: 22-10

### **1.3 Reason:**

Honeywell has issued a Service Bulletin which addresses possible intermittent operation of the KAP 140 flight control system caused by a bad top cover of the KC 140.

### **1.4 Information:**

For detailed information please contact your Honeywell Service Center.

## **II. OTHERS**

In case of doubt contact Honeywell International Inc.