

## TEMPORARY REVISION

### TR-MÄM 40-378

### Preflight Check Tank Vents

This Temporary Revision TR-MÄM 40-378 is approved in conjunction with the Mandatory Design Change Advisory MÄM 40-378 and is valid in conjunction with the latest revision of the DA 40, DA 40 F and DA 40 D Airplane Flight Manual until this Temporary Revision has been incorporated into the Airplane Flight Manual.

The limitations and information contained herein either supplement or, in the case of conflict, override those in the Airplane Flight Manual.

The technical information contained in this document has been approved under the authority of DOA No. EASA.21J.052.

Doc. No.	Chapter	Affected Pages
6.01.01-E	4A	4A-6b, 4A-8b
6.01.02-E	4A	4A-7a, 4A-9a
6.01.05-E	4A	4A-5a, 4A-7a

#### Instruction

- Print this document on yellow paper (single-sided).
- Insert this cover page as the first page of the AFM.
- Insert the other pages of this Temporary Revision in front of the corresponding AFM pages.

Doc. No. 6.01.01-E Doc. No. 6.01.02-E Doc. No. 6.01.05-E	TR-MÄM 40-378	24-Mar-2009	COVER PAGE
----------------------------------------------------------------	------------------	-------------	---------------

DA 40 AFM  
DA 40 F AFM  
DA 40 D AFM



Temporary Revision  
Preflight Check Tank Vents

**4A. . PRE-FLIGHT INSPECTION**

*The following Item is added:*

2. Left Wing:

- h) Tank air outlet in lower surface . . . . . visual inspection

Doc. No. 6.01.01-E	TR-MÄM 40-378	24-Mar-2009	Page 4A-6b
Doc. No. 6.01.02-E			Page 4A-7a
Doc. No. 6.01.05-E			Page 4A-5a

DA 40 AFM  
DA 40 F AFM  
DA 40 D AFM



Temporary Revision  
Preflight Check Tank Vents

*The following Item is added:*

6. Right Wing:

- k) Tank air outlet in lower surface . . . . . visual inspection

Doc. No. 6.01.01-E	TR-MÄM 40-378	24-Mar-2009	Page 4A-8b
Doc. No. 6.01.02-E			Page 4A-9a
Doc. No. 6.01.05-E			Page 4A-7a