

# LIST OF APPLICABLE PUBLICATIONS

## MODEL DA 40 F

### Revision 25 Updates

| Doc. No. | Description   | Rev | Status |
|----------|---|-----|--------|
| -        | Removed the temporary revisions previously incorporated in the current Airplane Flight Manual (AFM) | -   | -      |

### Full Listing

| Doc. No.          | Description  | Rev | Status     |
|-------------------|--|-----|------------|
| 6.05.01 Chapter 3 | List of Applicable Publications (LOAP) - This document | 25  | 2025-02-27 |

### Aircraft Manuals

| Doc. No.         | Description  | Rev | Status     |
|------------------|--|-----|------------|
| <b>6.01.02-E</b> | <b>Airplane Flight Manual (AFM)</b>                  | 3   | 2013-08-26 |
| Supplement A2    | Intercom System PM 1000 II, PS Engineering Inc.      | 2   | 2005-03-15 |
| Supplement A11   | Compass System KCS 55A Bendix/King                   | 4   | 2005-03-15 |
| Supplement A12   | Transponder KT 76C Bendix/King                       | 2   | 2005-03-15 |
| Supplement A13   | Autopilot System KAP140 Bendix/King                  | 2   | 2005-03-15 |
| Supplement A14   | GPS KLN 94 Bendix(King, IFR Operation                | 3   | 2005-03-15 |
| Supplement A15   | GPS Annunciation Control Unit MD 41 MID-Continent    | 2   | 2005-03-15 |
| Supplement A17   | COM/NAV/GPS, GNS 430                                 | 3   | 2005-06-22 |
| Supplement A18   | Audio Panel, GMA 340                                 | 2   | 2005-06-22 |
| Supplement A19   | Transponder GTX 327 Garmin                           | 1   | 2005-03-15 |
| Supplement A20   | Course Deviation Indicator GI 106A Garmin            | 1   | 2005-03-15 |
| Supplement A25   | Audio Panel GMA 340 Garmin, VFR Operation            | 2   | 2005-03-15 |
| Supplement A26   | COM/NAV/GPS GNS 430 Garmin, VFR Operation            | 1   | 2005-03-15 |
| Supplement E2    | Attitude Indicator AIM 1100-28L(0F) BF Goodrich      | 2   | 2005-03-15 |
| Supplement E3    | Attitude Indicator AIM 1100-28LK(0F) DIA BF Goodrich | 2   | 2005-03-15 |
| Supplement E4    | Digital Chronometer Model 803 Davtron                | 1   | 2005-03-15 |
| Supplement N02   | Operation in Brazil                                  | -   | 2008-10-10 |
| Supplement O1    | Operation with Winter Kit                            | -   | 2006-01-26 |
| Supplement O2    | Intentional Spin                                     | -   | 2007-02-26 |
| Supplement S1    | Emergency Locator Transmitter Model E-01 Ack         | 2   | 2005-03-15 |
| Supplement S4    | MHz ELT Artex ME 406 and ME 406 'ACE'                | 1   | 2007-04-10 |

### 6.05.01 Chapter 3 R25

**LIST OF APPLICABLE PUBLICATIONS****MODEL DA 40 F**

| <b>Full Listing</b>      |   |            |                  |
|--------------------------|---|------------|------------------|
| <b>Doc. No.</b>          | <b>Description</b>  | <b>Rev</b> | <b>Status</b>    |
| Supplement S5            | Canopy Jettison System  | -          | 2007-01-24       |
| TR-MÄM 40-1020           | Removal of Pilot Gust Lock Mount  | -          | 2018-09-13       |
| TR-MÄM 40-1087           | Use of Alt. Static Source   | -          | 2020-12-21       |
| TR-MÄM DAIC-0042         | Amerex 337TS Fire Extinguisher  | -          | 2023-04-01       |
| TR-OÄM 40-401            | Emergency Egress Hammer   | -          | 2017-03-13       |
| TR-17-02                 | Change in Type Design Responsibility                                      | -          | 2017-11-15       |
| TR-MÄM-40-1203           | Door Latching and Locking   | -          | 2024-12-16       |
| <b>6.02.01</b>           | <b>Airplane Maintenance Manual</b>  | 10         | 2023-03-28       |
| AMM-TR-MÄM-40-1203       | Visual Indicator for the Position of the Passenger Door Handle            | -          | 2025-01-02       |
| <b>6.03.02</b>           | <b>Illustrated Parts Catalogue (IPC)</b>                                  | (N/A)      | Available Online |
| <b>Service Bulletins</b> |   |            |                  |
| OSB 40-037               | Installation of maintenance access holes in front seats                   | -          | 2005-05-23       |
| OSB 40-042               | Mechanical installation of a GARMIN GDL69/A XM Data Link system           | 1          | 2005-11-21       |
| OSB 40-043               | Mechanical installation of a Becker ADF3500 and or Honeywell KN63 DME     | 1          | 2005-11-21       |
| MSB 40-046               | Inspection of the nose landing gear leg                                   | 3          | 2008-11-17       |
| OSB F4-001               | Long range fuel tank  | 1          | 2009-12-21       |
| OSB F4-002               | Landing gear, Speed kit   | -          | 2006-06-16       |
| OSB F4-003               | CG adjustment   | 1          | 2012-10-09       |
| OSB F4-005               | Installation of baggage extension and baggage tray                        | -          | 2006-06-16       |
| OSB F4-006               | Installation of Winter Baffle in Wing Fresh Air Inlet                     | -          | 2006-06-16       |
| OSB F4-007               | Installation of a sheep skin cover on the front seat                      | -          | 2006-06-16       |
| RSB F4-008               | Replacement of the Right Hand Aileron                                     | 3          | 2014-11-04       |
| SB F4-009                | not issued yet  |            |                  |
| OSB F4-010               | Installation of a Canopy Jettison System                                  | -          | 2007-04-23       |
| OSB F4-011               | Installation of the MT Propeller  | -          | 2007-05-29       |
| OSB F4-012               | Adjustment of Elevator Travel Stops and Approval for Intentional Spinning | -          | 2007-06-15       |

**6.05.01 Chapter 3 R25**

# LIST OF APPLICABLE PUBLICATIONS

## MODEL DA 40 F

| <b>Full Listing</b>                |  |            |               |
|------------------------------------|--|------------|---------------|
| <b>Doc. No.</b>                    | <b>Description</b>   | <b>Rev</b> | <b>Status</b> |
| MSB F4-013                         | Reinforcement of the Pitot, static and stall warning line installation                             | -          | 2008-08-27    |
| MSB F4-014                         | Installation of the inline 100 ohm resistor, on the AUX line of the alternator, on a circuit board | -          | 2008-02-14    |
| MSB F4-016                         | Wing Skin to Spar Bond   | 1          | 2009-12-21    |
| OSB F4-017                         | Maintenance Access Holes in the Elevator   | 1          | 2016-02-03    |
| RSB F4-018                         | Seal between the firewall shield and the fuselage  | -          | 2010-02-25    |
| MSB F4-021                         | Check of emergency exit lever  | -          | 2010-07-14    |
| OSB F4-023                         | Installation of a coated safety walk   | -          | 2010-07-20    |
| MSB F4-024                         | Replacement of Passenger Door Retaining Bracket incl. WI Rev. 1                                    | 1          | 2011-01-17    |
| OSB F4-026                         | Installation of a reinforced nose wheel fork   | -          | 2011-11-14    |
| OSB F4-027                         | Installation of a tall canopy bubble to the existing canopy frame                                  | -          | 2013-01-08    |
| MSB F4-028                         | Reinforcement of aft main spar   | -          | 2013-05-10    |
| OSB F4-029                         | Use of Avgas 100   | 1          | 2013-09-26    |
| OSB F4-030                         | Installation of CO Detector P/N 452-201-010 as a replacement for P/N 452-201-004                   | -          | 2013-10-31    |
| RSB F4-031                         | Installation of permanent maintenance access holes in wings  | -          | 2014-10-09    |
| OSB F4-032                         | Installation provisions for a safety mesh to protect the fuel vent covers into the wings           | 2          | 2019-03-26    |
| RSB F4-035                         | Inspection of NLG elastomer pack center tube   | 1          | 2015-12-16    |
| MSB F4-036                         | Removal of Pilot Gust Lock Mount   | 1          | 2018-11-20    |
| MSB F4-037                         | Fuel Tank Interconnect Hose (Flexible Coupling) Replacement  | 3          | 2019-11-05    |
| MSB F4-038                         | Dye penetrant inspection of D41-3223-10-00 and D41-3223-10-00_1 nose landing gear legs             | -          | 2021-01-18    |
| MSB F4-039                         | Baggage net latches  | -          | 2021-07-06    |
| OSB F4-040                         | Installation of Amerex 337TS fire extinguisher   | -          | 2023-08-23    |
| <b>Service Information Letters</b> |  |            |               |
| SI40-001                           | Descriptions of DAI technical publication systems and handling of documents                        | 3          | 2017-08-28    |
| SI40-033                           | Garmin GNS 430/430A use of additional TERRAIN functionality  | -          | 2006-04-25    |
| SI40-034                           | Garmin GNS 530/530A use of additional TERRAIN functionality  | -          | 2006-04-25    |
| SI40-036                           | Garmin GNS 430/430A and GNS 530/530A use of additional TERRAIN functionality                       | -          | 2006-05-23    |
| SI40-037                           | FAA AD 2006-12-07 and ECi SB for Replacement of classic cast cylinders                             | -          | 2006-06-20    |

# LIST OF APPLICABLE PUBLICATIONS

## MODEL DA 40 F

| Full Listing |  |     |            |
|--------------|--|-----|------------|
| Doc. No.     | Description  | Rev | Status     |
| SI40-038     | Garmin GDL 69/69A XM Satellite Datalink Storm Cell Tracking Limitation                             | -   | 2006-06-27 |
| SI40-039     | Garmin 500 Series TAWS Inhibit Mode Functionality  | -   | 2006-08-22 |
| SI40-040     | Garmin G1000 System Software Version Update  | -   | 2006-09-12 |
| SI40-042     | Garmin G1000 System Software Version Update  | -   | 2006-10-11 |
| SI40-043     | Garmin G1000 System Software Version Update  | -   | 2006-11-23 |
| SI40-044     | Garmin G1000 SB New Magnetic Field Model   | -   | 2007-01-11 |
| SI40-045     | Garmin SA, Multiple Initial Approach Fixes in the Transition List                                  | -   | 2007-01-22 |
| SI40-046     | ACK Service Bulletin SB E-01.9   | -   | 2007-01-22 |
| SI40-047     | Garmin SB, SW Version 5.02 for GNS 430/530 Series Units  | -   | 2007-01-22 |
| SI40-048a    | Garmin SB, SW Upgrade to Version 4.06 for GTX 330/330D and GTX 33/33D, non-G1000 applications only | -   | 2007-02-07 |
| SI40-049     | Electronic Checklist   | -   | 2007-01-31 |
| SI40-050     | Garmin Service Alert 070227-00   | -   | 2007-03-02 |
| SI40-052     | Garmin SB No. 0713 Rev. D, inspection of GSM 85 servo gearbox                                      | 1   | 2008-05-06 |
| SI40-053     | Garmin SB No. 0710 Rev. A, Hardware Changes to GTX 33/33D units                                    | -   | 2007-05-29 |
| SI40-054     | Garmin SB No. 0714 Rev. A, Hardware Changes to GTX 330/330D units                                  | -   | 2007-05-29 |
| SI40-055     | Garmin SB No. 0702 Rev. A, GLD 69/69A Software Upgrade to Version 3.10                             | -   | 2007-06-11 |
| SI40-056     | Garmin SB No. 0713 Rev. D, inspection of GSM 85 servo gearbox                                      | -   | 2007-06-20 |
| SI40-057     | Garmin Service Alert 070801-00   | 1   | 2007-08-23 |
| SI40-058     | Garmin Service Advisory 070816-00, GRS 77  | -   | 2007-08-17 |
| SI40-060     | Garmin Service Bulletin No. 0705, Main Software Version 6.03 for 500 Series Units                  | -   | 2007-09-07 |
| SI40-061     | Garmin Service Bulletin No. 0735, GRS 77   | -   | 2007-09-10 |
| SI40-062     | Garmin Service Bulletin No. 0736B, G1000 System ID Tool  | 1   | 2007-12-21 |
| SI40-063     | Garmin Software Service Bulletin No. 0730 Rev. A   | -   | 2007-09-25 |
| SI40-064     | Garmin Software Service Bulletin No. 0739  | -   | 2007-10-22 |
| SI40-066     | Garmin Service Bulletin No. 0738 Rev. B, Replacement of Failed Transient Voltage Suppressors       | -   | 2007-10-23 |
| SI40-067     | Garmin Software Service Bulletin No. 0739B   | -   | 2007-12-21 |
| SI40-068     | Garmin Software Service Bulletin No. 0706  | -   | 2007-12-21 |
| SI40-069     | Garmin Software Service Bulletin No. 0739 Rev. C   | -   | 2007-11-28 |
| SI40-071     | Garmin Service Alert No. 0801, Supplemental Data Cards   | -   | 2008-02-11 |

# LIST OF APPLICABLE PUBLICATIONS

## MODEL DA 40 F

| Full Listing |  |     |            |
|--------------|--|-----|------------|
| Doc. No.     | Description  | Rev | Status     |
| SI40-076     | Garmin Service Alert No. 0811, Flight Plan Sequencing Issue  | -   | 2008-04-21 |
| SI40-079     | Garmin Service Alert No. 0816, Forward Looking Terrain Avoidance (FLTA)  | -   | 2008-05-09 |
| SI40-080     | Garmin Service Alert No. 0817, Forward Looking Terrain Avoidance (FLTA)  | -   | 2008-05-13 |
| SI40-081     | Honeywell Service Bulletin KAP 140-22-102, Reduce the possibility of intermittent failures because of top cover on KC 140                  | 1   | 2008-10-27 |
| SI40-082     | Honeywell Service Bulletin KC 140-22-102, Replace top cover to make sure connector pins engage correctly                                   | 1   | 2008-10-27 |
| SI40-083     | Garmin Service Bulletin No. 0823, GDU 104X CRS/BARO Knob Interference  | -   | 2008-07-11 |
| SI40-084     | Garmin Service Alert No. 0824, GDU 104X CRS/BARO Knob Interference   | -   | 2008-07-11 |
| SI40-085     | Garmin Service Advisory No. 0825, LPV and LNAV/VNAV approaches with three-character airport identifiers                                    | -   | 2008-07-25 |
| SI40-086     | Garmin Service Bulletin No. 0823 Rev. B, GDU 104X CRS/BARO Knob Interference   | -   | 2008-08-05 |
| SI40-087     | Garmin Service Alert No. 0824 Rev. B, GDU 104X CRS/BARO Knob Interference  | -   | 2008-08-05 |
| SI40-089     | Garmin Service Advisory No. 0826 Rev. A, Traffic symbols on GDU displays with SVT (Synthetic Vision Technology)                            | -   | 2008-08-11 |
| SI40-090     | Garmin Service Advisory No. 0831 Rev. A, Automatic approach course selection   | -   | 2008-08-21 |
| SI40-091     | Garmin Service Advisory No. 0829 Rev. A, SVT runway will appear higher or lower than the actual runway                                     | -   | 2008-11-17 |
| SI40-092     | Garmin Service Advisory No. 0826 Rev. B, , Traffic symbols on GDU displays with SVT (Synthetic Vision Technology) may appear to be cropped | -   | 2008-11-17 |
| SI40-093     | Garmin Service Advisory No. 0838 Rev. A, GPS/WAAS Loss of Reception  | -   | 2008-11-17 |
| SI40-094     | Honeywell-SB KS 270C-22-09, Exchange of the tach generator   | -   | 2008-10-27 |
| SI40-095     | Honeywell-SB KS 271C-22-10, Exchange of the tach generator   | -   | 2008-10-27 |
| SI40-097     | Garmin Software Service Bulletin No. 0845, New Software for (non-WAAS) 500 Series Units  | -   | 2008-12-18 |
| SI40-098     | Garmin Software Service Bulletin No. 0846 Rev. A, GTX 330/330D and GTX 33/33D Software Version 6.00 Non-G1000/G900X Applications Only      | -   | 2008-12-09 |
| SI40-099     | EASA-AD: Wings - Upper Wing Skin-to-Main Spar Adhesive Joint - Inspection/Repair   | -   | 2008-12-18 |
| SI40-100     | EASA-AD: Nose Landing Gear Leg - Inspection / Replacement  | -   | 2009-02-03 |
| SI40-102     | Garmin Service Advisory No. 0904 Rev. A, Synthetic Vision Technology (SVT)   | -   | 2009-02-06 |
| SI40-104     | Garmin Service Advisory No. 0908 Rev. A, Garmin Integrated Flight Deck Systems Equipped with the Honeywell Model KN63 DME                  | -   | 2009-03-16 |

# LIST OF APPLICABLE PUBLICATIONS

## MODEL DA 40 F

| Full Listing |   |     |            |
|--------------|---|-----|------------|
| Doc. No.     | Description   | Rev | Status     |
| SI40-105     | Garmin Software Service Bulletin No. 0846 Rev. B, GTX 330/330D and GTX 33/33D Software Version 6.00 Non-G1000/G900X/GNS480 Applications Only                    | -   | 2009-03-12 |
| SI40-106     | Garmin Service Advisory No. 0914 Rev. A, Possible temporary loss of heading/attitude information  | -   | 2009-05-08 |
| SI40-107     | Garmin Service Advisory No. 0915 Rev. A, Navigation suspending during non-precision approaches  | -   | 2009-05-11 |
| SI40-108     | FAA-AD: Nose Landing Gear Leg - Inspection / Replacement  | -   | 2009-05-19 |
| SI40-109     | Garmin Service Advisory No. 0912 Rev. A, SBAS Operations in Australia, New Zealand and South Pacific Regions  | -   | 2009-06-04 |
| SI40-110     | Garmin Service Advisory No. 0922 Rev. A, VOR or LOC/ILS Approaches  | -   | 2009-07-08 |
| SI40-111     | Garmin Service Advisory No. 0929 Rev. A, Momentary failure indications (Red-X) can occur when deleting stored data  | -   | 2009-07-13 |
| SI40-112     | Illustrated Parts Catalogue (IPC) - Change of the available media   | -   | 2009-10-05 |
| SI40-113     | Garmin Service Bulletin No. 0919 Rev. A, G1000 System Software Update   | -   | 2009-10-05 |
| SI40-114     | Garmin Service Advisory No. 0944 Rev. A, SVT Pathways may be displayed at a higher altitude than expected   | -   | 2009-10-05 |
| SI40-115     | Garmin Mandatory Service Bulletin No. 0823 Rev. C, GDU 104X CRS/BARO Knob Interference  | -   | 2009-12-09 |
| SI40-116     | Garmin Service Alert No. 0824 Rev. C, GDU 104X CRS/BARO Knob Interference   | -   | 2009-12-09 |
| SI40-118     | FAA-AD: To prevent loss of engine power due to cracks at the head-to-barrel interface and possible engine failure caused by separation of a cylinder head       | -   | 2010-02-22 |
| SI40-118     | FAA-AD: To prevent loss of engine power due to cracks at the head-to-barrel interface and possible engine failure caused by separation of a cylinder head       | 1   | 2010-03-01 |
| SI40-121     | EASA-AD: Rear passenger door retaining bracket - Replacement  | 1   | 2014-03-04 |
| SI40-122     | FAA-AD: Passenger door retaining bracket - Replacement  | -   | 2010-12-17 |
| SI40-123     | Garmin Service Advisory No. 1051 Rev. A & Software Service Bulletin No. 0533 Rev. B, 2010 IGRF (International Geomagnetic Reference Field) Magnetic Field Model | -   | 2011-02-16 |
| SI40-124     | Garmin Service Advisory No. 1118 Rev. A, Momentary failure indications (Red-X) can occur when sorting stored flight plans                                       | -   | 2011-05-17 |
| SI40-125     | Garmin Service Advisory No. 1129 Rev. A, Momentary loss of GRS 77/77H and GDC 74A/74B/74H functions   | -   | 2011-05-31 |
| SI40-130     | Garmin Service Alert No. 1228, SIDs and STARs non-JETs Limitation   | -   | 2012-11-06 |
| SI40-131     | EASA-AD: Inspection of the markings of the safety belts   | 1   | 2014-04-08 |
| SI40-133     | Garmin Service Advisory No. 1309, Verification of displayed heading is not noticeable drifting prior Take-Off   | -   | 2013-03-04 |

# LIST OF APPLICABLE PUBLICATIONS

## MODEL DA 40 F

| Full Listing |   |     |            |
|--------------|---|-----|------------|
| Doc. No.     | Description   | Rev | Status     |
| SI40-134     | Garmin Service Advisory No. 1309 Rev. B, Verification of displayed heading is not noticeable drifting prior Take-Off  | -   | 2013-04-12 |
| SI40-135     | Identification of stainless steel control cables  | -   | 2013-06-17 |
| SI40-136     | EASA-AD: Modification of the aft main spar in the cabin area  | -   | 2013-07-18 |
| SI40-137     | Garmin Terrain Data Alert No. 1351 Rev. B, Anomalies when using Synthetic Vision Technology in Northwest Greenland  | 1   | 2015-03-03 |
| SI40-138     | Garmin Service Advisory No. 1352 Rev. A, Course deviation indicator (CDI) may deflect in the wrong direction in certain situations  | -   | 2013-09-26 |
| SI40-139     | Garmin STC Service Bulletin No. 1334 Rev. A, update of G1000 equipped aircraft to G1000 System Software Version 0321.23   | -   | 2013-10-24 |
| SI40-140     | United Instruments Inc. Service Bulletin No. 12, Paint on dial may crack and separate from the surface  | -   | 2013-10-31 |
| SI40-141     | Garmin Service Advisory No. 1363 Rev. A, User-modified terminal procedure stored in a Flight Plan may cause error condition   | -   | 2013-11-21 |
| SI40-142     | FAA-AD: Modification of the aft main spar in the cabin area   | -   | 2013-12-05 |
| SI40-143     | Garmin Service Advisory No. 1344 Rev. B, LPV and LNAV/VNAV Approach Full Scale Deflection   | -   | 2013-12-18 |
| SI40-144     | Garmin Service Advisory No. 1372 Rev. A, Unavailable RNAV (GPS) approaches due to lack of VDA   | -   | 2013-12-18 |
| SI40-145     | Andair GAS375 Gascolator Filters  | 1   | 2014-06-25 |
| SI40-146     | FAA-AD: Modification of the aft main spar in the cabin area   | -   | 2014-08-27 |
| SI40-150     | Garmin Service Alert No. 1538 Rev. A, Operations with Altimeter Set to QFE (height above field elevation)   | -   | 2015-08-12 |
| SI40-151     | Andair Service Alert: Certain fuel valve systems with extension may have a possible lack of engagement between the universal joint assembly and the top of the valve assembly   | -   | 2015-09-17 |
| SI40-153     | Garmin STC Service Bulletin No. 1534 Rev. A, Installation instructions for a G1000 configuration update that prevents the loss of Engine Indication System  | -   | 2016-03-01 |
| SI40-154     | United Instruments Inc. SB No. 13, Specific 5934 Series Altimeters manufactured between January 2015 and February 2016 are susceptible to develop a slow diaphragm leak which would affect the accuracy of the altimeters | -   | 2016-04-29 |
| SI40-155     | Garmin Service Advisory No. 1372 Rev. B, unavailable RNAV (GPS) approaches  | -   | 2016-06-24 |
| SI40-156     | Garmin Service Advisory No. 1612 Rev. A, Update of the IGRF (International Geomagnetic Reference Field) Magnetic Field Model from base year 2010 to 2015  | -   | 2016-09-19 |

**LIST OF APPLICABLE PUBLICATIONS****MODEL DA 40 F**

| <b>Full Listing</b> |  |            |               |
|---------------------|--|------------|---------------|
| <b>Doc. No.</b>     | <b>Description</b>   | <b>Rev</b> | <b>Status</b> |
| SI40-158            | FAA-AD: Certain altimeters displaying higher than actual altitude due to a slow diaphragm leak which were examined in United Instruments SB No. 13 | -          | 2017-03-24    |
| SI40-159            | Lycoming Service Bulletin No. 632, Identification of Connecting Rod assemblies or Connecting Rod Bushings on certain engine serial numbers         | -          | 2017-07-21    |
| SI40-160            | FAA-AD: Inspection of connecting rods and replacement of affected connecting rod small end bushings  | -          | 2017-08-29    |
| SIF4-002            | EASA-SID: Volare Carburetors LLC Carburetor Float Failures   | -          | 2009-04-16    |
| SIF4-003            | Garmin Service Advisory No. 0916 Rev. A, Left Fuel Low alert does not display when low fuel condition exists                                       | -          | 2009-05-11    |
| SIF4-004            | TCCA AD No. CF-2019-39: Fuel tank interconnect hose replacement.   | -          | 2020-02-20    |
| SIF4-005            | Aircraft cleaning and disinfection recommendations   | -          | 2020-05-21    |
| SIF4-006            | Nose landing gear maintenance and inspections.   | -          | 2023-01-12    |
| SIF4-007            | United Instruments Service Note No. 14   | -          | 2023-04-13    |
| SIDA40-002          | Change in Type Design Responsibility   | -          | 2017-11-15    |
| SIF4-008            | Closing and latching the passenger door.   | -          | 2024-08-30    |