

OPTIONAL SERVICE BULLETIN

NO. OSB-40-042/1

SUPERSEDES OSB-40-042

I TECHNICAL DETAILS

I.1 Category

Optional.

I.2 Airplanes affected

DA40 and DA40F with Garmin G1000 equipment installed (Garmin STC # SA01254WI).

I.3 Time of Compliance

At owner's discretion.

I.4 Subject

Mechanical installation of a GARMIN GDL69/A XM Data Link system.

NOTE: This SB does not allow configuration and activation of the GDL69/A. This has to be done in accordance with appropriate approved documents of the appliance manufacturer.

I.5 Reason

The optional mechanical installation of a GARMIN GDL69/A.

I.6 Concurrent Documents

None

I.7 Approval

The technical information or instructions contained in this document relate to the Design Change Advisory No. OÄM 40-213/a, which has been approved under the authority of EASA Design Organization Approval No. EASA.21J.052.

I.8 Accomplishment/Instructions

Comply with WI-OSB-40-052.

I.9 Mass (Weight) and CG

Update the Mass and Balance Report in the AFM Chapter 6.

II PLANNING INFORMATION

II.1 Material & Availability

For necessary material refer to WI-OSB-40-042 "Installation of GDL69/A". Materials are available from Diamond Aircraft Industries.

II.2 Special Tools

Refer to WI-OSB-40-042 "Installation of GDL69/A".

II.3 Labor effort

Approx. 28 hours.

II.4 Credit

None.

II.5 Reference Documents

WI-OSB-40-042 "Installation of GDL69/A".

III REMARKS

1. All measures must be carried out by the manufacturer or a certified aircraft station.
2. Accomplishment of the measures must be confirmed in the log book
3. In case of doubt, contact Diamond Aircraft.
4. This SB does not allow configuration and activation of the GDL69/A. This has to be done in accordance with appropriate approved documents of the appliance manufacturer.