

OPTIONAL SERVICE BULLETIN

NO. OSB-F4-011

I TECHNICAL DETAILS

I.1 Category

Optional

I.2 Airplanes affected

Type: DA 40 F

Serial Numbers: all

I.3 Time of Compliance

At owners discretion

I.4 Subject

Installation of the MT-Propeller

ATA-Code: 61

I.5 Reason

Optional installation of the MT-Propeller MT188R135-4G.

At the time being this Optional Service Bulletin may solely be carried out by Diamond Aircraft Industries.

I.6 Concurrent Documents

None

I.7 Approval

The technical information or instructions contained in this document relate to the Design Change Advisory No. OÄM 40-203, which has been approved by EASA.

The technical content of this document has been approved under the authority of DOA No. EASA.21J.052.

I.8 Accomplishment / Instructions

WI-OSB-F4-011, latest effective issue must be complied with.
Contact your responsible authority for further necessary noise certificates.

I.9 Mass (Weight) and CG

Update of Mass and Balance by weighing.

II PLANNING INFORMATION

II.1 Material & Availability

The Work Instruction WI-OSB-F4-011 and appropriate necessary materials are available through DAI.

II.2 Special Tools

None

II.3 Credit

None

II.4 Labor effort:

Approximately 3 hours

II.5 Reference Documents

DA 40 Series Airplane Maintenance Manual Doc. No. 6.02.01, latest effective issue and Temporary Revision AMM-TR-VÄM-40-002/a and WI-OSB-F4-011, latest effective issue.

III REMARKS

1. This Service Bulletin may ONLY be carried out by Diamond Aircraft Industries.
2. Accomplishment of the measures must be confirmed in the log book.
3. In case of any doubt, contact Diamond Aircraft Industries.