Diamond Aircraft Industries





Model DA 40 F

OPTIONAL SERVICE BULLETIN NO. OSB F4-040 REV. 0

l **TECHNICAL DETAILS**

I.1 Category

Optional.

<u>I.2</u> **Airplanes Affected**

DA 40 F Type:

S/N: 40.F001 and subsequent.

1.3 **Date of Effectivity**

03 August 2023.

1.4 **Time of Compliance**

At owner's discretion.

<u>1.5</u> **Subject**

Installation of Amerex 337TS fire extinguisher.

ATA code: 26-00

1.6 Reason

Due to the elimination of the substance Halon 1211 by the Canadian environmental legislation and discontinuation of the A620T fire extinguisher, Diamond Aircraft has approved the Amerex 337TS fire extinguisher as an alternate to the existing extinguisher. This Service Bulletin describes the installation of the Amerex 337TS fire extinguisher.

1.7 **Concurrent Documents**

None.

<u>1.8</u> **Approval**

The technical information and instructions contained in this document relate to Design Change Advisories MÄM 40-1162 and MÄM DAIC-0042, which have been approved as part of the type design.

<u>I.9</u> **Accomplishment/Instructions**

See WI-OSB F4-040, latest effective issue.

I.10 Mass (Weight) and CG

The change in mass and CG is negligible.

Page 1 of 3 03 August 2023

Diamond Aircraft Industries

OPTIONAL SERVICE BULLETIN



Model DA 40 F

II PLANNING INFORMATION

II.1 Material and Availability

See WI-OSB F4-040, latest effective issue.

II.2 Special Tools

None.

II.3 Labour Effort

Approximately 1.5 hours will be required to accomplish this service bulletin.

This estimate is for direct labour performed by a technician, and it does not include setup, planning, familiarization, cure time, part fabrication, or tool acquisition.

II.4 Credit

None.

II.5 Reference Documents

DA 40 Series Airplane Maintenance Manual, Doc. No. 6.02.01, latest effective issue.

III REMARKS

- 1. All work must be done by the appropriate authorized personnel.
- 2. All work, in particular which is not especially described in this service bulletin, must be done in accordance with the referenced maintenance manual.
- 3. Completion of all work must be recorded in the logbook.
- 4. In case of doubt, contact Diamond Aircraft Industries Inc.

Page 2 of 3 03 August 2023

Diamond Aircraft Industries

OPTIONAL SERVICE BULLETIN





SERVICE BULLETIN OSB F4-040 REV. 0

AIRPLANE DATA Airplane serial number Airplane registration Airplane operator Hours of operation of airplane (TSN) Typical operation of airplane private, club, training, other: **MAINTENANCE DATA** Date of maintenance Maintenance carried out by During scheduled inspection? No Yes Name Signature Date

Please e-mail the completed form to Techpubs@diamondaircraft.com.