

## SERVICE INFORMATION No. SI 40-095

**NOTE:** SI's are used only:  
1) To distribute information from DAI to our customers.  
2) To distribute applicable information/documents from our suppliers to our customers with additional information.  
Typically there is no revision service for SI's. Each new information or change of that will be sent along with a new SI.

### I. TECHNICAL DETAILS

#### 1.1 Airplanes affected:

All DA 40 airplanes and  
all DA 40 F airplanes  
equipped with Honeywell KAP 140 A/P System

#### 1.2 Subject:

Honeywell Service Bulletin KS 271C-22-10  
ATA-Code: 22-10

#### 1.3 Reason:

Honeywell has issued a Service Bulletin which addresses the exchange of the tach generator which is installed in the KS 271C units. The new tach generator solves the intermittent problems (A/C and A/P oscillations) observed on the KAP 140 A/P system.

#### 1.4 Information:

For detailed information please contact your Honeywell Service Center.

### II. OTHERS

In case of doubt contact Honeywell International Inc.