

**COVER PAGE TO
TEMPORARY REVISION
TR-RÄM-40-056
Firmware m2.32 for 19:1 Engine**

This Temporary Revision TR-RÄM-40-056 is approved in conjunction with the Repair Design Change Advisory RÄM 40-056. For the operation of the TAE 125 engine (19:1 compression) with the new firmware this TR must be included in the AFM or that AFM revision must be used in which the TR is incorporated.

The limitations and information contained herein either supplement or, in the case of conflict, override those in the Airplane Flight Manual.

The technical information contained in this document has been approved under the authority of DOA no. EASA.21J.052

Affected Pages:

Doc. No.	Rev.	Page
6.01.05-E	3	0-1e, 1-2e, 6-15e

Instruction:

Insert pages of Temporary Revision in front of original manual page.

Insert this cover page as first page of the manual.

Doc. No. 6.01.05-E	TR-RÄM- 40-056	10-Jan-2006	Page 0 - 1e
--------------------	-------------------	-------------	-------------

1. GENERAL

1.1 INTRODUCTION

The following entry must be added to the Modification List:

Modification	Source	Installed	
Firmware m2.32 for 19:1 engine	RÄM 40-056	<input type="checkbox"/> yes	<input type="checkbox"/> no

6.5 EQUIPMENT LIST AND EQUIPMENT INVENTORY

The following items must be added to the Equipment List:

Airplane Serial No.:		Registration:		Date:	
Description	Type	Part No.:	Manufacturer	S/N	in- stalled
ENGINE CONTROL UNIT	ECU	02-7610-55001R(*)	Thielert		
	ECU Software TAE-125 m2.32	02-7610-55101R(*)	Thielert		
	ECU Mapping S14V230DIA	50-7610-55105R(*)	Thielert		

*Approved Software and Mapping see Service Information SI D4.018.