

OPTIONAL SERVICE BULLETIN NO. OSB-D4-051

I <u>TECHNICAL DETAILS</u>

I.1 Category

Optional.

I.2 Airplanes Affected

Type: DA 40 D

Serial Numbers: all DA 40 D aircraft with G1000 installed

I.3 Date of Effectivity

19-Sep-2006

I.4 <u>Time of Compliance</u>

At owner's discretion.

I.5 Subject

Installation of Artex C406-1 ELT ATA Code: 25

I.6 <u>Reason</u>

This OSB specifies the optional installation of the Artex C406-1 ELT.

I.7 Concurrent Documents

None.



I.8 Approval

The technical information or instructions contained in this document relate to the Design Change Advisory No. OÄM 40-240, which has been approved under the authority of EASA Design Organization Approval No. EASA.21J.052.

The technical content of this document has been approved under the authority of DOA No. EASA.21J.052.

I.9 Accomplishment/Instructions

Comply with WI-OSB-D4-051, latest effective issue.

I.10 Mass (Weight) and CG

Mass and CG are not affected.

II PLANNING INFORMATION

II.1 Material & Availability

See WI-OSB-D4-051, latest effective issue.

II.2 Special Tools

None.

II.3 Labor Effort

Approximately 7 man hours.

II.4 Credit

None.

II.5 <u>Reference Documents</u>

DA 40 Series Airplane Maintenance Manual, Doc. No. 6.02.01, latest effective issue. WI-OSB-D4-051, latest effective issue.



III <u>REMARKS</u>

- 1) All measures must be carried out by a certified aircraft service station or a certified aircraft maintenance mechanic.
- 2) All works, particular those that are not especially described in this service bulletin, must be carried out in accordance with the referenced maintenance manual.
- 3) Accomplishment of the measures must be confirmed in the log book.
- 4) In case of doubt, contact Diamond Aircraft.



APPLICATION TO OBTAIN THE WORK INSTUCTION for OSB D4-051

AIRPLANE DATA

Typical operation of airplane: private, club, training, other _____

Date, Name, Sign

Please fax the completed form to Fax No. **43-2622-26620 or e-mail to support@diamond-air.at