

Diamond Aircraft Industries G.m.b.H. N.A. Otto-Straße 5 A-2700 Wiener Neustadt

DAI SI 40-019 DAI SI D4-027 Page 1 of 1 11-Apr-2005

SERVICE INFORMATION NO. SI 40-019 SERVICE INFORMATION NO. SI D4-027

NOTE: SI's are used **only** as a cover sheet to distribute information / documents of other manufacturers to our customers with additional information when applied to the DAI product. Typically there is no revision service for Si's. Each new information or change of that will be send along with a new SI.

I. TECHNICAL DETAILS

1.1 Airplanes affected:

DA 40 airplanes equipped with Garmin GNS 430

s/n 97125747 through 97126193, 96303169, 97107697, 97123197 and 97123079

DA 40 D airplanes equipped with Garmin GNS 430

s/n 97125747 through 97126193, 96303169, 97107697, 97123197 and 97123079

1.2 Subject:

Service Alert No. 050321-01 issued by Garmin

ATA-Code: 23-34

1.3 Reason:

Garmin has discovered an issue which may result in the GNS 430 unit tripping the aircraft circuit breaker, rendering the unit inoperative.

1.4 Information:

For detailed information see attached Garmin Service Alert No. 050321-01. Please note the immediate action required.

This SA is applicable with no restrictions to all affected aircraft.

II. OTHERS



SERVICE ALERT

Service Alert: 050321-01

STATEMENT OF REVISION FOR -01:

This service alert has been revised to adjust the list of affected serial numbers.

Please refer to http://www.garmin.com/aviation/servicenotices.jsp for an updated list of units that remain affected. As serial numbers are corrected at the factory this web list will be updated until all affected units are compliant. The list on the web site will supercede the affected product serial number list shown below.

AFFECTED PRODUCT:

GNS 430 and GNS 430A units manufactured between Feb 23, 2005 and March 21, 2005.

Affected units serial numbers are as follows:

GNS430 s/n 97125747 through 97126193 s/n 96303169, 97107697, 97123197, 97123079

GNS430A s/n 46150016 through 46150024

IMMEDIATE ACTION REQUIRED:

- Pilots, Operators, and Avionics Installers, do NOT fly IFR operations using the affected product(s).
- Pilots, Operators, and Avionics Installers, notify all customers and pilots who may have an affected product(s).
- Avionics Installers, hold all affected inventory until corrective action is accomplished.
- Avionics Installers, do not approve installations with affected product(s) until corrective action is accomplished.

DESCRIPTION:

Garmin has discovered an issue with the above listed GNS 430 units. This issue may result in the GNS 430 unit tripping the aircraft circuit breaker, rendering the unit inoperative. All other Garmin products except for those specifically listed above are unaffected.

CORRECTIVE ACTION:

If you have an affected GNS 430 unit, please contact your local Garmin Authorized Service Center immediately to arrange for modification or exchange of the subject GNS 430 unit.

ADDITIONAL INFORMATION:

Please contact Garmin Product Support for additional assistance.



The following is a list of unit serial numbers that remain affected by Garmin Service Alert 050321-01. This list resides at http://www.garmin.com/aviation/servicenotices.jsp and will be updated until all affected units listed below are compliant.

| http://www.gammi.com/av | lation/servicehotices.jsp e |
|-------------------------|-----------------------------|
| 46150017 | 97125904 |
| 46150018 | 97125905 |
| 46150021 | 97125906 |
| 46150022 | 97125907 |
| 97125747 | 97125908 |
| 97125749 | 97125909 |
| 97125750 | 97125910 |
| 97125751 | 97125913 |
| 97125752 | 97125914 |
| 97125755 | 97125914 |
| 97125756 | 97125919 |
| 97125850 | 97125920 |
| 97125852 | 97125920 |
| 97125853 | 97125921 |
| | |
| 97125854 | 97125923 |
| 97125855 | 97125926 |
| 97125856 | 97125930 |
| 97125857 | 97125932 |
| 97125858 | 97125933 |
| 97125860 | 97125935 |
| 97125861 | 97125936 |
| 97125862 | 97125937 |
| 97125864 | 97125938 |
| 97125865 | 97125940 |
| 97125866 | 97125941 |
| 97125867 | 97125942 |
| 97125868 | 97125943 |
| 97125877 | 97125944 |
| 97125880 | 97125945 |
| 97125881 | 97125946 |
| 97125884 | 97125947 |
| 97125885 | 97125948 |
| 97125886 | 97125949 |
| 97125887 | 97125950 |
| 97125888 | 97125951 |
| 97125889 | 97125953 |
| 97125890 | 97125954 |
| 97125891 | 97125955 |
| 97125892 | 97125956 |
| 97125893 | 97125957 |
| 97125894 | 97125959 |
| 97125895 | 97125960 |
| 97125897 | 97125962 |
| 97125898 | 97125963 |
| 97125899 | 97125964 |
| 97125900 | 97125965 |
| 97125901 | 97125966 |
| 97125902 | 97125967 |
| 97125903 | 97125968 |
| | 31.20000 |
| | |

| 97125969 97125970 97125971 97125972 97125973 97125974 97125976 97125977 97125978 97125979 97125980 97125981 97125983 97125986 |
|--|
| 97125987 97125989 |
| 97125990 |
| 97125992 |
| 97125993 97125994 |
| 97125995 |
| 97125999 |
| 97126001 |
| 97126002 97126004 |
| 97126004 |
| 97126007 |
| 97126008 |
| 97126009 97126011 |
| 97126013 |
| 97126014 |
| 97126020 97126023 |
| 97126023 97126024 |
| 97126026 |
| 97126033 |
| 97126037 |
| 97126045 97126046 |
| 97126048 |
| 97126049 |
| 97126050 97126052 |
| 97126052 97126053 |
| 97126055 |
| 97126056 |
| 97126057 97126060 |
| 31 120000 |