

## SERVICE INFORMATION NO. SI D4-037

**NOTE:** SIs are used **only**:

- 1) To distribute information from DAI to our customers.
- 2) To distribute applicable information / documents from our suppliers to our customers with additional information.

Typically there is no revision service for SIs. Each new information or change of that will be send along with a new SI.

### I. TECHNICAL DETAILS

#### 1.1 Airplanes affected:

all DA 40 D

#### 1.2 Subject:

Engine

ATA-Code: 72-00

#### 1.3 Reason:

New TAE Operation & Maintenance Manual TAE 125-01 Doc. No. OM-02-01 Version 3/0.

#### 1.4 Approval:

The technical information contained in this document has been approved under the authority of EASA Design Organization Approval No. EASA.21J.052.



Diamond Aircraft Industries G.m.b.H.  
N.A. Otto-Straße 5  
A-2700 Wiener Neustadt

DAI SI D4-037

Page 2 of 2  
07-Jul-2005  
FT

### 1.5 Information:

This SI is issued to ensure that all Diamond Aircraft DA 40 D customers take notice of the new issue of the TAE Operation & Maintenance Manual issued on 04.05.2005 and the changes in Section 6.2 Maintenance actions based on operating hours.

The TAE Operation & Maintenance Manual TAE 125-01 Doc. No. OM-02-01 Version 3/0 is applicable with no restriction.

## II. OTHERS

In case of doubt contact Diamond Aircraft Industries or Thielert Aircraft Engines GmbH.