

SERVICE INFORMATION NO. SI D4-067

NOTE: SI's are used **only**:

- 1) To distribute information from DAI to our customers.
- 2) To distribute applicable information / documents from our suppliers to our customers with additional information.

Typically there is no revision service for SI's. Each new information or change of that will be sent along with a new SI.

I. TECHNICAL DETAILS

1.1 Airplanes affected:

DA 40 D see MSB D4-057

1.2 Subject:

MSB D4-057 Retrofit Breather Line
ATA-Code: 72-00

1.3 Reason:

On recommendation of Thielert Aircraft Engines GmbH (TAE) the Mandatory Service Bulletin MSB D4-057 could also be carried out without an engine change.

1.4 Information:

For detailed technical information confer MSB D4-057 which is applicable without any further additions.

Restriction: *Diamond Aircraft does not grant any credit as stated in MSB D4-057 section II.2 - Credit if the execution of the mentioned MSB is on behalf of TAE.*

II. OTHERS

The Mandatory Service Bulletin MSB D4-057 is attached to this SI.

In case of doubt contact Diamond Aircraft Industries GmbH.