

Diamond Aircraft Industries G.m.b.H N.A. Otto-Straße 5 A-2700 Wiener Neustadt Austria

Page 1 of 1 27-Oct-2008 FT

# **SERVICE INFORMATION No. SI D4-103/1**

## SUPERSEDES SERVICE INFORMATION No. SI D4-103

NOTE: SI's are used only:

1) To distribute information from DAI to our customers.

2) To distribute applicable information/documents from our suppliers to our customers with additional information.

Typically there is no revision service for SI's. Each new information or change of that will be sent along with a new SI.

# I. TECHNICAL DETAILS

### 1.1 Airplanes affected:

All DA 40 D airplanes equipped with Honeywell KAP 140 A/P System

### 1.2 Subject:

Honeywell Service Bulletin KAP 140-22-102 ATA-Code: 22-10

#### 1.3 Reason:

Honeywell has issued a Service Bulletin which addresses possible intermittent operation of the KAP 140 flight control system caused by a bad top cover of the KAP 140.

#### 1.4 Information:

For detailed information please contact your Honeywell Service Center.

## II. OTHERS

In case of doubt contact Honeywell International Inc.