

SERVICE INFORMATION No. SI D4-115

NOTE: SI's are used only:
1) To distribute information from DAI to our customers.
2) To distribute applicable information/documents from our suppliers to our customers with additional information.
Typically there is no revision service for SI's. Each new information or change of that will be sent along with a new SI.

I. TECHNICAL DETAILS

1.1 Airplanes affected:

All DA 40 D airplanes
equipped with Honeywell KAP 140 A/P System

1.2 Subject:

Honeywell Service Bulletin KS 270C-22-09
ATA-Code: 22-10

1.3 Reason:

Honeywell has issued a Service Bulletin which addresses the exchange of the tach generator which is installed in the KS 270C units. The new tach generator solves the intermittent problems (A/C and A/P oscillations) observed on the KAP 140 A/P system.

1.4 Information:

For detailed information please contact your Honeywell Service Center.

II. OTHERS

In case of doubt contact Honeywell International Inc.