
SERVICE INFORMATION LETTER NO. SID4-193

NOTE: Service Information Letters are used only:

1. To distribute information from Diamond Aircraft Industries Inc. to our customers.
2. To distribute applicable information/documents from our suppliers to our customers with additional information.

NOTE: Typically there is no revision service for Service Information Letter (SIL). Each new information or change will be sent along with a new SIL.

1. TECHNICAL DETAILS

1.1 Aircraft Affected

All DA 40 D aircraft equipped with fuel tank interconnect hoses from purchases indicated in MSB D4-107, latest revision.

1.2 Subject

TCCA Airworthiness Directive Number: CF-2019-39

ATA-Code: 28-10

1.3 Reason

Diamond Aircraft Industries have received reports of the deterioration of fuel tank connection hoses on DA 40 airplanes in the field. During investigation, it was found that the deteriorated fuel tank connection hoses (flexible couplings) originate from two isolated batches. The affected parts were sold as replacement parts from 13-Jul-2017 until 26-Feb-2019. All parts from these two isolated batches need to be replaced. Subsequently, TCCA has issued Airworthiness Directive Number CF-2019-39 mandating the replacement of the affected hoses.

1.4 Information

For detailed technical information refer to TCCA Airworthiness Directive Number CF-2019-39 and Diamond Aircraft Industries Service Bulletin No. MSB D4-107 latest revision, which is applicable without any further additions or restrictions.

TCCA Airworthiness Directive Number CF-2019-39 is attached to this Service Information Letter.

2. OTHER DETAILS

To obtain satisfactory results, procedures specified in this service information letter must be accomplished in accordance with accepted methods and current government regulations. Diamond Aircraft Industries Inc. cannot be responsible for the quality of work performed in accomplishing the requirements of this service information letter. Diamond Aircraft reserves the right to void continued warranty coverage in the area affected by this service information letter if it is not incorporated. If you no longer own the aircraft to which this service information letter applies, please forward it to the current owner and send the name of the current owner to Diamond Aircraft Industries Inc. at the address below.

Diamond Aircraft Industries Inc.
1560 Crumlin Sideroad, London, Ontario, Canada
N5V 1S2

Customer Support
Phone: (519) 457-4041, Fax: (519) 457-4045
Email: support-canada@diamondaircraft.com

Technical Publications
Email: techpubs@diamondair.com